



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATION | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

3035 / Ah Hui

QUOTATION

Customer :

CHINA TAIPING INSURANCE (S) PTE LTD

105 CECIL STREET

#18-00 / 19-00

THE OCTAGON

S'PORE 069534

ATTN: CHINA TAIPING INSURANCE (S) PTE LTD

NO. : 48157

Repair sum \$2900

DATE : 04/11/2024

CLAIM NO. : 12637

POLICY NO. : MC/01092334/01

FROM : STEPHANIE

VEHICLE NO. : FBS8933G

MAKE/MODEL : HON / ADV150 ABS CVT

(Page 1 of 3)

S/N	Description	Action	Qty	Unit Price	Amount
1	BALANCER HANDLE P/N: 78435 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$29.00	29.00
2	BAR HANDLE P/N: 78431 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$88.00	88.00
3	BEARING 6002 P/N: 59830 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$34.00	34.00
4	BOARD FOOTREST LH P/N: 77183 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$61.00	61.00
5	BOX AIR CLEANER P/N: 77182 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$35.00	35.00
6	BOX REAR ALUMINIUM 55LITRE (ZEDGE) P/N: 75144 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$372.00	372.00
7	BRACKET BOX REAR P/N: 72842 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$155.00	155.00
8	CLIP BUMPER SEAL P/N: 58571 - (REPORTED BY MECHANIC)	REPLACE	5.00	\$8.00	40.00
9	CLIP COVER P/N: 70181 - (REPORTED BY MECHANIC)	REPLACE	4.00	\$11.00	44.00



bizSAFE₃



S/N	Description	Action	Qty	Unit Price	Amount
10	COVER CRANKCASE OUTER P/N: 67046 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$287.00	287.00
11	COVER FRONT UPPER - (REPORTED BY MECHANIC)	REPLACE	1.00	\$59.00	59.00
12	COVER SIDE FRONT LH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$186.00	186.00
13	COVER SIDE LH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$140.00	140.00
14	COVER SIDE LOWER FRONT LH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$85.00	85.00
15	EMBLEM ABS - (REPORTED BY MECHANIC)	REPLACE	1.00	\$62.00	62.00
16	FOOTREST REAR LH P/N: 67027 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$54.00	54.00
17	GASKET COVER CRANKCASE LH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$19.00	19.00
18	LABOUR P/N: 06766 - LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS.	* Supply/Install	8.00	\$85.00	680.00
19	LAMP SIGNAL FRONT LH P/N: 72988 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$100.00	100.00
20	LEVER BRAKE LH P/N: 82182 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$43.00	43.00
21	MIRROR LH P/N: 82126 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$28.00	28.00
22	OBV TYPE B (12V) NEW P/N: 82490 - (REPORTED BY MECHANIC)	* REPLACE	1.00	\$341.00	341.00
23	RUBBER STAND STOPPER P/N: 70658 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$12.00	12.00
24	SPRAY PAINT COVER - (REPORTED BY MECHANIC)	* REPLACE	1.00	\$0.00 \$1,200.00	0.00 \$1,200.00



S/N	Description	Action	Qty	Unit Price	Amount
25	STAND MAIN P/N: 67040 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$89.00	89.00
26	STAND SIDE P/N: 77181 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$66.00	66.00
27	STICKER COWLING SIDE (L& R) - (REPORTED BY MECHANIC)	REPLACE	1.00	\$124.00	124.00
28	TRANSPORT CHARGES P/N: 07169 - BIKE TOWED BACK TO BHH	K	1.00	\$62.00	62.00
SUB TOTAL					\$3,295.00
GST @ 9 %					\$296.55
GRAND TOTAL (SGD)					\$3,591.55

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of
BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By



STEPHANIE

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



P-2146
102
1-1931-40
S.N-278
L-1075
3284-4
102
2955