

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG24110049/UQP3E2
Date: 30/12/2024REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1002655942
Claimant Vehicle No :	YQ3156D	Insured Vehicle No :	GBK117R
Date of Loss:	24/10/2024	Nature of Claim:	TP
		Claim No:	378774

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	YQ3156D	Engine No:	6M60268158
Make & Model:	MITSUBISHI FUSO, 7.5 D FK62FMZ1RDEC (M)	Chassis No:	FK62FMA40213
Reg. Date:	14/01/2021 (Man. Year: 2020)	Odometer:	201256 km
Colour:	Orange		
Engine Capacity:	7545 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	265/70 R19.5	Rear Tyre Size:	265/70 R19.5 (D)
Front Left Side:	Austone 6 mm	Rear Left Side:	Austone 6/6 mm
Front Right Side:	Austone 6 mm	Rear Right Side:	Austone 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,879.70	4,502.52	2,377.18	34.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,410.00	1,070.00	340.00	24.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,289.70	5,572.52	2,717.18	32.78
Approved Total (Overridden) (S\$)		4,400.00		
(S\$)	8,289.70	4,400.00	3,889.70	46.92
+ GST 9.00/9.00% (S\$)	746.07	396.00	350.07	46.92
Nett Amount (S\$)	9,035.77	4,796.00	4,239.77	46.92

INSPECTION

Date of Assignment:	04/11/2024	Liu's Brother Auto Engineering Workshop (HQ) BLK 1 KAKI BUKIT AVE 6, #01-01 AUTO BAY @ KAKI BUKIT Singapore 417883
Date Inspected:	04/11/2024 Inspected At:	
Estimated Period of Repair:	4.0 days	

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 30 Dec 2024)	
Parts:	N/A	mitsubishi fuso 7.5 d fk62fmz1rdec (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YQ3156D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT RH DOOR	Dented	3,246.80 F	*3,246.80 FL
2	1		*FRONT RH DOOR SIGNAL LAMP	Broken	249.60 F	*180.00 FL
3	1		*FRONT RH CORNER ANEL	Cracked	1,183.70 F	*1,021.11 FL
4	1		*FRONT RH HEAD LAMP COVER	Repair	497.40 F	*- FL
5	1		*FRONT RH STEP PANEL LOWER	Cracked	657.00 F	*550.25 FL
6	1		*FRONT RH WHEEL ARCH PANEL	Cracked	845.20 F	*845.20 FL
7	1		*FRONT RH CORPORATE ADVERTISEMENT & ARTWORK	Necessary	200.00 FS	*120.00 FS
					Sub Total (\$\$)	6,879.70 5,963.36
					- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00 1,460.84
					Total Parts (\$\$)	6,879.70 4,502.52

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION	New	60.00	20.00
2	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED AREAS	New	600.00	500.00
3	LABOR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN & REPLACING PARTS ETCS	New	700.00	550.00
4	TO APPLY RUST PROOFING, RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA	New	50.00	0.00
Gross Labour Cost (\$\$)			1,410.00	1,070.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >