

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/III24110054/RPA3Q2**Date:** 14/02/2025**REFERENCE**

Handling Insurer: India International Insurance Pte Ltd Policy No: D24MCV0003129
Claimant Vehicle No : SMM3302L **Insured Vehicle No :** GBE8950E
Date of Loss: 29/10/2024 Nature of Claim: TP Claim No: MCV2024D0012964

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMM3302L**
Make & Model: BMW 216I, 1.5 ACTIVE TOURER (A) Engine No: 39175663B38A15A
Reg. Date: 26/06/2019 (Man. Year: 2019) Chassis No: WBA2X920107D95464
Colour: Blue Odometer: 61869 km
Engine Capacity: 1499 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R17 Rear Tyre Size: 205/55 R17
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,879.15	3,017.80	7,861.35	72.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,822.00	5,098.00	3,724.00	42.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	19,701.15	8,115.80	11,585.35	58.81
+ GST 9.00/9.00% (S\$)	1,773.10	730.42	1,042.68	58.81
Nett Amount (S\$)	21,474.25	8,846.22	12,628.03	58.81
+ Loss of Use (5.0 x S\$60.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		2.18		
Nett Liability (S\$)		9,148.40		

INSPECTION

Date of Assignment: 25/11/2024
Date Inspected: 25/11/2024 Inspected At: Performance Motors Limited (HQ)
303 Alexandra Road, Singapore
Singapore 159941
Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Jan 2025)
Parts:	143	BMW 216I 1.5 ACTIVE TOURER (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMM3302L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	150.00 FS	*80.00 FS
2	1		*FRONT EMBOSS NUMBER PLATE	Bent	83.00 FS	*83.00 FS
3	1		*FRT CROSSLINK	Serviceable	182.80 FS	*- FS
4	1		*FRT LH TOP DEFORMATION ELEMENT	Serviceable	104.15 FS	*- FS
5	1		*FRT RH TOP DEFORMATION ELEMENT	Serviceable	104.15 FS	*- FS
6	1		*FRT BUMPER TOP CARRIER	Serviceable	420.15 FS	*- FS
7	1		*LH FINISHER	Serviceable	55.45 FS	*- FS
8	1		*RH FINISHER	Serviceable	55.45 FS	*- FS
9	1		*IMPACT ABSORBER TOP	Cracked	64.00 FS	*64.00 FS
10	1		*FRT BUMPER PANEL PRIMED (BASIS)	Deformed	987.80 FS	*987.80 FS
11	1		*LH GRID LATERAL (LINER/PDC)	Serviceable	102.35 FS	*- FS
12	1		*RH GRID LATERAL (LINER/PDC)	Serviceable	102.35 FS	*- FS
13	1		*RR BUMPER LH SIDE GUIDE	Serviceable	172.60 FS	*- FS
14	1		*RR BUMPER RH SIDE GUIDE	Serviceable	184.95 FS	*- FS
15	1		*REAR BUMPER CARRIER	Serviceable	525.75 FS	*- FS
16	1		*RR BUMPER LH INNER SIDE GUIDE	Serviceable	172.60 FS	*- FS
17	1		*RR BUMPER RH INNER SIDE GUIDE	Serviceable	172.60 FS	*- FS
18	1		*REAR BUMPER TRIM STRIP (BLACK)	Scratched	108.45 FS	*108.45 FS
19	1		*REAR BUMPER PANEL PRIMED (LINES PDC)	Deformed	1,132.45 FS	*1,132.45 FS
20	1		*FRT LH GRILLE	Serviceable	125.55 FS	*- FS
21	1		*FRT RH GRILLE	Serviceable	167.45 FS	*- FS
22	1		*FRONT PANEL V STRUT	Serviceable	135.90 FS	*- FS
23	1		*AIR DUCT	Cracked	562.10 FS	*562.10 FS
24	1		*LH HEADLIGHT LED TECHNOLOGY	Serviceable	2,503.55 FS	*- FS
25	1		*RH HEADLIGHT LED TECHNOLOGY	Serviceable	2,503.55 FS	*- FS
Total Parts (S\$)					10,879.15	3,017.80

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE FRONT BUMPER PANEL REAR BUMPER ,FRONT AIR DUCT ,TOP IMPACT ABSORBER ,REAR TRIM STRIP INCLUDE CARRYING OUT OTHER NECESSARY REPAIRS CAUSED BY THE ACCIDENT	New	4,250.00	2,550.00
2	TO CHECK ELECTRICAL WIRING SYSTEM AND LIGHTINGS AT THE FRONT AND REAR SECTION FOR PROPER FUNCTION	New	295.00	295.00
3	TO RESPRAY REAR BUMPER FRONT BUMPER AND TAILGATE	New	2,961.00	2,076.00
4	TO CHECK ELECTRICAL WIRING SYSTEM AND LIGHTING AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	0.00
5	TO REMOVE OLD PDC ASSEMBLY ,REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECK FOR PROPER FUNCTION	New	177.00	177.00
6	TO REPLACE LEFT HEADLIGHT	New	481.00	0.00
7	TO REPLACE RIGHT HEADLIGHT	New	481.00	0.00
Gross Labour Cost (\$\$)			8,822.00	5,098.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >