

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24110058/TUA3Q2
Date: 14/04/2025

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D24MPC0004685
Claimant Vehicle No :	SNH6928B	Insured Vehicle No :	SLP9154D
Date of Loss:	26/10/2024	Nature of Claim:	TP
		Claim No:	MPC2024D0012952

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNH6928B		
Make & Model:	HYUNDAI CN7 AVANTE 1.6, 1.6 DOHC CVT S/R (A)	Engine No:	G4FMNU511098
Reg. Date:	21/11/2022 (Man. Year: 2022)	Chassis No:	KMHLN41ETNU322492
Colour:	Grey	Odometer:	17603 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Kumho 6 mm	Rear Left Side:	Kumho 6 mm
Front Right Side:	Kumho 6 mm	Rear Right Side:	Kumho 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,870.40	1,331.20	5,539.20	80.62
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,580.00	1,480.00	2,100.00	58.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	10,450.40	2,811.20	7,639.20	73.10
+ GST 9.00/9.00% (S\$)	940.54	253.01	687.53	73.10
Nett Amount (S\$)	11,390.94	3,064.21	8,326.73	73.10
+ Loss of Use (3.0 x S\$65.00/day) (S\$)		195.00		
+ Doc/Search Fee (S\$)		2.18		
Nett Liability (S\$)		3,261.39		
Global Sum Settlement (S\$)		3,250.00		

INSPECTION

Date of Assignment:	30/10/2024		
Date Inspected:	30/10/2024	Inspected At:	Komoco Motors Pte Ltd (HQ) 253 ALEXANDRA ROAD, #01-01 Singapore 159936
Estimated Period of Repair:	3.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: NA MENG YAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Jan 2025)
Parts:	143	HYUNDAI CN7 AVANTE 1.6 1.6 DOHC CVT S/R (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNH6928B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	10		*BUMPER CLIP	Necessary	20.00 FL	*20.00 FL
2	1		*COVER RADIATOR GRILLE RR	Not Necessary	235.00 FL	*- FL
3	1		*COVER FR BUMPER	Deformed	605.00 FL	*605.00 FL
4	1		*GRILLE RADIATOR	Cut	897.00 FL	*897.00 FL
5	1		*MOULDING FRT BPR LICENSE PLATE	Cracked	22.00 FL	*22.00 FL
6	1		*LIP FRONT BUMPER	Not Necessary	53.00 FL	*- FL
7	1		*COVER RADIATOR GRILLE UPR	Not Necessary	125.00 FL	*- FL
8	1		*MOLDING ASSY BUMPER LWR	Not Necessary	122.00 FL	*- FL
9	1		*MOULDING FRONT BUMPER RH	Not Necessary	117.00 FL	*- FL
10	1		*MOULDING FRONT BUMPER LH	Not Necessary	117.00 FL	*- FL
11	1		*GRILLE FRONT BUMPER	Not Necessary	132.00 FL	*- FL
12	1		*EMBLEM -HYUNDAI	Necessary	45.00 FL	*45.00 FL
13	1		*CAP FRONT HOOK	Not Necessary	12.00 FL	*- FL
14	1		*BRACKET FR BUMPER SIDE RH	Not Necessary	28.00 FL	*- FL
15	1		*BRACKET FR BUMPER SIDE LH	Not Necessary	28.00 FL	*- FL
16	1		*PANEL ASSY HOOD	Not Necessary	2,288.00 FL	*- FL
17	1		*LAMP ASSY HEAD RH	Not Necessary	3,642.00 FL	*- FL
18	1		*SUNDRIES	Necessary	40.00 FS	*20.00 FS
19	1		*FRONT PLATE NUMBER	Bent	40.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	8,568.00	1,649.00
- List Item Discount on L Items 20.00/20.00% (S\$)	1,697.60	317.80
Total Parts (S\$)	6,870.40	1,331.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CARRY OUT ACCIDENT BODY REPAIR -FRT BUMPER /HOOD	New	1,380.00	460.00
2	COMPLETE PUTTY AND SPRAY PAINT ALL AFFECTED AREAS -FRT BUMPER /SKID FRT BUMPER /HOOD	New	1,520.00	380.00
3	TO REALIGN HEADLAMP	New	40.00	0.00
4	TO CALIBRATE RADAR SENSOR	New	460.00	460.00
5	TO REPROGRAMME AFTER THE ACCIDENT REPAIR	New	180.00	180.00
Gross Labour Cost (\$\$)			3,580.00	1,480.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >