



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2501320

16 RAFFLES QUAY
#42-01 HONG LEONG BUILDING
SINGAPORE 048581
ATTN:GARNET LOW

INV Date 07/03/2025
Reference CD/FCI24110059/Ema3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SNA 5941E
Insured Veh. SHA 9539D
Claim No. D24009515MFCT/CCPL/TPD 2
Policy No. D-24101860MFCT
Accident Date 27/10/2024
Inspection Date 30/10/2024

Description	Total
Survey Inspection	350.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Merimen Fee	12.00
Subtotal	362.00
GST (9%)	32.58
Grand Total	394.58

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS MS FIRST CAPITAL INSURANCE LTD		Ref:	CD/FCI24110059/Ema3q2	
16 RAFFLES QUAY		Date:	07/03/2025	
#42-01 HONG LEONG BUILDING		Code:	FCI2	
SINGAPORE 048581				
1. Policy Particulars :- DIRECT SETTLEMENT				
Insured Veh.	SHA 9539D	Veh. Inspected	SNA 5941E	
Policy No.	D-24101860MFCT	Coverage	0	
Claim No.	D24009515MFCT/CCPL/TPD 2	Excess	\$0.00	
Assign From	JOANNE YONG	Assign Date	30/10/2024	
2. Vehicle Details				
Make & Model	TOYOTA HARRIER 2.5 HYBRID (AUTO) (2WD) PREMIUM	C.C	2487	
Engine No.	A25A0906245	Year of Reg.	30/06/2021	
Chassis No.	JTEAD3BH20J000584	Colour	RED	
Odometer	35758 KM	Steering	IN ORDER	
Brakes	IN ORDER	General	GOOD	
Modification(s)	RIMS: SPORTS RIM			
3. Conditions of Tyres				
	Size	Make	Balance (mm)	
R/H Front Tyre	225/60 R18	BRIDGESTONE	6	
L/H Front Tyre	225/60 R18	BRIDGESTONE	6	
R/H Rear Tyre	225/60 R18	BRIDGESTONE	6	
L/H Rear Tyre	225/60 R18	BRIDGESTONE	6	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	27/10/2024	Inspection Date	30/10/2024	
Survey held at	BORNEO MOTORS (S) PTE LTD 17 UBI ROAD 4 SINGAPORE 408611			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.				
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SNA 5941E

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	SUNDRIES (SN)	NECESSARY	\$50.00	\$50.00
1	SEALANT (SN)	NECESSARY	\$300.00	\$200.00
1	PILLAR ,CTR BODY (SN)	NOT NECESSARY	\$476.00	\$0.00
1	STRIPE ,FR DOOR (SN)	NECESSARY	\$60.30	\$60.30
1	TAPE ,BLACK OUT (SN)	NECESSARY	\$15.30	\$15.30
1	STRIPE ,FR DOOR (SN)	NECESSARY	\$36.30	\$36.30
1	WEATHERSTRIP FR (SN)	NOT NECESSARY	\$299.10	\$0.00
1	PANEL SUB-ASSY FR (SN)	DENTED	\$2,716.50	\$2,716.50
1	PANEL SUB-ASSY RR (SN)	DENTED	\$2,536.40	\$2,536.40
1	STRIPE RR DOOR (SN)	NECESSARY	\$36.30	\$36.30
1	STRIPE ,RR DOOR (SN)	NECESSARY	\$42.20	\$42.20
1	TAPE,BLACK OUT RR (SN)	NECESSARY	\$30.40	\$30.40
1	HINGE ASSY FR DOOR (SN)	NOT NECESSARY	\$135.40	\$0.00
1	HINGE ASSY FR DOOR (SN)	NOT NECESSARY	\$153.00	\$0.00
1	HINGE ASSY FR DOOR (SN)	NOT NECESSARY	\$133.50	\$0.00
1	HINGE ASSY RR DOOR (SN)	NOT NECESSARY	\$137.10	\$0.00
1	MOULDING ASSY BODY (SN)	NOT NECESSARY	\$666.20	\$0.00
1	MOULDING SUB-ASSY (SN)	CUT	\$331.60	\$331.60
1	MOULDING SUB-ASSY (SN)	CUT	\$479.10	\$479.10
			\$8,634.70	\$6,534.40

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	CHECK WIRING AND CONDUCT LEAK TEST		\$198.00	\$198.00
	R/I INTERIOR TRIMMING TO FAC REPAIR	NOT NECESSARY	\$396.00	\$0.00
	TRANSFER BOTH FRT AND REAR DOOR MECHANISM		\$792.00	\$792.00
	TO RESET ECU AND REPROGRAMME		\$198.00	\$198.00
	REPL ACC AFF PARTS AND PANEL		\$3,960.00	\$1,584.00
	RESPRAY ACC AFF AREA		\$3,280.00	\$1,312.00
			\$8,824.00	\$4,084.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

GRAND TOTAL		\$17,458.70	\$10,618.40
	RECOMMENDED COST OF REPAIRS		\$10,618.40
Report Ref No: CD/FCI24110059/Ema3q2			

CTY

STEVE CHEN TSUE YEE

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



PHOTOGRAPHS FOR VEHICLE NO. : SNA 5941E




PHOTOGRAPHS FOR VEHICLE NO. : SNA 5941E






PHOTOGRAPHS FOR VEHICLE NO. : SNA 5941E



PHOTOGRAPHS FOR VEHICLE NO. : SNA 5941E




PHOTOGRAPHS FOR VEHICLE NO. : SNA 5941E



PHOTOGRAPHS FOR VEHICLE NO. : SNA 5941E



PHOTOGRAPHS FOR VEHICLE NO. : SNA 5941E



PHOTOGRAPHS FOR VEHICLE NO. : SNA 5941E





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 9 of 9)

PHOTOGRAPHS FOR VEHICLE NO. : SNA 5941E





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 1 of 1)

PHOTOGRAPHS FOR VEHICLE NO. : SNA 5941E

