



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

16 RAFFLES QUAY  
#42-01 HONG LEONG BUILDING  
SINGAPORE 048581  
ATTN:GARNET LOW

INV No. AC2501320

INV Date 07/03/2025

Reference CD/FCI24110059/Ema3q2

Code FCI2

### PROFESSIONAL SERVICE FEE

Vehicle No. SNA 5941E  
Insured Veh. SHA 9539D  
Claim No. D24009515MFCT/CCPL/TPD 2  
Policy No. D-24101860MFCT  
Accident Date 27/10/2024  
Inspection Date 30/10/2024

Description	Total
Survey Inspection	350.00
Resurvey Inspection	
Digital Photographs	
Transportation	
<b>Subtotal</b>	<b>350.00</b>
<b>GST (9%)</b>	<b>31.50</b>
<b>Grand Total</b>	<b>381.50</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

**LKM**



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.  
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDING SINGAPORE 048581	Ref: Date: Code:	CD/FCI24110059/Ema3q2 07/03/2025 FCI2	
1. Policy Particulars :- DIRECT SETTLEMENT			
Insured Veh.	SHA 9539D	Veh. Inspected	SNA 5941E
Policy No.	D-24101860MFCT	Coverage	0
Claim No.	D24009515MFCT/CCPL/TPD 2	Excess	\$0.00
Assign From	JOANNE YONG	Assign Date	30/10/2024
2. Vehicle Details			
Make & Model	TOYOTA HARRIER 2.5 HYBRID (AUTO) (2WD) PREMIUM	C.C	2487
Engine No.	A25A0906245	Year of Reg.	30/06/2021
Chassis No.	JTEAD3BH20J000584	Colour	RED
Odometer	35758 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		
3. Conditions of Tyres			
	Size	Make	Balance (mm)
R/H Front Tyre	225/60 R18	BRIDGESTONE	6
L/H Front Tyre	225/60 R18	BRIDGESTONE	6
R/H Rear Tyre	225/60 R18	BRIDGESTONE	6
L/H Rear Tyre	225/60 R18	BRIDGESTONE	6
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	27/10/2024	Inspection Date	30/10/2024
Survey held at	BORNEO MOTORS (S) PTE LTD 17 UBI ROAD 4 SINGAPORE 408611		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days			



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SNA 5941E

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	SUNDRIES (SN)	NECESSARY	\$50.00	\$50.00
1	SEALANT (SN)	NECESSARY	\$300.00	\$200.00
1	PILLAR ,CTR BODY (SN)	NOT NECESSARY	\$476.00	\$0.00
1	STRIPE ,FR DOOR (SN)	NECESSARY	\$60.30	\$60.30
1	TAPE ,BLACK OUT (SN)	NECESSARY	\$15.30	\$15.30
1	STRIPE ,FR DOOR (SN)	NECESSARY	\$36.30	\$36.30
1	WEATHERSTRIP FR (SN)	NOT NECESSARY	\$299.10	\$0.00
1	PANEL SUB-ASSY FR (SN)	DENTED	\$2,716.50	\$2,716.50
1	PANEL SUB-ASSY RR (SN)	DENTED	\$2,536.40	\$2,536.40
1	STRIPE RR DOOR (SN)	NECESSARY	\$36.30	\$36.30
1	STRIPE ,RR DOOR (SN)	NECESSARY	\$42.20	\$42.20
1	TAPE,BLACK OUT RR (SN)	NECESSARY	\$30.40	\$30.40
1	HINGE ASSY FR DOOR (SN)	NOT NECESSARY	\$135.40	\$0.00
1	HINGE ASSY FR DOOR (SN)	NOT NECESSARY	\$153.00	\$0.00
1	HINGE ASSY FR DOOR (SN)	NOT NECESSARY	\$133.50	\$0.00
1	HINGE ASSY RR DOOR (SN)	NOT NECESSARY	\$137.10	\$0.00
1	MOULDING ASSY BODY (SN)	NOT NECESSARY	\$666.20	\$0.00
1	MOULDING SUB-ASSY (SN)	CUT	\$331.60	\$331.60
1	MOULDING SUB-ASSY (SN)	CUT	\$479.10	\$479.10
			\$8,634.70	\$6,534.40

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	CHECK WIRING AND CONDUCT LEAK TEST		\$198.00	\$198.00
	R/I INTERIOR TRIMMING TO FAC REPAIR	NOT NECESSARY	\$396.00	\$0.00
	TRANSFER BOTH FRT AND REAR DOOR MECHANISM		\$792.00	\$792.00
	TO RESET ECU AND REPROGRAMME		\$198.00	\$198.00
	REPL ACC AFF PARTS AND PANEL		\$3,960.00	\$1,584.00
	RESPRAY ACC AFF AREA		\$3,280.00	\$1,312.00
			\$8,824.00	\$4,084.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

<b>GRAND TOTAL</b>	<b>\$17,458.70</b>	<b>\$10,618.40</b>
<b>RECOMMENDED COST OF REPAIRS</b>		<b>\$10,618.40</b>
<b>Report Ref No: CD/FCI24110059/Ema3q2</b>		

**CTY**

STEVE CHEN TSUE YEE

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of repositibility whatsoever, in contract or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.


**PHOTOGRAPHS FOR VEHICLE NO. : SNA 5941E**



**PHOTOGRAPHS FOR VEHICLE NO. : SNA 5941E**





**PHOTOGRAPHS FOR VEHICLE NO. : SNA 5941E**



**PHOTOGRAPHS FOR VEHICLE NO. : SNA 5941E**



**PHOTOGRAPHS FOR VEHICLE NO. : SNA 5941E**



**PHOTOGRAPHS FOR VEHICLE NO. : SNA 5941E**



**PHOTOGRAPHS FOR VEHICLE NO. : SNA 5941E**



**PHOTOGRAPHS FOR VEHICLE NO. : SNA 5941E**





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

**INSPECTION PHOTOS (Page 9 of 9)**

### PHOTOGRAPHS FOR VEHICLE NO. : SNA 5941E





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

REINSPECTION PHOTOS (Page 1 of 1)

### PHOTOGRAPHS FOR VEHICLE NO. : SNA 5941E

