

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24110060/TPA3Q2

Date: 03/03/2025

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D20MFL0002383_04

Claimant Vehicle No : SNL6750A Insured Vehicle No : GBA5368C

Date of Loss: 04/11/2024 Nature of Claim: TP Claim No: MFL2024D0013108

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SNL6750A

Make & Model: TOYOTA YARIS CROSS, 1.5 HYBRID ACTIVE (2WD) (A) Engine No: M15AY491610

Reg. Date: 27/07/2023 (Man. Year: 2022) Chassis No: JTDKBAB3601002586

Colour: White Odometer: 12478 km

Engine Capacity: 1490 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/65 R16 Rear Tyre Size: 205/65 R16

Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,271.00	5,415.20	1,855.80	25.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,715.82	5,277.82	2,438.00	31.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	14,986.82	10,693.02	4,293.80	28.65
+ GST 9.00/9.00% (S\$)	1,348.81	962.37	386.44	28.65
Nett Amount (S\$)	16,335.63	11,655.39	4,680.24	28.65
+ Car Rental (4.0 x S\$100.00/day + 9.00% GST) (S\$)		436.00		
+ Doc/Search Fee (S\$)		27.25		
Nett Liability (S\$)		12,118.64		

INSPECTION

Date of Assignment: 09/12/2024

Date Inspected: 09/12/2024 Inspected At: Borneo Motors (S) Pte Ltd (Pandan)
2 Pandan Crescent
Singapore 128462

Estimated Period of Repair: 5.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 09 Jan 2025)

Parts: M1-SUV TOYOTA YARIS CROSS 1.5 HYBRID ACTIVE (2WD) (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SNL6750A)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRY	Necessary	100.00 FS	*50.00 FS
2	1		*SEALANT	Necessary	100.00 FS	*100.00 FS
3	1		*COVER ,RR BUMPER	Not Necessary	444.00 FS	*- FS
4	1		*GUARD RR BUMPER	Cut	766.70 FS	*766.70 FS
5	1		*PANEL SUB -ASSY ,BACK	Bent	2,175.40 FS	*2,175.40 FS
6	1		*GLASS SUB-ASSY ,BACK	Necessary	1,644.20 FS	*1,644.20 FS
7	1		*DAM BACK WINDOW	Necessary	28.30 FS	*28.30 FS
8	2		*SIKA 182010 SIKA TACK GO! (BLA)	Necessary	216.00 FS	*216.00 FS
9	1		*SIKA 207 G+P ADHESIVE PRIMER	Necessary	200.00 FS	*200.00 FS
10	1		*PLATE BACK DOOR	Necessary	56.70 FS	*56.70 FS
11	1		*PLATE LUGGAGE COMPT	Necessary	56.70 FS	*56.70 FS
12	1		*PLATE LUGGAGE COMPT	Necessary	63.20 FS	*63.20 FS
13	4		*RETAINER ULTRASONIC	Not Necessary	220.80 FS	*- FS
14	2		*CLIP ULTRASONIC	Not Necessary	33.20 FS	*- FS
15	2		*SENSOR ULTRASONIC	Not Necessary	1,007.80 FS	*- FS
16	1		*ANTENNA ELECTRICAL	Not Necessary	100.00 FS	*- FS
17	10		*PIECE RR BUMPER	Necessary	58.00 FS	*58.00 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) **7,271.00** **5,415.20**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	DRILL HOLE AND INSTALL REVERSE SENSOR	New	198.00	0.00
2	CHECK WIRING SYSTEM	New	134.64	134.64
3	REMOVE AND TRANSFER TAILGATE COMPONENTS ONTO NEW TAILGATE R/I REAR REVERSE CAMERA TO FAC REPAIR	New	594.00	594.00
4	REPLACE REAR TAILGATE GLASS	New	594.00	594.00
5	SUPPLY SOLAR FILM	New	480.00	480.00
6	REMOVE INTERIOR UPHOLSTERY TO FAC REPAIR	New	792.00	0.00
7	TO RESET FCU AND REPROGRAMME	New	198.00	198.00
8	TO CONDUCT ADJUSTMENT ON BLIND SPOT SENSOR	New	198.00	198.00
9	REPLACE ACC DAMAGED PARTS	New	2,376.00	1,584.00
10	RESPRAY ACC AFFECTED AREAS	New	1,968.00	1,312.00
11	LABOUR FOR PLATINUM SHINE PRO & SHINE PER PANEL APPLICATION	New	183.18	183.18
Gross Labour Cost (\$\$)			7,715.82	5,277.82

Report was unsubmitted during this print-out.

< END OF ESTIMATES >