



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

INV No. AC2502903

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV Date 13/05/2025
Reference CD/LPC24110062/Kpa3q2
Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. GBF 4070R
Insured Veh. GBE 1107U
Claim No. 24/24/24/VC05/030093
Policy No. Z24VC05026420
Accident Date 24/10/2024
Inspection Date 09/12/2024

Description	Total
Third Party Express Settlement	450.00
Subtotal	450.00
GST (9%)	40.50
Grand Total	490.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CD/LPC24110062/Kpa3q2(N)	
			Date: 13/05/2025	
			Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBE 1107U	Veh. Inspected	GBF 4070R
	Policy No.	Z24VC05026420	Coverage (\$)	0.00
	Claim No.	24/24/24/VC05/030093	Excess (\$)	0.00
	Assign From	ENG HUEY NI	Assign Date	09/12/2024
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA DYNA (M)	c.c	2982
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	JTFAT35Y20K206895	Colour	SILVER
	Odometer	242938 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195 R15X8	GITI	8 mm
	L/H Front Tyre	195 R15X8	GITI	8 mm
	R/H Rear Tyre	155 R12X8 (D)	YOKOHAMA	3/3 mm
	L/H Rear Tyre	155 R12X8 (D)	YOKOHAMA	3/3 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	24/10/2024	Inspection Date	09/12/2024
	Survey held at	CHENG HOE MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBF 4070R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR TAILGATE	BENT	1,703.60	1,703.60
1	TAILGATE STICKER -TOYOTA	NECESSARY	330.10	330.10
1	TAILGATE LH SIDE LOCK HANDLE	BENT	160.50	160.50
1	TAILGATE STICKER DYNA	NECESSARY	39.10	39.10
1	TAILGATE LH HINGE	BENT	49.90	49.90
1	LH TAILLAMP	CRACKED	357.10	357.10
1	LH TAILLAMP PANEL	BENT	61.70	61.70
	LESS 25% DISCOUNT		-675.50	-675.50
			2,026.50	2,026.50
	<u>SPECIAL NETT ITEMS</u>			
1	STICKER 70KM/HR (SN)	NECESSARY	10.00	10.00
1	STICKER 13 PAX (SN)	NECESSARY	10.00	10.00
1	REAR LH CORNAL STOPPER (SN)	MISSING	18.00	18.00
1	TAILGATE INNER PROTECTOR (SN)	BENT	340.00	340.00
1	REAR CENTRE STEP TRAY (SN)	CRACKED	200.00	200.00
1	SET REVERSE SENSOR (SN)	DENTED	200.00	200.00
			778.00	778.00
	<u>LABOUR</u>			
	TO REMOVE & REFIX TAILGATE ,TAILLAMPS ,TO KNOCKING & REPAIR TAILGATE LOWER MEMBER ,LH SIDE GATE LOWER PANEL,CABIN REAR LH PILLAR ,REAR FLOORBOARD & REALIGN REAR TRUCK POSITION.		1,200.00	900.00
	PUTTY & RESPRAY ON TAILGATE LH SIDE GATE ,LH SIDE LOWER MEMBER ,TAILGATE LOWER MEMBER ,REAR TRUCK LH CORNAL PILLAR & CABIN REAR LH PILLAR & ALL AFFECTED AREAS .		1,100.00	800.00
	TO REWRITE ADVERTISEMENT .		200.00	100.00
			2,500.00	1,800.00
	GRAND TOTAL		5,304.50	4,604.50

Report Ref No. CD/LPC24110062/Kpa3q2(N)



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,650.00
---	--	--	-----------------

Report Ref No. CD/LPC24110062/Kpa3q2(N)

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

PHOTOGRAPHS FOR VEHICLE NO. : GBF 4070R



PHOTOGRAPHS FOR VEHICLE NO. : GBF 4070R



PHOTOGRAPHS FOR VEHICLE NO. : GBF 4070R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 4 of 5)

PHOTOGRAPHS FOR VEHICLE NO. : GBF 4070R



PHOTOGRAPHS FOR VEHICLE NO. : GBF 4070R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 1 of 1)

PHOTOGRAPHS FOR VEHICLE NO. : GBF 4070R

