

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24110067/RUA3Q2
Date: 03/03/2025

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D24MPCM001138
Claimant Vehicle No : GBL5477M **Insured Vehicle No :** SKR2450X
 Date of Loss: 28/10/2024 Nature of Claim: TP Claim No: MPC2024D0013102

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBL5477M**
 Make & Model: TOYOTA HIACE, 3.0 D TURBO 5DR MT (M) Engine No: 1KDB074111
 Reg. Date: 04/10/2021 (Man. Year: 2021) Chassis No: JTFHT02P800251862
 Colour: White Odometer: 92890 km
 Engine Capacity: 2982 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 215/70 R16 Rear Tyre Size: 215/70 R16
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
 Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,022.80	2,302.20	720.60	23.84
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,530.00	1,050.00	480.00	31.37
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,552.80	3,352.20	1,200.60	26.37
Approved Total (Overridden) (S\$)		2,650.00		
(S\$)	4,552.80	2,650.00	1,902.80	41.79
+ GST 9.00/9.00% (S\$)	409.75	238.50	171.25	41.79
Nett Amount (S\$)	4,962.55	2,888.50	2,074.05	41.79
+ Car Rental (6.0 x S\$100.00/day + 9.00% GST) (S\$)		654.00		
+ Doc/Search Fee (S\$)		33.18		
Nett Liability (S\$)		3,575.68		

INSPECTION

Date of Assignment: 06/11/2024
 Date Inspected: 06/11/2024 Inspected At: ETHOZ Protect Pte Ltd (Bukit Batok)
 30 Bukit Batok Crescent
 Singapore 658075
 Estimated Period of Repair: 4.0 days

Adjuster: MOHD RASUL

Manager: NA MENG YAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 23 Jan 2025)	
Parts:	N/A	TOYOTA HIACE 3.0 D TURBO 5DR MT (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBL5477M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	422.50 FL	*422.50 FL
2	10		*REAR BUMPER CLIPS	Necessary	50.00 FL	*50.00 FL
3	1		*TAILGATE	Bent	2,156.00 FL	*2,156.00 FL
4	1		*TAILGATE LOGO	Necessary	86.10 FL	*86.10 FL
5	1		*EMBLEM -TOYOTA HIACE	Necessary	75.00 FL	*75.00 FL
6	1		*TAILGATE LOCK	Not Necessary	289.60 FL	*- FL
7	1		*TAILGATE WEATHERSTRIPE	Not Necessary	311.20 FL	*- FL
8	1		*END PANEL (NPA)	Not Necessary	0.00 FL	*- FL
9	1		*REVERSE SENSOR	Not Necessary	200.00 FS	*- FS
10	1		*SEALANT	Necessary	50.00 FS	*30.00 FS
11	1		*ADVERTISEMENT STICKER	Necessary	200.00 FS	*150.00 FS
12	1		*70KM/H STICKER	Necessary	15.00 FS	*15.00 FS
13	1		*8 PAX STICKER	Necessary	15.00 FS	*15.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,870.40	2,999.60
- List Item Discount on L Items 25.00/25.00% (\$\$)	847.60	697.40
Total Parts (\$\$)	3,022.80	2,302.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO FACILITATE REPAIR	New	600.00	400.00
2	TO RESPRAY AFFECTED AREAS	New	700.00	500.00
3	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	New	30.00	0.00
4	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	150.00	120.00
5	RUST PROOFING	New	50.00	30.00
			Gross Labour Cost (\$\$)	1,530.00
				1,050.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >