



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO FBR 3508P

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT FORK ASSY	TO REPAIR SEE LABOUR	\$980.00	\$0.00
1	FRONT FORK UNDER BRACKET	NOT NECESSARY	\$398.00	\$0.00
1	FRONT FORK UPPER BRACKET	NOT NECESSARY	\$280.00	\$0.00
1	FRONT SPORT RIM	NOT NECESSARY	\$650.00	\$0.00
1	FRONT BRAKE DISC	NOT NECESSARY	\$220.00	\$0.00
1	FRONT RIM SHAFT	NOT NECESSARY	\$75.00	\$0.00
1	HEADLAMP (LED)	CRACKED	\$1,380.00	\$1,380.00
1	SIDE MIRROR	CUT	\$240.00	\$148.00
1	HANDLE-BAR	BENT	\$235.00	\$235.00
1	SET HANDLE-BAR BALANCER	CUT	\$150.00	\$60.00
1	SET HAND GRIP	NOT NECESSARY	\$70.00	\$0.00
1	BRAKE LEVERS - L/H	CUT	\$280.00	\$120.00
1	SET FRONT COWLING INNER PANEL	NOT NECESSARY	\$340.00	\$0.00
1	FRONT COVER	CUT	\$195.00	\$195.00
2	FOOTSTEP PANELS	N/S CUT	\$370.00	\$145.00
1	AIR FILTER COVER	CUT	\$260.00	\$180.00
1	BELT COVER	CUT	\$210.00	\$190.00
1	SET REAR FOOTREST	SERVICEABLE	\$185.00	\$0.00
1	MAIN STAND	TO REPAIR SEE LABOUR	\$168.00	\$0.00
1	SIDE STAND	TO REPAIR SEE LABOUR	\$108.00	\$0.00
1	SET FAIRING COVER	CRACKED/CUT	\$1,320.00	\$980.00
	LESS 10.00% DISCOUNT		(\$811.40)	(\$363.30)
			\$7,302.60	\$3,269.70

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	SET NUMBER PLATE (SN)	NOT NECESSARY	\$38.00	\$0.00
2	FORK OILS (SN)	NOT NECESSARY	\$50.00	\$0.00
2	FORK OIL SEALS (SN)	NOT NECESSARY	\$78.00	\$0.00
1	SET STEERING CONE (SN)	NOT NECESSARY	\$150.00	\$0.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	"X MAX" EMBLEM (SN)	NECESSARY	\$120.00	\$90.00
			\$436.00	\$90.00

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO CHECK WIRING AND RESET HEADLAMP FOCUSING	NOT NECESSARY	\$80.00	\$0.00
	TO PROVIDE LABOUR. INCLUSIVE OF THE REPAIR OF FRONT FORK ASSY, MAIN STAND AND SIDE STAND		\$620.00	\$400.00
	TO REPAIR BODY FRAME	NOT NECESSARY	\$580.00	\$0.00
			\$1,280.00	\$400.00

GRAND TOTAL			\$9,018.60	\$3,759.70
--------------------	--	--	-------------------	-------------------

	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			\$3,000.00
--	---	--	--	-------------------

Report Ref No: CS/INC24110068/Uvp3e2

TOTAL FOR SPARE PARTS: \$ 7,738.60 \$ 3,359.70
TOTAL FOR LABOUR : \$ 1,280.00 \$ 400.00
TOTAL REPAIR COST: \$ 9,018.60 \$ 3,759.70

CKS

MARCUS CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.