

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/AIG24110071/DUA3Q2**Date:** 07/05/2025**REFERENCE**

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800071499
Claimant Vehicle No : SHA7008H **Insured Vehicle No :** SMA7149A
 Date of Loss: 25/10/2024 Nature of Claim: TP Claim No: 1474592721SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHA7008H**
 Make & Model: HYUNDAI AE IONIQ HEV, 1.6 DCT (A) Engine No: G4LEKU296070
 Reg. Date: 26/06/2019 (Man. Year: 2019) Chassis No: KMHC851CVKU164385
 Colour: Blue Odometer: 745912 km
 Engine Capacity: 1580 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
 Front Left Side: West Lake 5 mm Rear Left Side: West Lake 5 mm
 Front Right Side: West Lake 5 mm Rear Right Side: West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,922.24	5,882.96	10,039.28	63.05
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,170.00	1,250.00	2,920.00	70.02
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,092.24	7,132.96	12,959.28	64.50
Approved Total (Overridden) (S\$)		5,700.00		
(S\$)	20,092.24	5,700.00	14,392.24	71.63
+ GST 9.00/9.00% (S\$)	1,808.30	513.00	1,295.30	71.63
Nett Amount (S\$)	21,900.54	6,213.00	15,687.54	71.63
+ Car Rental (8.0 x S\$117.72/day) (S\$)		941.76		
+ Loss of Earnings (8.0 x S\$50.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		27.25		
+ Other Costs (S\$)		80.00		
Nett Liability (S\$)		7,662.01		

INSPECTION

Date of Assignment: 29/10/2024
 Date Inspected: 29/10/2024 Inspected At: BIFROST AUTO PTE LTD - LOYANG (HQ)
 59 Loyang Drive Level 4 Room 7
 Singapore 508969
 Estimated Period of Repair: 6.0 days

Adjuster: BRYAN TANI**Manager:** NA MENG YAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER COVER	Dented / Cut	481.10 FL	*481.10 FL
2	1		*FRONT BUMPER TOP COVER	Not Necessary	476.30 FL	*- FL
3	1		*FRONT BUMPER SPONGE	Not Necessary	186.90 FL	*- FL
4	1		*FRONT BUMPER MOULDING CENTRE UPPER	Distorted	368.50 FL	*368.50 FL
5	1		*FRONT BUMPER MOULDING	Not Necessary	93.60 FL	*- FL
6	1		*FRONT BUMPER BRACKET TOP (LH)	Not Necessary	35.00 FL	*- FL
7	1		*FRONT BUMPER BRACKET (LH)	Broken	28.00 FL	*28.00 FL
8	1		*FRONT BUMPER RETAINER MOUNTING (LH)	Not Necessary	65.30 FL	*- FL
9	10		*FRONT BUMPER CLIPS	Necessary	25.00 FL	*25.00 FL
10	1		*FRONT BUMPER GRILLE (LH)	Not Necessary	186.90 FL	*- FL
11	1		*FRONT BUMPER AIR DUCT (LH)	Not Necessary	153.80 FL	*- FL
12	1		*DAY LIGHT LH	Mtg Broken	642.50 FL	*642.50 FL
13	1		*HEADLAMP SUPPORT PANEL ASSY	Broken	1,139.30 FL	*1,139.30 FL
14	1		*HEADLAMP (LH)	Broken	3,987.30 FL	*3,987.30 FL
15	1		*FRONT FENDER (LH)	Dented	490.70 FL	*490.70 FL
16	1		*FRONT FENDER APRON PANEL (LH)	Not Necessary	756.20 FL	*- FL
17	1		*FRONT FENDER APRON PANEL UPPER (LH)	Not Necessary	329.00 FL	*- FL
18	1		*FRONT FENDER SHIELD (LH)	Deformed	164.70 FL	*164.70 FL
19	1		*FRONT WHEEL RIM (LH)	Not Necessary	1,124.20 FL	*- FL
20	1		*FRONT WHEEL HUB ASSY (LH)	Not Necessary	678.50 FL	*- FL
21	1		*FRONT WHEEL HUB CAP	Not Necessary	346.40 FL	*- FL
22	1		*FRONT SHOCK ABSORBER (ASSY) (LH)	Not Necessary	372.50 FL	*- FL
23	1		*FRONT SHOCK ABSORBER MOUNTING (LH)	Not Necessary	372.50 FL	*- FL
24	1		*FRONT DRIVE SHAFT (LH)	Not Necessary	1,136.70 FL	*- FL
25	1		*RACK & PINION ASSY	Not Necessary	2,387.40 FL	*- FL
26	1		*STG TIE END	Not Necessary	94.70 FL	*- FL
27	1		*STABILIZER BAR	Not Necessary	326.80 FL	*- FL
28	1		*STABILIZER BAR LINK	Not Necessary	92.10 FL	*- FL
29	1		*FRONT SUSPENSION LOWER ARM (LH)	Not Necessary	596.80 FL	*- FL
30	1		*KNUCKLE ARM (LH)	Not Necessary	663.60 FL	*- FL
31	1		*ENGINE CROSSMEMBER	Not Necessary	1,803.90 FL	*- FL
32	1		*EMBLEM -BLUE DRIVE (LH)	Necessary	26.60 FL	*26.60 FL
33	1		*FRONT TYRE (LH)	Serviceable	216.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	19,848.80	7,353.70
- List Item Discount on L Items 20.00/20.00% (\$\$)	3,926.56	1,470.74
Total Parts (\$\$)	15,922.24	5,882.96

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,400.00	600.00
2	SPRAY PAINTING CHARGE	New	1,200.00	600.00
3	WIRING CHARGE	New	100.00	30.00
4	TUFF KOTE	New	100.00	20.00
5	TOWING CHARGE	New	80.00	0.00
6	FOUR WHEEL ALIGNMENT	New	120.00	0.00
7	REMOVE/REFIX UNDERCARRIAGE (FRT)	New	400.00	0.00
8	REMOVE/REFIX RADIATOR	New	90.00	0.00
9	REMOVE/REFIX AIRCON & REFILL GAS	New	130.00	0.00
10	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE	New	550.00	0.00
Gross Labour Cost (\$\$)			4,170.00	1,250.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >