

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/ICS24110072/EVP3M4**Date:** 15/11/2024**REFERENCE**

Handling Insurer: ECICS Limited Policy No: MPC23A00367800  
**Claimant Vehicle No :** GBA8218H **Insured Vehicle No :** SMH9299A  
Date of Loss: 21/10/2024 Nature of Claim: TP Claim No: DMPC2401418H/02/ST

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **GBA8218H**  
Make & Model: TOYOTA DYNA 150 MANUAL, 3.0 D (M) Engine No: 1KD1722484  
Reg. Date: 04/02/2008 (Man. Year: 2007) Chassis No: JTFAT35Y803001544  
Colour: Blue Odometer: 750274 km  
Engine Capacity: 2982 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 195R15C Rear Tyre Size: 195R15C  
Front Left Side: Bridgestone 5 mm Rear Left Side: Bridgestone 5 mm  
Front Right Side: Bridgestone 5 mm Rear Right Side: Bridgestone 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	5,995.60	2,182.42	3,813.18	63.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,140.00	1,460.00	680.00	31.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>8,135.60</b>	<b>3,642.42</b>	<b>4,493.18</b>	<b>55.23</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,900.00</b>		
<b>(S\$)</b>	8,135.60	2,900.00	5,235.60	64.35
<b>+ GST 9.00/9.00% (S\$)</b>	732.20	261.00	471.20	64.35
<b>Nett Amount (S\$)</b>	<b>8,867.80</b>	<b>3,161.00</b>	<b>5,706.80</b>	<b>64.35</b>

**INSPECTION**

Date of Assignment: 04/11/2024

Date Inspected: 06/11/2024 Inspected At:

DING AUTO PTE LTD (CARROS CENTRE)  
60 JALAN LAM HUAT, #06-46/47 CARROS  
CENTRE  
SINGAPORE 737869

Estimated Period of Repair: 5.0 days

**Adjuster:** CHEN TSUE YEE**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 15 Nov 2024)	
Parts:	N/A	TOYOTA DYNA 150 MANUAL 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBA8218H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILLAMP RHS	Broken	357.10 FL	*270.00 FL
2	1		*REAR TAILLAMP BRACKET RHS	Bent	61.70 FL	*61.70 FL
3	1		*REAR TAILLAMP LHS	Not Necessary	357.10 FL	*- FL
4	1		*REAR TAILLAMP BRACKET LHS	Not Necessary	61.70 FL	*- FL
5	1		*REAR END DOOR	Repair	1,703.60 FL	*- FL
6	1		*EXHAUST	Not Necessary	942.30 FL	*- FL
7	1		*REAR SPARE TYRE HOLDER	Not Necessary	340.80 FL	*- FL
8	1		*REAR BODY	Dented	2,540.30 FL	*1,482.00 FL
9	1		*REAR NUMBER PLATE WITH FRAME	Bent	100.00 FS	*100.00 FS
10	1		*JAE COMPANY STICKER	Necessary	400.00 FS	*300.00 FS
11	2		*REAR SPARE TYRE	Bent	500.00 FS	*200.00 FS
12	1		*REAR REVERSE SENSOR	Shorted	150.00 FS	*150.00 FS
13	1		*REAR LLICENSE PLATE LIGHT	Broken	96.20 FL	*96.20 FL
						F=Franchise part. S=SpcNett. L=ListItemDisc.
					Sub Total (\$\$)	7,610.80 2,659.90
					- List Item Discount on L Items 25.00/25.00% (\$\$)	1,615.20 477.48
					Total Parts (\$\$)	5,995.60 2,182.42

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	REPAIR, PANEL BEAT & SPRAY - REAR BODY, REAR PANEL, TAILGATE LATCH LHS, RHS	New	1,000.00	800.00
2	SPRAY PAINT - REAR PANEL, REAR BODY, TAILGATE LATCH LHS,RHS	New	1,000.00	600.00
3	RUST PROOFING	New	80.00	30.00
4	ALIGN TAILLAMP AND TEST WIRING	New	60.00	30.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,140.00</b>	<b>1,460.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >