



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SLR 230R

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT LICENSE PLATE (SN) (NPA)	NOT NECESSARY	\$0.00	\$0.00
1	SUNDRIES (SN)	NECESSARY	\$50.00	\$30.00
1	FRT LICENCE PLATE (SN)	DAMAGED	\$35.00	\$30.00
1	EMBLEM RAD GRILLE (SN)	CRACKED	\$43.70	\$43.70
1	HORN (SN)	SERVICEABLE	\$78.20	\$0.00
1	HOSE FLEXIBLE A/COND (SN)	NOT NECESSARY	\$94.40	\$0.00
1	HOSE-FLEXIBLE A/COND (SN)	NOT NECESSARY	\$215.00	\$0.00
1	A/COND HIGH PRESSURE PIPE (SN)	NOT NECESSARY	\$74.30	\$0.00
1	AIR GUIDE OIL COOLER OUTER (SN)	NOT NECESSARY	\$243.00	\$0.00
1	AIR GUIDE OIL COOLER INNER (SN)	NOT NECESSARY	\$242.50	\$0.00
1	OIL COOLER (SN)	NOT NECESSARY	\$261.50	\$0.00
1	HOSE UPPER RADITOR (SN)	NOT NECESSARY	\$129.10	\$0.00
1	HOSE-BOTTOM RADIATOR (SN)	NOT NECESSARY	\$41.20	\$0.00
1	RADIATOR OVERFLOW TANK (SN)	CRACKED	\$102.90	\$102.90
1	RADIATOR FAN MOTOR (SN)	CRACKED/JAMMED	\$678.60	\$678.60
1	A/COND AMBIENT SENSOR (SN)	NOT NECESSARY	\$81.90	\$0.00
1	RADIATOR COOLANT (SN)	NECESSARY	\$19.00	\$19.00
1	RADIATOR (SN)	BENT	\$585.20	\$585.20
1	A/COND CONDENSER (SN)	BENT	\$435.20	\$435.20
1	WIPER WASHER TANK (SN)	NOT NECESSARY	\$250.80	\$0.00
1	BONNET LOCK (SN)	TWISTED	\$113.80	\$113.80
1	BONNET RUBBER SEAL (SN)	NECESSARY	\$42.50	\$42.50
1	BONNET (SN)	BUCKLED	\$3,533.20	\$3,533.20
1	AIR GUIDE FRT LH (SN)	TORN	\$96.80	\$96.80
1	AIR GUIDE FRT RH (SN)	NOT NECESSARY	\$65.90	\$0.00
1	HOOD LOCK STAY (SN)	BENT	\$238.80	\$238.80
1	RADIATOR SUPPORT STAY LH (SN)	BENT	\$160.40	\$160.40
1	RADIATOR SUPPORT STAY RH (SN)	NOT NECESSARY	\$160.40	\$0.00
1	RADIATOR SUPPORT TOP LH (SN)	NOT NECESSARY	\$589.60	\$0.00



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	RADIATOR SUPPORT TOP RH (SN)	NOT NECESSARY	\$589.60	\$0.00
1	RADIATOR SUPPORT TOP CENTRE (SN)	DISTORTED	\$632.50	\$632.50
13	CLIP RAD GRILLE @ \$1.00 EACH (SN)	NECESSARY	\$13.00	\$13.00
1	RADIATOR SUPPORT TOP GARNISH (SN)	DISTORTED	\$329.60	\$329.60
1	RADIATOR GRILLE (SN)	BROKEN	\$383.90	\$383.90
1	HEADLAMP LH (SN)	BROKEN	\$970.90	\$970.90
1	HEADLAMP RH (SN)	CRACKED	\$970.90	\$970.90
1	FRT BUMPER TOW COVER (SN)	MISSING	\$13.50	\$13.50
1	FOG LAMP LH (SN)	NOT NECESSARY	\$232.30	\$0.00
1	FOG LAMP RH (SN)	NOT NECESSARY	\$232.30	\$0.00
1	FOG LAMP GARNISH LH (SN)	NOT NECESSARY	\$175.90	\$0.00
1	FOG LAMP GARNISH RH (SN)	NOT NECESSARY	\$175.90	\$0.00
1	FRT BUMPER CHASSIS STAY LH (SN)	NOT NECESSARY	\$475.41	\$0.00
1	FRT BUMPER CHASSIS STAY RH (SN)	NOT NECESSARY	\$384.80	\$0.00
1	FRT BUMPER LOWER COVER (SN)	NOT NECESSARY	\$83.30	\$0.00
1	FRT BUMPER REINFORCEMENT (SN)	TO REPAIR SEE LABOUR	\$2,475.60	\$0.00
1	ENERGY ABSORBER FRT BUMPER (SN)	TORN	\$296.00	\$296.00
1	FRT BUMPER SIDE BRKT LH (SN)	BENT	\$12.90	\$12.90
1	FRT BUMPER SIDE BRKT RH (SN)	BENT	\$12.90	\$12.90
20	CLIP FRT BUMPER @ \$1.00 EACH (SN)	NECESSARY	\$20.00	\$20.00
1	FASCIA KIT FRT (SN)	DISTORTED	\$976.90	\$976.90
1	FRONT BUMPER SPOILER (SN) (ADDITIONAL)	TORN	\$380.00	\$380.00
1	BONNET HINGE RH (SN) (ADDITIONAL)	BENT	\$83.20	\$83.20
1	BONNET HINGE LH (SN) (ADDITIONAL)	BENT	\$83.20	\$83.20
1	INTAKE MANIFOLD (SN) (ADDITIONAL)	CRACKED	\$778.50	\$778.50
1	BONNET INSULATOR (SN) (ADDITIONAL)	TORN	\$179.70	\$179.70
			\$19,625.61	\$12,247.70

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	LABOUR CHARGES TO REPAIR BOTH FRT FENDER, RENEW RADIATOR SUPPORT, BONNET AND FRONT BUMPER. INCLUSIVE OF THE REPAIR OF FRT BUMPER REINFORCEMENT		\$1,200.00	\$720.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

Labour			
Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
CHARGES TO SPRAY PAINTING SAME	FOC	\$1,200.00	\$1,080.00
RENEW HEADLAMP AND FOCUS		\$48.00	\$48.00
RENEW A/COND CONDENSER, VACUUM AND REFILL FREON GAS		\$120.00	\$120.00
APPLY SEALANT TO BONNET		\$100.00	\$100.00
TOWING CHARGES BY AUTOSWIFT W/O T212008		\$80.00	\$0.00
RENEW INTAKE MANIFOLD (ADDITIONAL)		\$234.00	\$234.00
		\$2,982.00	\$2,302.00
<b>GRAND TOTAL</b>		<b>\$22,607.61</b>	<b>\$14,549.70</b>
<b>RECOMMENDED COST OF REPAIRS</b>			<b>\$14,549.70</b>
Report Ref No: CS/SMO24060251/Uvp3			

### CKS

MARCUS CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of repositibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.