



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CS/FCI24110076/Kqp3e2
16 RAFFLES QUAY	Date:	13/11/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 258M	Veh. Inspected	SKZ 3196G
Policy No.	D-24101860MFCT	Coverage	0
Claim No.	D24009172MFCT	Excess	\$0.00
Assign From	JOANNE	Assign Date	04/11/2024

2. Vehicle Details

Make & Model	MAZDA 5 (A)	C.C	1998
Engine No.	PE10294026	Year of Reg.	18/01/2016
Chassis No.	JM6CW1071G0123115	Colour	METALLIC GREY
Odometer	157472 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: STANDARD ALLOY RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	205/55R16	FALKEN	7
L/H Front Tyre	205/55R16	FALKEN	7
R/H Rear Tyre	205/55R16	FALKEN	7
L/H Rear Tyre	205/55R16	FALKEN	7

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	15/10/2024	Inspection Date	05/11/2024
Survey held at	CHOON HOCK MOTOR TRADING CO - BLK 176 SIN MING DRIVE #05- 05 SIN MING AUTOCARE (S) 575721		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT.
B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days