

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile MS MSIG INSURANCE (S) PTE LTD Ref: CS3/MSG24110077/Rqp3e2 4 SHENTON WAY #21-01 Date: 14/11/2024 SGX CENTRE 2 SINGAPORE 068807 Code: MSG 1. **Policy Particulars :- PRE-REPAIR SURVEY** Insured Veh. PUBLIC LIABILITY Veh. Inspected SMT 2237L Policy No. Coverage 0 Claim No. 376870 **Excess** \$0.00 **Assign From ASHLEY LOOP** Assign Date 04/11/2024 2. **Vehicle Details** C.C Make & Model **HONDA FIT** Engine No. Year of Reg. Chassis No. Colour **RED** Odometer IN ORDER 49133 KM Steering **Brakes** IN ORDER **FAIR** General Modification(s) RIMS: SPORTS RIM **Conditions of Tyres** 3. Size Make Balance (mm) 175/70 R14 **FALKEN R/H Front Tyre** 6 L/H Front Tyre 175/70 R14 **FALKEN** 6 R/H Rear Tyre 175/70 R14 **FALKEN** 6 L/H Rear Tyre 175/70 R14 **FALKEN** 6 **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. 5. **General Information Accident Date** 17/09/2024 **Inspection Date** 08/11/2024 Survey held at JURONG EAST STREET 24 BLOCK 246 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000 5b. **Estimate Days of Repair**

MRB

MOHAMMED RASUL BIN MOHD YUNUS

ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days