

ASS. REC. BY:

REF: LPC 1Kenneth

ASSIGNMENT

From: _____

Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

EM

of _____

2741

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: \$84k

IDAC Accident Report: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: 03 days

Res.: Yes or No

Lum Sum: 20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: STN 1108Yr Regn: 04, 18Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: MerC180

c.c

1595Colour: White

A/C: _____

Insured / Std / NI / NA

Sp. Reading: 105529

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WDD 2050 402 R 381611Gen. Cohd: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModl: Nil / S/Rlm / STD A/Rlm or

Tyre Size: _____

F: _____

R: _____

245/35 ER19BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

Rear

R/Bal. 7 mmR/Bal. 7 mmL/Bal. 7 mmL/Bal. 7 mmD.O.A. 3/11/24D.O.I. 5/11/2024

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

O/S RM

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 GIA & En not ready

Date/Time, File Pass to?

☐

: Prell. Report

☐

: Final Report

1)

Date/Time, File Return to?

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐

: Site Insp (\$ _____)

) S - RS. SI

☐

: Interview (\$ _____)

) F. J. S.

☐

: Tech Invs (\$ _____)

) Others

☐

: Weekend (\$ _____)

)

Report Format :

ump Sum / I.B.I. (\$ _____)

TOTAL

EMI SOLUTION PTE LTD

160 Sin Ming Drive, (Sin Ming Autocity), #03-18/19, Singapore 575722
 H/P: 9004 2254 (Derek Keh) Tel: 6456 0226 Fax: 6458 4500
 Email: emautosolution@singnet.com.sg

Not Authorised
 L1 Pay &
 Resurvey After Paint
 3 days

Vehicle number: SJN110ZVehicle Make & Model: MERCEDES-BENZ C180

Qty	List Items	Amount \$
1	Front bumper	cm 2,101.79 ✓
1	Front bumper tow cover	cm 48.85 ✓
1	Front bumper lower grille - CTR	cm 190.55 ✓
1	Front bumper side grille - RH	cm 110.25 ✓
1	Front bumper corner garnish - RH	cm 181.23 ✓
1	Front bumper PDC sensor - RH	cm 281.33 X
1	Front bumper top seal	cm 89.95 X
1	Front bumper top guide support	cm 280.93 ✓
1	Front bumper side guides - L/R @ 45	cm 90.00 X
2	Front bumper sponge	cm 214.37 X
1	Front bumper reinforcement	cm 915.60 X
1	Front fender - RH	cm 1,068.87 X
2	Front fender inner shields - L/R @ 181.52	cm 363.04 X
1	Front headlamp - RH	mgcm 4,885.08 ✓
1	Front headlamp panel - RH	cm 195.50 X
1	Front headlamp lower bracket	cm 131.50 X
1	Front headlamp side garnish - RH	cm 89.62 X
1	Radiator grille assy	mgcm 1,660.51 ✓
1	Front undercover	cm 281.93 X
Sub-total		13,180.90
Less 10%		1,318.09
Total List		11,862.81

<u>Special Nett Items</u>	
1 set	Front bumper clip
1	Front bumper lower spoiler

cm 60.00 ✓
cm 1,800.00 ✓
Total Special Nett 1,860.00

<u>Labour charges</u>	
To check front electrical wiring	
To respray undercoating	
To respray painting and etc	
Panel beating, cut, weld remove & replacing above parts	

50.00 2ol
cm 60.00 X
800.00 25ol
800.00 25ol
Total Labour 1,710.00

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$ 15,432.81

Page 1 of 1

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: