

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS24060252/KVH3E2**Date:** 11/07/2024REFERENCE

Handling Insurer:	ECICS Limited	Policy No:	
Claimant Vehicle No :	SMY579L	Insured Vehicle No :	SNH4475D
Date of Loss:	23/06/2024	Nature of Claim:	TP
		Claim No:	DMPU2400025H/ST

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMY579L		
Make & Model:	TOYOTA PRIUS, 1.8 (A)	Engine No:	2ZR2G82898
Reg. Date:	10/02/2021 (Man. Year: 2020)	Chassis No:	JTDKB3FUX03091601
Colour:	Metallic Silver	Odometer:	235346 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Wanli 7 mm	Rear Left Side:	Wanli 8 mm
Front Right Side:	Wanli 7 mm	Rear Right Side:	Wanli 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,850.33	10,834.63	2,015.70	15.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,940.00	1,970.00	3,970.00	66.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	18,790.33	12,804.63	5,985.70	31.86
+ GST 9.00/9.00% (S\$)	1,691.13	1,152.42	538.71	31.86
Nett Amount (S\$)	20,481.46	13,957.05	6,524.41	31.86

INSPECTION

Date of Assignment:	25/06/2024	
Date Inspected:	26/06/2024	Inspected At: Trans-cab Auto Services (HQ) NO. 2 ANG MO KIO ST 63 Singapore 569111
Estimated Period of Repair:	6.0 days	

Adjuster: KENNETH KONG**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$644.65 NETT)

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Jul 2024)
Parts:	144	TOYOTA PRIUS 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMY579L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER, FRONT BUMPER	Torn	653.31 FL	*653.31 FL
2	1		*ABSORBER, FRONT BUMPER ENERGY	Cracked	100.91 FL	*100.91 FL
3	1		*REINFORCEMENT SUB-ASSY, FRONT BUMPER	Bent	902.16 FL	*902.16 FL
4	1		*SUPPORT, FRONT BUMPER SIDE, RH	Distorted	100.49 FL	*100.49 FL
5	1		*MOULDING, FRONT BUMPER SIDE, RH	Missing	120.86 FL	*120.86 FL
6	1		*COVER, FRONT BUMPER HOLE, RH	Missing	38.22 FL	*38.22 FL
7	1		*COVER SUB-ASSY, ENGINE UNDER, NO.2	Cracked	304.92 FL	*304.92 FL
8	1		*GRILLE SUB-ASSY, RADIATOR	Distorted	532.88 FL	*532.88 FL
9	1		*GRILLE, RADIATOR, LOWER NO.1	Cracked	224.70 FL	*224.70 FL
10	1		*SUPPORT, RADIATOR, UPPER RH	Buckled	99.33 FL	*99.33 FL
11	1		*SUPPORT SUB-ASSY, RADIATOR, UPPER	* Check	476.28 FL	*- FL
12	1		*SUPPORT SUB-ASSY, RADIATOR, RH	* Check	308.91 FL	*- FL
13	1		*CLEANER ASSY, AIR	Serviceable	1,448.06 FL	*- FL
14	1		*CONDENSER ASSY	Punctured	2,247.95 FL	*2,247.95 FL
15	1		*JAR ASSY, WINDSHIELD WASHER	Dented	276.15 FL	*276.15 FL
16	1		*GLASS, WINDSHIELD	Cracked	1,993.53 FL	*1,993.53 FL
17	1		*HOOD SUB-ASSY	Bent	1,243.20 FL	*1,243.20 FL
18	1		*HINGE ASSY, HOOD, LH	* Check	74.34 FL	*- FL
19	1		*HINGE ASSY, HOOD, RH	Distorted	74.34 FL	*74.34 FL
20	1		*COVER SUB-ASSY, FRONT PILLAR, UPR RH	Missing	126.74 FL	*126.74 FL
21	1		*FENDER SUB-ASSY, FRONT RH	Bent	1,236.69 FL	*1,236.69 FL
22	1		*LINER, FRONT FENDER, RH	Cracked	255.36 FL	*255.36 FL
23	1		*EMBLEM, SIDE PANEL, RH	Necessary	68.88 FL	*68.88 FL
24	1		*UNIT ASSY, HEADLAMP, RH	Cracked	3,325.56 FL	*3,325.56 FL
25	1		*FRT BUMPER CLIP	Necessary	65.00 FS	*60.00 FS
26	1		*FENDER LINER CLIP	Necessary	65.00 FS	*60.00 FS
27	2		*WINDSCREEN SEALANT	Necessary	150.00 FS	*40.00 FS
28	1		*WINDSCREEN MOULDING	Necessary	200.00 FS	*200.00 FS
29	1		*WINDSCREEN INNER SPONGE SEAL	Necessary	130.00 FS	*30.00 FS
30	1		*FRT BUMPER SIDE RETAINER CLIP	Not Necessary	65.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	16,908.77	14,316.18
- List Item Discount on L Items 25.00/25.00% (S\$)	4,058.44	3,481.55
Total Parts (S\$)	12,850.33	10,834.63

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	1,200.00	90.00
2	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,800.00	1,100.00
3	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR	New	380.00	0.00
4	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
5	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME	New	2,000.00	700.00
6	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	60.00
7	TO TRANSFER OF REAR FENDER PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
Gross Labour Cost (\$)			5,940.00	1,970.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >