

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTIndia International Insurance Pte Ltd
6 Raffles Quay, #22-00
Singapore 048580**Our File No:** CS/III24110084/UNP3E2**Date:** 13/11/2024REFERENCE

Insured/Claimant:	Kwek Siew Chuan Jason	Policy No:	D18MPC0003164
Date of Loss:	03/11/2024	Nature of Claim:	OD
		Claim No:	MPC2024D0012985

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLT4012S		
Make & Model:	TOYOTA WISH, 2.0 (A)	Engine No:	3ZRA437827
Reg. Date:	30/12/2009 (Man. Year: 2009)	Chassis No:	JTDGJ20W705001810
Colour:	Brown	Odometer:	259534 km
Engine Capacity:	1987 cc		
Market Value/New Car Price:	S\$50,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,138.82	7,154.15	4,984.67	41.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,410.00	2,750.00	1,660.00	37.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,548.82	9,904.15	6,644.67	40.15
Approved Total (Overridden) (S\$)		7,900.00		
- Excess (S\$)	750.00	750.00	0.00	0.00
Nett Amount (S\$)	15,798.82	7,150.00	8,648.82	54.74

INSPECTION

Date of Assignment: 05/11/2024

Date Inspected: 05/11/2024 Inspected At:

Hup Motor Trading & Service (HQ)
Blk 9004 Tampines Street 93, #01-120
Singapore 528838

Estimated Period of Repair: 6.0 days

Adjuster: MARCUS CHUA**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 Nov 2024)
Parts:	M1-MPV	TOYOTA WISH 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLT4012S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL GATE DOOR	Badly Dented	2,821.30 FL	*2,821.30 FL
2	1		*SET REAR WINDSCREEN GLASS SEAL	Necessary	199.80 FL	*199.80 FL
3	1		*REAR WINDSCREEN GLASS INNER DAMPER	Necessary	143.00 FL	*143.00 FL
4	1		*REAR WINDSCREEN GLASS SEALANT	Necessary	60.00 FN	*40.00 F
5	1		*TAIL GATE DOOR LOGO EMBLEM	Necessary	73.50 FL	*73.50 FL
6	1		*LICENCE LAMP CHROME MOULDING	Bent / Cracked	342.30 FL	*342.30 FL
7	1		*BRONEO MOTOR EMBLEM	Necessary	57.30 FL	*57.30 FL
8	1		*TAIL GATE DOOR O/S REFLECTOR	Cracked	315.70 FL	*315.70 FL
9	1		*TAIL GATE DOOR HANDLE COVER	Missing	31.90 FL	*31.90 FL
10	1		*TAIL GATE DOOR INNER LOCK	Damaged	571.50 FL	*571.50 FL
11	1		*TAIL GATE DOOR LOCK STRICKER	Not Necessary	56.70 FL	*- FL
12	1		*TAIL GATE DOOR WEATHERSTRIP	Twisted	463.00 FL	*463.00 FL
13	1		*TRIM BOARD COVER	Deformed / Torn	503.50 FL	*503.50 FL
14	16		*TRIM BOARD CLIPS	Not Necessary	60.80 FL	*- FL
15	1		*WIPER MOTOR	Serviceable	1,035.30 FL	*- FL
16	1		*TOP SPOILER SEALANT	Not Necessary	60.00 FL	*- FL
17	10		*TOP SPOILER CLIPS	Not Necessary	42.00 FL	*- FL
18	1		*TOP SPOILER DAMPER SEAL	Necessary	38.80 FL	*38.80 FL
19	1		*REAR BUMPER	Distorted	911.60 FL	*911.60 FL
20	10		*REAR BUMPER CLIPS	Necessary	60.00 FL	*60.00 FL
21	1		*REAR BUMPER O/S TOP RETAINER	Cracked	70.20 FL	*70.20 FL
22	1		*REAR BUMPER O/S SIDE RETAINER	Cracked / Bent	149.10 FL	*149.10 FL
23	1		*REAR BUMPER O/S STAY BRACKET	Dented	74.70 FL	*74.70 FL
24	1		*SET REAR BUMPER REVERSE SENSOR	Malfunction	268.80 FL	*268.80 FL
25	1		*REAR BUMPER O/S REFLECTOR	Serviceable	83.40 FL	*- FL
26	1		*REAR EXHAUST MUFFLER	Repair	1,823.40 FL	*- FL
27	2		*REAR EXHAUST MUFFLER MOUNTING	Not Necessary	136.40 FL	*- FL
28	1		*REAR END PANEL	Badly Dented	817.70 FL	*817.70 FL
29	1		*REAR END PANEL TOP GARNISH	Twisted	413.40 FL	*413.40 FL
30	6		*REAR END PANEL TOP GARNISH CLIPS	Necessary	36.00 FL	*36.00 FL
31	1		*REAR FLOOR BOARD COVER	Not Necessary	999.00 FL	*- FL
32	1		*SPARE TYRE CARRIER	Serviceable	455.40 FL	*- FL
33	1		*SPARE TYRE CARRIER LOCK NUT	Not Necessary	55.30 FL	*- FL
34	1		*REAR O/S FENDER	Repair	1,652.70 FL	*- FL
35	1		*REAR O/S FENDER INNER WHEEL GUARD	Not Necessary	92.50 FL	*- FL
36	1		*O/S TAIL LAMP ASSY	Cracked	461.80 FL	*461.80 FL
37	8		*REAR O/S FENDER INNER SHIELD CLIPS	Not Necessary	48.00 FL	*48.00 FL
38	1		*LUGGAGE ROOM BOX SEPARATOR	Cracked	559.30 FL	*559.30 FL
39	1		*BODY SEALANT	Not Necessary	60.00 FS	*- FS
40	1		*REAR NUMBER PLATE	Scratched	45.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

Sub Total (\$\$) 16,150.10 9,512.20

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
- List Item Discount on L Items 25.00/25.00% (S\$)					3,996.28	2,358.05
- Nett Item Discount on N Items 25.00/0.00% (S\$)					15.00	0.00
Total Parts (S\$)					12,138.82	7,154.15

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO WIRING CHECK UP & TRANSFER AFFECTED WIRING SYSTEM. CAMERA,	New	100.00	30.00
2	TO REMOVE & REFIX REAR WINDSCREEN GLASS & O/S QUARTER GLASS	New	250.00	120.00
3	TO REMOVE & REFIX TAIL GATE DOOR HINGE, SHOCK ABSORBER, INNER LOCK, WIPER MOTOR, ARM, TRIM BOARD COVER, HANDLE & NECESSARY PARTS INTO NEW DOOR	New	180.00	60.00
4	TO REMOVE & REFIT CARPET, FLOOR MAT, GARNISH, FLOOR BOARD COVER, SPARE TYRE, TOOL SET & NECESSARY PARTS	New	150.00	80.00
5	TO TRANSFER TAIL GATE DOOR TOP SPOILER & PUMP SEALANT	New	150.00	0.00
6	TO JACK, STRAIGHTEN REAR EXHAUST MUFFLER & TAIL PIPE	New	180.00	60.00
7	LABOUR CHARGE TO REMOVE & CUT OUT DAMAGED PARTS, TO JACK, STRAIGHTEN & KNOCKING OUT REAR O/S FENDER, REAR FLOOR BOARD PANEL & NECESSARY PARTS, TO WELD, RENEW & ALIGN ABOVE PARTS	New	1,800.00	1,200.00
8	TO PUTTY & RESPRAY PAINTING ON ALL AFFECTED ACCIDENT PARTS	New	1,600.00	1,200.00
Gross Labour Cost (S\$)			4,410.00	2,750.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >