



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555
ATTN: JASMINE LOK

INV No. AC2507399

INV Date 29/10/2025

Reference CD/LPC24110090/Ama3q2

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. GBE 9539D
Insured Veh. YP 5020D
Claim No. 24/24/24/VC05/030107
Policy No. Z24VC05021985
Accident Date 29/10/2024
Inspection Date 01/11/2024

Description	Total
Third Party Express Settlement	450.00
Subtotal	450.00
GST (9%)	40.50
Grand Total	490.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555 ATTN: JASMINE LOK			Ref: CD/LPC24110090/Ama3q2(N) Date: 29/10/2025 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	YP 5020D	Veh. Inspected	GBE 9539D
	Policy No.	Z24VC05021985	Coverage (\$)	0.00
	Claim No.	24/24/24/VC05/030107	Excess (\$)	0.00
	Assign From	GERALD POH	Assign Date	01/11/2024
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA HIACE	c.c	2982
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	KDH2015019966	Colour	SILVER
	Odometer	321324 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195 R15C	GREENLANDER	6 mm
	L/H Front Tyre	195 R15C	GREENLANDER	6 mm
	R/H Rear Tyre	195 R15C	GREENLANDER	6 mm
	L/H Rear Tyre	195 R15C	GREENLANDER	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	29/10/2024	Inspection Date	01/11/2024
	Survey held at	BIFROST AUTO PTE LTD 8 KAKI BUKIT AVENUE 4 #01-49 PREMIER @ KAKI BUKIT SINGAPORE 415875		
5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBE 9539D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	TAILGATE	DENTED	3,303.90	2,785.00
1	TAILGATE CENTRE EMBLEM	NECESSARY	89.40	89.40
1	TAILGATE RH DAMPER	NOT NECESSARY	419.40	-
1	TAILGATE LH DAMPER	NOT NECESSARY	419.40	-
1	TAILGATE RH HINGE	BENT	94.80	94.80
1	TAILGATE LH HINGE	BENT	94.80	94.80
1	TAILGATE LOCK	NOT NECESSARY	383.60	-
1	TAILGATE LOCK COVER	NOT NECESSARY	142.60	-
1	TAILGATE INNER TRIM BOARD	NOT NECESSARY	469.70	-
1	SET TAILGATE INNER TRIM BOARD CLIPS	NOT NECESSARY	70.00	-
1	TAILGATE RH RUBBER STOPPER	NOT NECESSARY	78.00	-
1	TAILGATE LH RUBBER STOPPER	NOT NECESSARY	78.00	-
	LESS 25% DISCOUNT		-1,410.90	-766.00
			4,232.70	2,298.00
	<u>SPECIAL NETT ITEMS</u>			
1	TAILGATE WINDSCREEN GLASS SEALANT (SN)	NECESSARY	80.00	40.00
1	TAILGATE WINDSCREEN GLASS INNER SEAL (SN)	NECESSARY	60.00	30.00
1	TAILGATE 70KM/H STICKER (SN)	NECESSARY	28.00	15.00
			168.00	85.00
	<u>LABOUR</u>			
	LABOUR CHARGES TO REMOVE ,CHECK ,REPLACE AND REINSTALL DAMAGES BODYPARTS .TO PANEL BEATING ,CUT/WELD AND REALIGN ALL AFFECTED PANELS AND AREAS .		800.00	250.00
	SPRAY PAINTING ON AFFECTED AREAS AND PANELS.		800.00	200.00
	CHECK WIRING AND LIGHTING SYSTEM ON AFFECTED AREAS .	NOT NECESSARY	60.00	-
	APPLY RUST COATING CHEMICAL ON AFFECTED AREAS AND PANELS.	NOT NECESSARY	50.00	-
	REMOVE AND REFIT TAILGATE WINDSCREEN GLASS TO ASSIST REPAIR .		250.00	120.00

Report Ref No. CD/LPC24110090/Ama3q2(N)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE AND REPLACE TAILGATE INNER MECHANISM TO NEW TAILGATE.		180.00	60.00
			2,140.00	630.00
GRAND TOTAL			6,540.70	3,013.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,400.00

Report Ref No. CD/LPC24110090/Ama3q2(N)

ADRIAN LING WAI PING


B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

PHOTOGRAPHS FOR VEHICLE NO. : GBE 9539D



PHOTOGRAPHS FOR VEHICLE NO. : GBE 9539D



PHOTOGRAPHS FOR VEHICLE NO. : GBE 9539D



PHOTOGRAPHS FOR VEHICLE NO. : GBE 9539D



PHOTOGRAPHS FOR VEHICLE NO. : GBE 9539D



PHOTOGRAPHS FOR VEHICLE NO. : GBE 9539D



PHOTOGRAPHS FOR VEHICLE NO. : GBE 9539D

