

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/AIG24110091/AMA3Q2**Date:** 12/12/2025REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100508328-07
Claimant Vehicle No : SND3673B **Insured Vehicle No :** SLN2963S
 Date of Loss: 29/10/2024 Nature of Claim: TP Claim No: 3490716673SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SND3673B**
 Make & Model: TOYOTA COROLLA ALTIS, 1.6 Elegance 2WD (A) Engine No: 1ZR0H51252
 Reg. Date: 24/12/2021 (Man. Year: 2021) Chassis No: MR2BE3BE600017219
 Colour: White Odometer: 32630 km
 Engine Capacity: 1598 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17 Rear Tyre Size: 225/45 R17
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
 Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,793.65	665.15	1,128.50	62.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,330.00	400.00	930.00	69.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,123.65	1,065.15	2,058.50	65.90
Approved Total (Overridden) (S\$)		850.00		
Nett Amount (S\$)	3,123.65	850.00	2,273.65	72.79
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 01/11/2024
 Date Inspected: 01/11/2024 Inspected At: Chia Auto Services Pte Ltd (HQ)
 23 Kaki Bukit Ave 4, #04-01 Vicom Inspection Center
 Singapore 415933
 Estimated Period of Repair: 2.0 days

Adjuster: ADRIAN LING**Manager:** Daphne Lee Mooi Ngiuk

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	860.20 FL	*860.20 FL
2	2		*REAR BUMPER SIDE RETAINER	Not Necessary	148.00 FL	*- FL
3	1		*REAR BUMPER REINFORCEMENT	*Check	20.00 FL	*- FL
4	2		*REAR BUMPER REFLECTOR	*Check	190.00 FL	*- FL
5	1		*END PANEL	Not Necessary	680.00 FL	*- FL
6	1		*END PANEL TOP GARNISH	Not Necessary	280.00 FL	*- FL
7	1		*SET REAR BUMPER CLIPS	Necessary	20.00 FS	*20.00 FS
8	1		*SET REAR END PANEL TOP GARNISH CLIPS	Not Necessary	20.00 FS	*- FS
9	1		*REAR END PANEL INSULATION SEALANT	Not Necessary	120.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	2,338.20	880.20
- List Item Discount on L Items 25.00/25.00% (\$\$)	544.55	215.05
Total Parts (\$\$)	1,793.65	665.15

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,REMOVAL AND REPLACING PARTS	New	400.00	200.00
2	TO SPRAY PAINT AFFECTED AREA	New	400.00	200.00
3	TUFF COAT	New	200.00	0.00
4	WIRING CHECK	New	80.00	0.00
5	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	New	250.00	0.00
Gross Labour Cost (\$\$)			1,330.00	400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >