

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/AIG24110092/AMA3Q2**Date:** 17/01/2025REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 7990000153
Claimant Vehicle No : GBK3983L **Insured Vehicle No :** SLR7488T
 Date of Loss: 26/10/2024 Nature of Claim: TP Claim No: 5246491353SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBK3983L**
 Make & Model: TOYOTA HIACE, 3.0 D Commuter (M) Engine No: 1KD1985807
 Reg. Date: 22/03/2010 (Man. Year: 2010) Chassis No: JTFJT02P400001312
 Colour: Grey Odometer: 378733 km
 Engine Capacity: 2982 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15C Rear Tyre Size: 195 R15C
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
 Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,836.27	5,377.20	6,459.07	54.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,680.00	1,560.00	3,120.00	66.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,516.27	6,937.20	9,579.07	58.00
Approved Total (Overridden) (S\$)		5,450.00		
(S\$)	16,516.27	5,450.00	11,066.27	67.00
+ GST 9.00/9.00% (S\$)	1,486.46	490.50	995.96	67.00
Nett Amount (S\$)	18,002.73	5,940.50	12,062.23	67.00
+ Car Rental (8.0 x S\$90.00/day) (S\$)		720.00		
+ Doc/Search Fee (S\$)		27.25		
Nett Liability (S\$)		6,687.75		
Global Sum Settlement (S\$)		6,680.00		

INSPECTION

Date of Assignment: 29/10/2024
 Date Inspected: 29/10/2024 Inspected At: JL Perfect Autowork Pte Ltd (HQ)
 8 Kaki Bukit Avenue 4, #08-09 Premier@Kaki Bukit
 Singapore 415875
 Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING**Manager:** Daphne Lee Mooi Ngiuk

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	2,210.70 FL	*2,098.00 FL
2	1		*TAILGATE OUTER MOULDING	Cracked	364.90 FL	*364.90 FL
3	1		*TAILGATE LOGO	Necessary	70.50 FL	*70.50 FL
4	2		*TAILGATE STOPPER	Not Necessary	48.20 FL	*- FL
5	2		*TAILGATE SIDE STOPPER	Not Necessary	57.20 FL	*- FL
6	1		*TAILGATE INNER BOARD	Torn	388.70 FL	*165.00 FL
7	1		*TAILGATE WEATHERSTRIP	Cut	397.80 FL	*397.80 FL
8	1		*TAILGATE WEATHERSTRIP PROTECTOR	Not Necessary	271.60 FL	*- FL
9	1		*TAILGATE INNER LOCK	Damaged	354.60 FL	*354.60 FL
10	1		*TAILGATE LOCK MOTOR	Not Necessary	545.00 FL	*- FL
11	1		*TAILGATE LOWER LOCK	Not Necessary	254.10 FL	*- FL
12	2		*TAIL LAMP	N/S Cracked / O/S Cut	710.40 FL	*710.40 FL
13	2		*TAILLAMP LOWER GARNISH	Cracked	514.80 FL	*514.80 FL
14	2		*TAILLAMP LOWER GARNISH RETAINER	Not Necessary	107.40 FL	*- FL
15	1		*REAR BUMPER	Deformed	497.00 FL	*497.00 FL
16	2		*REAR BUMPER SIDE RETAINER	Not Necessary	95.00 FL	*- FL
17	1		*REAR END PANEL (EXTEND)	Repair	428.10 FL	*- FL
18	1		*REAR END PANEL (INNER)	Dented	1,124.80 FL	*958.00 FL
19	1		*REAR END PANEL (OUTER)	Dented	498.60 FL	*498.60 FL
20	1		*REAR FLOOR PANEL	Repair	1,966.20 FL	*- FL
21	1		*REAR FLOOR PANEL MAT	Not Necessary	1,215.10 FL	*- FL
22	1		*REAR SPARE TYRE HOLDER BRACKET	Not Necessary	355.20 FL	*- FL
23	1		*REAR SPARE TYRE HOLDER BOLT	Not Necessary	65.80 FL	*- FL
24	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
25	1		*SET REAR BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
26	1		*SET TAIL LAMP CLIP	Not Necessary	30.00 FS	*- FS
27	1		*SET TAILLAMP LOWER GARNISH CLIP	Not Necessary	30.00 FS	*- FS
28	1		*SET TAILGATE CENTER MOULDING CLIP	Necessary	30.00 FS	*10.00 FS
29	1		*TAILGATE SEALANT	Not Necessary	150.00 FS	*- FS
30	1		*SET TAILGATE INNER TRIM CLIP	Necessary	50.00 FS	*20.00 FS
31	1		*TAILGATE STICKER 70KM/H	Necessary	30.00 FS	*15.00 FS
32	1		*TAILGATE WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
33	1		*TAILGATE WINDSCREEN INNER SEAL	Necessary	60.00 FS	*30.00 FS
34	1		*REAR END PANEL (OUTER) SEALANT	Necessary	150.00 FS	*60.00 FS
35	1		*REAR END PANEL (EXTEND) SEALANT	Not Necessary	150.00 FS	*- FS
36	1		*REAR FLOOR PANEL TOP BOARD (WOODEN) SPECAIL TYPE	Not Necessary	800.00 FS	*- FS
37	1		*REVERSE SENSOR	Damaged	220.00 FS	*200.00 FS
38	1		*REVERSE CAMERA	Not Necessary	550.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 14,971.70 7,034.60
- List Item Discount on L Items 25.00/25.00% (\$\$) 3,135.43 1,657.40

Total Parts (\$\$) 11,836.27 5,377.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING AND REPLACING PARTS	New	2,000.00	700.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,600.00	600.00
3	WIRING BULB CHECKING	New	80.00	30.00
4	TRANSFER TAILGATE MECHANISM	New	80.00	60.00
5	CONDUCT WATER LEAKAGE TEST	New	120.00	0.00
6	REMOVE AND REFIX FUEL TANK	New	100.00	0.00
7	REMOVE AND REFIX REAR FLOOR TOP BOARD (WOODEN)	New	500.00	0.00
8	REMOVE AND REFIX REAR REVERSE SENSOR AND DISTANCE SETTING	New	80.00	50.00
9	REMOVE AND REFIX REAR WINDSCREEN	New	120.00	120.00
Gross Labour Cost (\$\$)			4,680.00	1,560.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >