

JL Perfect Autowork Pte Ltd

Company Reg No: 202136905K

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778
E-mail:jlperfectautowork@gmail.com



DATE : 28.10.2024

TO : AIG MOTOR CLAIMS DEPTS
VEHICLE NO : GBK3983L
MODEL : TOYOTA HIACE
DATE OF ACCIDENT : 26.10.2024
TIME OF ACCIDENT : 15:00 HOURS

Daphne

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAILGATE <i>Dented</i>	1	\$ 2,210.70	\$ 2,210.70
2	TAILGATE OUTER MOULDING <i>crackd</i>	1	\$ 364.90	\$ 364.90
3	TAILGATE LOGO <i>new</i>	1	\$ 70.50	\$ 70.50
4	TAILGATE STOPPER <i>new</i>	2	\$ 24.10	\$ 48.20
5	TAILGATE SIDE STOPPER <i>new</i>	2	\$ 28.60	\$ 57.20
6	TAILGATE INNER BOARD <i>form</i>	1	\$ 388.70	\$ 388.70
7	TAILGATE WEATHERSTRIP <i>cut</i>	1	\$ 397.80	\$ 397.80
8	TAILGATE WEATHERSTRIP PROTECTOR <i>new</i>	1	\$ 271.60	\$ 271.60
9	TAILGATE INNER LOCK <i>new</i>	1	\$ 354.60	\$ 354.60
10	TAILGATE LOCK MOTOR <i>new</i>	1	\$ 545.00	\$ 545.00
11	TAILGATE LOWER LOCK <i>new</i>	1	\$ 254.10	\$ 254.10
12	TAIL LAMP <i>2H crackd, RH int</i>	2	\$ 355.20	\$ 710.40
13	TAILLAMP LOWER GARNISH <i>new crackd</i>	2	\$ 257.40	\$ 514.80
14	TAILLAMP LOWER GARNISH RETAINER <i>new</i>	2	\$ 53.70	\$ 107.40
15	REAR BUMPER <i>Dented</i>	1	\$ 497.00	\$ 497.00
16	REAR BUMPER SIDE RETAINER <i>new</i>	2	\$ 47.50	\$ 95.00
17	REAR END PANEL (EXTEND) <i>RHS</i>	1	\$ 428.10	\$ 428.10
18	REAR END PANEL (INNER) <i>Right dented</i>	1	\$ 1,124.80	\$ 1,124.80
19	REAR END PANEL (OUTER) <i>Dented</i>	1	\$ 498.60	\$ 498.60
20	REAR FLOOR PANEL <i>Right</i>	1	\$ 1,966.20	\$ 1,966.20
21	REAR FLOOR PANEL MAT <i>new</i>	1	\$ 1,215.10	\$ 1,215.10
22	REAR SPARE TYRE HOLDER BRACKET <i>new</i>	1	\$ 355.20	\$ 355.20

2088

165

\$58

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **GBK3983L**
 MODEL : **TOYOTA HIACE**
 DATE OF ACCIDENT : 26.10.2024
 TIME OF ACCIDENT : 15:00 HOURS

23	REAR SPARE TYRE HOLDER BOLT <i>new</i>	1	\$ 65.80	\$ 65.80	<i>+</i>
----	--	---	----------	----------	----------

6529.60
4972.20

TOTAL PRICE \$ 12,541.70
 LESS 25% \$ 3,135.43
SUB TOTAL PRICE \$ 9,406.28

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR NUMBER PLATE <i>new</i>	1	\$ 50.00	\$ 50.00	<i>+</i>
2	REAR BUMPER CLIP (SET) <i>m</i>	1	\$ 50.00	\$ 50.00	<i>30</i>
3	TAIL LAMP CLIP (SET) <i>new</i>	1	\$ 30.00	\$ 30.00	<i>+</i>
4	TAILLAMP LOWER GARNISH CLIP (SET) <i>new</i>	1	\$ 30.00	\$ 30.00	<i>+</i>
5	TAILGATE CENTER MOULDING CLIP (SET) <i>m</i>	1	\$ 30.00	\$ 30.00	<i>10</i>
6	TAILGATE SEALANT <i>new</i>	1	\$ 150.00	\$ 150.00	<i>+</i>
7	TAILGATE INNER TRIM CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	<i>20</i>
8	TAILGATE STICKER '70KM/H' <i>new</i>	1	\$ 30.00	\$ 30.00	<i>15</i>
9	TAILGATE WINDSCREEN SEALANT <i>312</i>	1	\$ 80.00	\$ 80.00	<i>40</i>
10	TAILGATE WINDSCREEN INNER SEAL	1	\$ 60.00	\$ 60.00	<i>30</i>
11	REAR END PANEL (OUTER) SEALANT <i>new</i>	1	\$ 150.00	\$ 150.00	<i>60</i>
12	REAR END PANEL (EXTEND) SEALANT <i>new</i>	1	\$ 150.00	\$ 150.00	<i>+</i>
13	REAR FLOOR PANEL TOP BOARD (WOODEN) SPECAIL TYPE <i>new</i>	1	\$ 800.00	\$ 800.00	<i>+</i>
14	REVERSE SENSOR <i>2nd</i>	1	\$ 220.00	\$ 220.00	<i>40</i>
15	REVERSE CAMERA <i>new</i>	1	\$ 550.00	\$ 550.00	<i>+</i>

405

TOTAL \$ 2,430.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING AND REPLACE PARTS	\$ 2,000.00	<i>700</i>
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,600.00	<i>600</i>
3	WIRNING, BULB CHECKING	\$ 80.00	<i>30</i>
4	TRANSFER TAILGATE MECHAISM	\$ 80.00	<i>60</i>
5	CONDUCT WATER LEAKAGE TEST	\$ 120.00	<i>X</i>

TO : AIG MOTOR CLAIMS DEPTS
 VEHICLE NO : GBK3983L
 MODEL : TOYOTA HIACE
 DATE OF ACCIDENT : 26.10.2024
 TIME OF ACCIDENT : 15:00 HOURS

6	REMOVE AND REFIX FUEL TANK	\$ 100.00	+
7	REMOVE AND REFIX REAR FLOOR TOP BOARD (WOODEN)	\$ 500.00	+
8	REMOVE AND REFIX REAR REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50
9	REMOVE AND REFIX REAR WINDSCREEN	\$ 120.00	✓

TOTAL \$ 4,680.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 11,836.28
 TOTAL LABOUR COST : \$ 4,680.00
 TOTAL REPAIR COST : \$ 16,516.28

Adm L
 2/3 29/10/24
 06 days

1440

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
 IRENE
 HP : 8297 9787

total: 6817.20
 4/5 5450.
 5450

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____