



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Tax Invoice

CHINA TAIPING INSURANCE (S) PTE LTD
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV No. : SAC2401457

INV Date : 20-11-2024

Reference CD/CTI24060253/Kpa3q2

Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SLL 1096L
Insured Veh. SLQ 8040A
Claim No. SNM24D203592
Policy No. DMPCSNW00010102400
Accident Date 21/06/2024
Inspection Date 24/06/2024

Description	Amount
Survey Inspection	280.00
Resurvey Inspection	0.00
Digital Photographs	0.00
Transportation	0.00
Sub-Total	280.00
GST (9%)	25.20
Grand Total	305.20

We shall be glad if you could forward the payment at your earliest convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS CHINA TAIPING INSURANCE (S) PTE LTD	Ref:	CD/CTI24060253/Kpa3q2
3 ANSON ROAD #16-00	Date:	20/11/2024
SPRINGLEAF TOWER SINGAPORE 079909	Code:	CTI

1. Policy Particulars :- DIRECT SETTLEMENT

Insured Veh.	SLQ 8040A	Veh. Inspected	SLL 1096L
Policy No.	DMPCSNW00010102400	Coverage	0
Claim No.	SNM24D203592	Excess	\$0.00
Assign From	JACQUELINE TAN	Assign Date	26/06/2024

2. Vehicle Details

Make & Model	TOYOTA WISH 2.0 AUTO	C.C	1987
Engine No.	3ZRA444887	Year of Reg.	12/01/2010
Chassis No.	JTDGJ20W605001913	Colour	METALLIC GREY
Odometer	234011 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	215/50 R17	PIRELLI	5
L/H Front Tyre	215/50 R17	PIRELLI	5
R/H Rear Tyre	215/50 R17	PIRELLI	4
L/H Rear Tyre	215/50 R17	PIRELLI	4

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	21/06/2024	Inspection Date	24/06/2024
Survey held at	ALAN'S UNITED AUTO PTE LTD BLK 7 SIN MING INDUSTRIAL ESTATE #01-76		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SLL 1096L

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	TAIL GATE	BENT	\$1,599.30	\$1,599.30
1	TAIL GATE LOGO	NECESSARY	\$57.70	\$57.70
1	TAIL GATE GLASS MOULDING	NECESSARY	\$155.80	\$155.80
1	TAIL GATE INNER LOCK	DENTED	\$446.30	\$446.30
1	REAR END PANEL INNER	BENT	\$119.90	\$119.90
1	REAR END PANEL OUTER	BROKEN	\$580.80	\$580.80
1	END PANEL TOP GARNISH	BUCKLED	\$322.70	\$322.70
1	REAR BUMPER FASCIA	BENT / CRACKED	\$639.70	\$639.70
2	REAR BUMPER SIDE RETAINER -L @\$105.50	DISTORTED	\$211.00	\$211.00
2	REAR BUMPER SIDE RETAINER-S @\$49.70	DISTORTED	\$99.40	\$99.40
2	REAR BUMPER BRACKET @\$58.30	TO REPAIR SEE LABOUR	\$116.60	\$0.00
2	REAR BUMPER REFLECTOR @\$65.00	SERVICEABLE	\$130.00	\$0.00
	LESS 25.00% DISCOUNT		(\$1,119.80)	(\$1,058.15)
			\$3,359.40	\$3,174.45

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	TAIL GATE RUBBER (50%) (SN)	DISTORTED/DENTED	\$272.70	\$181.80
1	SET REAR BUMPER REVERSE SENSOR (SN)	CUT	\$300.00	\$200.00
1	REAR W/S GLASS SEALANT (SN)	NECESSARY	\$60.00	\$40.00
1	REAR BUMPER CLIP (SN)	NECESSARY	\$30.00	\$30.00
1	REAR NO PLATE WITH BOX (SN)	DENTED	\$50.00	\$45.00
			\$712.70	\$496.80

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO REMOVE & REFIX REAR WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST		\$150.00	\$120.00
	TO REMOVE ROOF LINING FRONT AND REAR SEATS TRIM BOARD AND CARPET		\$150.00	\$60.00
	TO APPLY UNDERSEALING		\$60.00	\$60.00
	TO PUTTY AND SPRAY REPLACED PARTS		\$1,000.00	\$800.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO REMOVE CUT OUT DAMAGED PARTS, PANEL BEATING ,WELDING ALIGN REFIX AND TO RENEW ABOVE PARTS.INCLUSIVE OF THE REPAIR OF REAR BUMPER BRACKET.		\$900.00	\$800.00
			\$2,260.00	\$1,840.00
GRAND TOTAL			\$6,332.10	\$5,511.25
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			\$4,400.00
Report Ref No: CD/CTI24060253/Kpa3q2				

KSC

KENNETH KONG SENG CHEONG

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.


PHOTOGRAPHS FOR VEHICLE NO. : SLL 1096L



PHOTOGRAPHS FOR VEHICLE NO. : SLL 1096L



PHOTOGRAPHS FOR VEHICLE NO. : SLL 1096L



PHOTOGRAPHS FOR VEHICLE NO. : SLL 1096L



PHOTOGRAPHS FOR VEHICLE NO. : SLL 1096L





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 6 of 6)

PHOTOGRAPHS FOR VEHICLE NO. : SLL 1096L



PHOTOGRAPHS FOR VEHICLE NO. : SLL 1096L



PHOTOGRAPHS FOR VEHICLE NO. : SLL 1096L

