

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| DAMAGE ASSESSMENT REPORT | | | | | | |
|------------------------------------|---|---|----------------|------------|--------------------------|--|
| | INCOME INSURANCE LTD | | | Ref: | CS/INC24110095/Anp3e2(N) | |
| | 75 BRAS BASAH R INCOME CENTRES | | Date: | 05/02/2025 | | |
| | ATTN: RAJESWARY | | | Code: | INC | |
| 1. | Policy Particulars :- THIRD PARTY CLAIM | | | | | |
| | Insured Veh. | SMG 963E | Veh. Inspected | k | SNQ 8972L | |
| | Policy No. | | Coverage (\$) | | 0.00 | |
| | Claim No. | MT/1301513-005 | Excess (\$) | | 0.00 | |
| | Assign From | JULIET KOH | Assign Date | | 05/11/2024 | |
| 2. Vehicle Particulars & Condition | | | | | | |
| | Make & Model | AUDI A3 | c.c | | 1395 | |
| | Engine No. | HIDDEN | Year of Reg. | | 2015 | |
| | Chassis No. | WAUZZZ8V3G1032511 | Colour | | WHITE | |
| | Odometer | 109665 KM | Steering | | IN ORDER | |
| | Brakes | IN ORDER | Modification | | SPORTS RIM | |
| | General | GOOD | | | | |
| 3. Conditions of Tyres | | | | | | |
| | | Size | Make | | Balance | |
| | R/H Front Tyre | 205/55 R16 | MICHELIN | | 6 mm | |
| | L/H Front Tyre | 205/55 R16 | MICHELIN | | 6 mm | |
| | R/H Rear Tyre | 205/55 R16 | MICHELIN | | 6 mm | |
| | L/H Rear Tyre | 205/55 R16 | MICHELIN | | 6 mm | |
| 4. Description of Damages | | | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION AND O/S BODY. | | | | | |
| | DAMAGES SEE DETAILS. | | | | | |
| 5. General Information | | | | | | |
| | Accident Date | 25/10/2024 | Inspect Date / | Time | 06/11/2024 (03:58 PM) | |
| | Survey held at KT MOTORWERK | | | | | |
| | | 3012 BEDOK INDUSTRIAL PARK E, #01-2020, BEDOK INDUSTRIAL PARK E, SINGAPORE 489978 | | | | |
| 5a. | | | | | | |
| | | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | |
| 5b. | Estimate Days of Repair | | | | | |
| | ESTIMATED NORM | MAL PERIOD FOR REPAIR: | | 11 Work | ing Days | |