

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG24110099/DVP3M4**Date:** 12/02/2025REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1001909708		
Claimant Vehicle No :	SJV6269T	Insured Vehicle No :	SMH2556D		
Date of Loss:	04/11/2024	Nature of Claim:	TP	Claim No:	379109

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJV6269T	Engine No:	2NRX439911
Make & Model:	TOYOTA SIENTA, 1.5 ELEGANCE (A)	Chassis No:	MHFZ28H3000063084
Reg. Date:	03/04/2019 (Man. Year: 2019)	Odometer:	65729 km
Colour:	Brown		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/50R16	Rear Tyre Size:	195/50R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,347.79	2,303.23	3,044.56	56.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,930.00	1,540.00	1,390.00	47.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	8,277.79	3,843.23	4,434.56	53.57
+ GST 9.00/9.00% (S\$)	745.00	345.89	399.11	53.57
Nett Amount (S\$)	9,022.79	4,189.12	4,833.67	53.57

INSPECTION

Date of Assignment:	06/11/2024	ACCORD AUTO SERVICES PTE LTD (BUKIT MERAH)
Date Inspected:	05/11/2024 Inspected At:	BLK 1009 BUKIT MERAH LANE 3, #01-80 SINGAPORE 159723
Estimated Period of Repair:	5.0 days	

Adjuster: BRYAN TANI**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 Feb 2025)
Parts:	M1-MPV	TOYOTA SIENTA 1.5 ELEGANCE (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJV6269T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SET REAR TAILGATE GLASS MOULDING	Necessary	155.80 FL	*130.20 FL
2	1		*REAR TAILGATE	Bent	1,681.10 FL	*1,535.20 FL
3	1		*REAR TAILGATE LOGO	Necessary	65.00 FL	*65.00 FL
4	1		*REAR TAILGATE LOCK	Not Necessary	590.80 FL	*- FL
5	1		*REAR TAILGATE WEATHERSTRIP	Not Necessary	438.20 FL	*- FL
6	1		*REAR TAILGATE OPEN HANDLE SIENTA	Not Necessary	320.58 FL	*- FL
7	1		*REAR TAILGATE LAMP LH	Old Damaged	580.70 FL	*- FL
8	1		*REAR BUMPER	Cracked	480.58 FL	*480.58 FL
9	1		*REAR BUMPER CENTRE	Scratched	350.00 FL	*350.00 FL
10	2		*REAR BUMPER LH/RH SIDE GARNISH	Not Necessary	290.00 FL	*- FL
11	2		*REAR BUMPER REFLECTOR LH/RH	Not Necessary	140.96 FL	*- FL
12	2		*REAR BUMPER SIDE RETAINER	Not Necessary	170.00 FL	*- FL
13	1		*REAR END PANEL	Not Necessary	580.00 FL	*- FL
14	1		*REAR END PANEL TOP GARNISH	Deformed	110.00 FL	*110.00 FL
15	2		*NUMBER PLATE LIGHT	Not Necessary	210.00 FL	*- FL
16	1		*REAR NUMBER PLATE WITH FRAME	Not Necessary	50.00 FS	*- FS
17	1		*REAR TAILGATE GLASS SEALANT	Necessary	80.00 FS	*40.00 FS
18	1		*SET REAR TAIL GATE INNER TRIM BOARD CLIPS	Necessary	45.00 FS	*30.00 FS
19	1		*SET REAR FENDER SHIELD CLIPS	Not Necessary	45.00 FS	*- FS
20	1		*SET REAR BUMPER CLIPS	Necessary	45.00 FS	*30.00 FS
21	1		*SET REVERSE SENSOR	Not Working	280.00 FS	*200.00 FS
22	1		*REVERSE CAMERA	Not Necessary	180.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,888.72	2,970.98
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,540.93	667.75
Total Parts (\$\$)	5,347.79	2,303.23

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SPRAY PAINTING TO ALL AFFECTED AREAS	New	800.00	600.00
2	LABOUR REMOVE / REFIX ACCIDENT DAMAGES PARTS TO KNOCK, JACK , CUT WELD AND REALIGN ACCIDENT AFFECTED AREA	New	1,000.00	600.00
3	CHECK WIRING SYSTEM & LIGHT	New	100.00	0.00
4	ANTI RUST TREATMENT	New	120.00	40.00
5	TO CHECK & ADJUST WHEEL ALIGNMENT	New	100.00	0.00
6	TO REMOVE / REFIX TAILGATE COMPARTMENT, MECHANISM TO NEW TAILGATE	New	180.00	60.00
7	TO REMOVE / REFIX REAR TAILGATE GLASS TO NEW TAILGATE	New	150.00	120.00
8	TO REMOVE / REFIX REAR INNER COMPARTMENT TO FACILITIES REPAIR	New	180.00	0.00
9	TO REMOVE / REFIX REVERSE CAMERA	New	150.00	60.00
10	TO REMOVE/REFIX/REPLACE REVERSE SENSOR	New	150.00	60.00
Gross Labour Cost (\$\$)			2,930.00	1,540.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >