

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	MS FIRST CAPITA	L INSURANCE LTD	Ref:	CS/FCI24110103/Enp3m4(N)	
	16 RAFFLES QUA #42-01 HONG LEC 048581	Y DNG BUILDINGSINGAPORE	Date	e: 13/03/2025	
	ATTN: JASON TEA	4	Cod	e: FCI2	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SH 6177S	Veh. Inspected	PC 7763E	
	Policy No.	D-24101861MFCT	Coverage (\$)	0.00	
	Claim No.	D24008911MFCT	Excess (\$)	0.00	
	Assign From	JOANNE TAN	Assign Date	05/11/2024	
2. Vehicle Particulars & Condition					
	Make & Model	MITSUBISHI ROSA	c.c	2998	
	Engine No.	HIDDEN	Year of Reg.	2019	
	Chassis No.	BE641JK30572	Colour	WHITE	
	Odometer	221826 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
	General	FAIR			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	205/85R16	GITI	5 mm	
	L/H Front Tyre	205/85R16	GITI	5 mm	
	R/H Rear Tyre	205/85R16	GITI	5 mm	
	L/H Rear Tyre	205/85R16	GITI	5 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	07/10/2024	Inspection Date	11/11/2024	
	Survey held at	BIFROST AUTO PTE LTD			
		8 KAKI BUKIT AVENUE 4 #01-49 PREMIER @ KAKI BUKIT SINGAPORE 415875			
5a.	Remarks				
	A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				