

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/III24110104/UVP3M4**Date:** 29/11/2024**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D22MFL0003403_02
<b>Claimant Vehicle No :</b>	SKW5159S	<b>Insured Vehicle No :</b>	SNM172C
Date of Loss:	30/10/2024	Nature of Claim:	TP
		Claim No:	N/A

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SKW5159S</b>	Engine No:	FB16Y051474
Make & Model:	SUBARU XV, 1.6 I-S AWD CVT (A)	Chassis No:	JF1GP3KC5FG158468
Reg. Date:	29/10/2015 (Man. Year: 2015)	Odometer:	177321 km
Colour:	White		
Engine Capacity:	1600 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	215/55R17	Rear Tyre Size:	215/55R17
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	5,208.50	1,590.40	3,618.10	69.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,850.00	940.00	3,910.00	80.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>10,058.50</b>	<b>2,530.40</b>	<b>7,528.10</b>	<b>74.84</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,000.00</b>		
<b>Nett Amount (S\$)</b>	<b>10,058.50</b>	<b>2,000.00</b>	<b>8,058.50</b>	<b>80.12</b>

**INSPECTION**

Date of Assignment:	05/11/2024		
Date Inspected:	18/11/2024	Inspected At:	KAIZEN MOTORS PTE LTD 68 KAKI BUKIT AVE 6 #02-12 ARK@KB SINGAPORE 417896
Estimated Period of Repair:	3.0 days		

**Adjuster:** MARCUS CHUA**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 29 Nov 2024)
Parts:	144	SUBARU XV 1.6 I-S AWD CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKW5159S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAIL GATE	Not Necessary	1,567.00 F	*- FL
2	1		*REAR SUBARU EMBLEM	Not Necessary	106.00 F	*- FL
3	1		*REAR AWD EMBLEM	Not Necessary	106.00 F	*- FL
4	1		*REAR XV EMBLEM	Not Necessary	95.00 F	*- FL
5	1		*REAR BUMPER	Deformed/Torn	1,036.00 F	*660.00 FL
6	1		*REAR BUMPER GARNISH	Distorted	513.50 F	*513.50 FL
7	1		*REAR BUMPER TOW COVER	Missing	66.00 F	*38.00 FL
8	2		*REAR BUMPER FOG LAMP	Serviceable	546.00 F	*- FL
9	1		*REAR ANTENNA SENSOR	Cracked (1Pc Only)	218.00 F	*180.00 FL
		2PCS				
10	1		*REAR REINFORCEMENT BEAM	Bent	575.00 F	*309.00 FL
11	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
12	1		*SET REVERSE SENSOR	Malfunction	300.00 FS	*200.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					5,208.50	1,930.50
- List Item Discount on L Items 0.00/20.00% (\$\$)					0.00	340.10
Total Parts (\$\$)					5,208.50	1,590.40
Report was unsubmitted during this print-out.						

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR FOR CHECKING ON WIRING	New	250.00	20.00
2	LABOUR FOR DISMANTLING & REPLACING OF ACCIDENT DAMAGED PARTS, INCLUDING WELDING, KNOCKING, REPAIRING, STRAIGHTENING, RESHAPE & ADJUSTMENT OF REAR END ASSY & PARTS	New	2,500.00	400.00
3	SPRAYPAINTING & PUTTY OF REAR BUMPER, REAR BOOT REAR DIFFUSER, REINFORCEMENT BEAM, FENDER	New	1,200.00	520.00
4	LABOUR FOR RETROFITTING MOULDING & SEAL	New	550.00	0.00
5	LABOUR FOR RUST PROOFING	New	350.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>4,850.00</b>	<b>940.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >