

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CD/III24110111/AMA3Q2  
**Date:** 03/04/2025**REFERENCE**

Handling Insurer: India International Insurance Pte Ltd Policy No: D20MFL0000326\_04  
**Claimant Vehicle No :** SNK705B **Insured Vehicle No :** SNG6430A  
 Date of Loss: 31/10/2024 Nature of Claim: TP Claim No: MFL2024D0013212

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SNK705B**  
 Make & Model: HONDA VEZEL, 1.5 G CVT (A) Engine No: L15Z1007420  
 Reg. Date: 17/03/2023 (Man. Year: 2022) Chassis No: RV31006366  
 Colour: Black Odometer: 61020 km  
 Engine Capacity: 1496 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16  
 Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm  
 Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	6,277.04	2,800.48	3,476.56	55.39
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,450.00	1,200.00	1,250.00	51.02
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>8,727.04</b>	<b>4,000.48</b>	<b>4,726.56</b>	<b>54.16</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,200.00</b>		
<b>Nett Amount (S\$)</b>	<b>8,727.04</b>	<b>3,200.00</b>	<b>5,527.04</b>	<b>63.33</b>
<b>+ Car Rental (4.0 x S\$100.00/day) (S\$)</b>		400.00		
<b>+ Doc/Search Fee (S\$)</b>		27.25		
<b>Nett Liability (S\$)</b>		<b>3,627.25</b>		
<b>Global Sum Settlement (S\$)</b>		<b>3,600.00</b>		

**INSPECTION**

Date of Assignment: 06/11/2024  
 Date Inspected: 06/11/2024 Inspected At: AKA AUTO PTE LTD  
 25 Kaki Bukit Road 4, #05-36/37 Synergy @ KB  
 Singapore 417800  
 Estimated Period of Repair: 4.0 days

**Adjuster:** ADRIAN LING**Manager:** Daphne Lee Mooi Ngiuk*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

<b>Reference</b>	
<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 20 Mar 2025)
<b>Parts:</b> 144	HONDA VEZEL 1.5 G CVT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SNK705B)	
<b>Validity:</b> These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR	Repair	1,285.40 FL	*- FL
2	1		*FRONT DOOR LOCK	Not Necessary	341.40 FL	*- FL
3	1		*FRONT DOOR WEATHERSTRIPE	Not Necessary	189.40 FL	*- FL
4	1		*FRONT DOOR LOWER PROTECTOR	Cut	290.40 FL	*290.40 FL
5	1		*REAR DOOR	Dented	1,298.10 FL	*1,298.10 FL
6	1		*REAR DOOR LOCK	Not Necessary	360.40 FL	*- FL
7	1		*REAR DOOR WEATHERSTRIPE	Not Necessary	194.10 FL	*- FL
8	1		*REAR DOOR LOWER PROTECTOR	Cut	288.90 FL	*288.90 FL
9	1		*REAR DOOR ARC MOULDING	Cut	140.50 FL	*140.50 FL
10	1		*REAR FENDER ARC GARNISH	Cut	195.20 FL	*195.20 FL
11	1		*SET FRONT DOOR LOWER PROTECTOR CLIPS	Necessary	30.00 FS	*30.00 FS
12	1		*FRONT DOOR BLACK TAPE	Not Necessary	60.00 FS	*- FS
13	1		*FRONT DOOR VISOR	Not Necessary	100.00 FS	*- FS
14	1		*SET REAR DOOR LOWER PROTECTOR CLIPS	Necessary	30.00 FS	*30.00 FS
15	1		*SET REAR DOOR ARC MOULDING CLIPS	Necessary	20.00 FS	*20.00 FS
16	1		*REAR DOOR BLACK TAPE	Necessary	60.00 FS	*60.00 FS
17	1		*REAR DOOR VISOR	Necessary	100.00 FS	*60.00 FS
18	1		*ROCKER PANEL OUTER SKIRTING	Cracked	1,000.00 FS	*800.00 FS
19	1		*SET ROCKER PANEL OUTER SKIRTING CLIPS	Necessary	30.00 FS	*30.00 FS
20	1		*REAR WHEEL RIM	Not Necessary	880.00 FS	*- FS
21	1		*REAR TYRE	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>7,193.80</b>	<b>3,243.10</b>
<b>- List Item Discount on L Items 20.00/20.00% (S\$)</b>	916.76	442.62
<b>Total Parts (S\$)</b>	<b>6,277.04</b>	<b>2,800.48</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	1,000.00	500.00
2	SPRAY PAINTING	New	800.00	600.00
3	WIRING	New	50.00	0.00
4	TO PERFORM WHEEL ALIGNMENT	New	150.00	0.00
5	TO APPLY TUFF COAT	New	150.00	40.00
6	TO TRANSFER FRONT & REAR DOOR FITTINGS	New	300.00	60.00
			<b>Gross Labour Cost (\$)</b>	<b>1,200.00</b>
			<b>2,450.00</b>	<b>1,200.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >