



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SBT 3280J

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR BOOT LID	DENTED/BENT	\$762.90	\$762.90
1	REAR BOOT "H" LOGO	NECESSARY	\$58.80	\$58.80
1	REAR BOOT EMBLEM "I-VTEC"	NECESSARY	\$68.60	\$68.60
1	REAR BOOT EMBLEM "CIVIC"	NECESSARY	\$68.80	\$68.80
1	REAR BOOT EMBLEM "1.6"	NECESSARY	\$58.80	\$58.80
2	REAR BOOT LAMPS - L/R @ 211.60	NOT NECESSARY	\$423.20	\$0.00
1	REAR BOOT INNER LOCK	TWISTED	\$283.60	\$283.60
1	REAR BOOT INNER TRIM	NOT NECESSARY	\$260.90	\$0.00
1	REAR BOOT W/STRIP	TWISTED	\$181.60	\$181.60
2	REAR BOOT HINGES - L/R @ 141.20	NOT NECESSARY	\$282.40	\$0.00
1	REAR BUMPER	DISTORTED	\$710.60	\$710.60
4	REAR BUMPER PDC SENSORS @ 281.30	* CHECK	\$1,125.20	\$0.00
2	REAR BUMPER SIDE BRACKETS @ 65.50	BENT	\$131.00	\$131.00
2	REAR BUMPER SIDE RETAINERS - L/R @ 55.10	BENT	\$110.20	\$110.20
1	REAR END PANEL	DENTED	\$427.60	\$427.60
1	REAR END PANEL INNER TRIM	* CHECK	\$161.20	\$0.00
1	REAR FLOOR BOARD	WARPED/TORN	\$460.20	\$460.20
1	REAR FLOOR PANEL	TO REPAIR SEE LABOUR	\$911.40	\$0.00
1	REAR TAILLAMPS - L/R @ 481.60	CRACKED	\$963.20	\$963.20
2	REAR TAILLAMP PANELS - L/R @ 151.20	TO REPAIR SEE LABOUR	\$302.40	\$0.00
	<b>LESS 20.00% DISCOUNT</b>		(\$1,550.52)	(\$857.18)
			\$6,202.08	\$3,428.72

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	SET REAR BUMPER CLIP (SN)	NECESSARY	\$50.00	\$30.00
1	SET REAR BOOT INNER TRIM CLIP (SN)	NOT NECESSARY	\$50.00	\$0.00
1	REAR REVERSE CAMERA (SN)	SERVICEABLE	\$450.00	\$0.00
			\$550.00	\$30.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

Labour			
Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
TO CHECK REAR ELECTRICAL WIRING		\$50.00	\$20.00
TO REMOVE, REFIX REAR INTERIOR TRIMS TO ASSIST REPAIR		\$80.00	\$60.00
TO RESPRAY UNDERCOATING		\$100.00	\$50.00
TO RESPRAY PAINTING & ETC		\$1,200.00	\$900.00
PANEL BEATING, CUT, WELD, REMOVE & REPLACING ABOVE PARTS. INCLUSIVE OF THE REPAIR OF REAR FLOOR PANEL AND REAR TAILLAMP PANELS - L/R		\$1,200.00	\$600.00
		\$2,630.00	\$1,630.00
<b>GRAND TOTAL</b>		<b>\$9,382.08</b>	<b>\$5,088.72</b>
<b>RECOMMENDED COST OF REPAIRS (EXCLUDE CHECK ITEMS S\$1,029.12 NETT)</b>			<b>\$5,088.72</b>
Report Ref No: CS/INC24110113/Uvh3m4			

TOTAL FOR SPARE PARTS: \$ 6,752.08 \$ 3,458.72  
TOTAL FOR LABOUR : \$ 2,630.00 \$ 1,630.00  
TOTAL REPAIR COST: \$ 9,382.08 \$ 5,088.72

## CKS

MARCUS CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of repositibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.