

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24110116/UPA3Q2
Date: 05/02/2025

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D24MFL000681
Claimant Vehicle No : SKZ3780U Insured Vehicle No : SLZ9349G
Date of Loss: 03/11/2024 Nature of Claim: TP Claim No: MFL2024D0013502

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKZ3780U
Make & Model: MITSUBISHI ASX 2.0 6-CVT, 2.0 ABS D/AIRBAG SR 2WD (M) Engine No: 4B11QT6375
Reg. Date: 21/01/2016 (Man. Year: 2015) Chassis No: JMFXTGA2WFC09058
Colour: Grey Odometer: 219879 km
Engine Capacity: 1998 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55Z R18 Rear Tyre Size: 225/55Z R18
Front Left Side: LAUFENN 6 mm Rear Left Side: LAUFENN 6 mm
Front Right Side: LAUFENN 6 mm Rear Right Side: LAUFENN 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,748.50	6,216.40	12,532.10	66.84
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,140.00	3,040.00	1,100.00	26.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	22,888.50	9,256.40	13,632.10	59.56
Approved Total (Overridden) (S\$)		7,400.00		
Nett Amount (S\$)	22,888.50	7,400.00	15,488.50	67.67
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 07/11/2024
Date Inspected: 07/11/2024 Inspected At: Progressive Car Care Pte Ltd (HQ)
Singapore 408716
Estimated Period of Repair: 10.0 days

Adjuster: MARCUS CHUA Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Feb 2025)
Parts:	M1-SUV	MITSUBISHI ASX 2.0 6-CVT 2.0 ABS D/AIRBAG SR 2WD (M) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKZ3780U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Dented	952.00 FL	*952.00 FL
2	10		*FRONT BUMPER CLIPS	Necessary	49.00 FL	*49.00 FL
3	1		*FRONT BUMPER TOP GRILLE	Scratched	280.00 FL	*280.00 FL
4	1		*FRONT BUMPER TOP GRILLE LOGO	Necessary	49.00 FL	*49.00 FL
5	1		*FRONT BUMPER LOWER GRILLE	Twisted	322.00 FL	*322.00 FL
6	1		*FRONT GRILLE SURROUND CHROME	Cracked	815.00 FL	*815.00 FL
7	1		*FRONT BUMPER FOAM	*Check	22.00 FL	*- FL
8	1		*FRONT BUMPER REINFORCEMENT (BIG)	*Check	493.00 FL	*- FL
9	1		*FRONT BUMPER BEAM (SMALL)	*Check	73.00 FL	*- FL
10	2		*FRONT BUMPER FOGLAMP LH/RH	Not Necessary	870.00 FL	*- FL
11	2		*FRONT BUMPER FOGLAMP COVER LH/RH	Not Necessary	110.00 FL	*- FL
12	2		*FRONT BUMPER DAY LAMP LH/RH	Not Necessary	1,420.00 FL	*- FL
13	2		*HEADLAMP UNIT LH/RH	*Check	2,030.00 FL	*- FL
14	2		*HEADLAMP TOP PANEL LH/RH	Repair	174.00 FL	*- FL
15	1		*SUPPORT PANEL -TOP	Bent	508.00 FL	*508.00 FL
16	1		*SUPPORT PANEL -LOWER	Repair	348.00 FL	*- FL
17	1		*SUPPORT PANEL TOP GARNISH	Twisted	138.00 FL	*138.00 FL
18	1		*A/C CONDENSER	*Check	1,087.00 FL	*- FL
19	2		*A/C CONDENSER SIDE AIR GUIDE -LH/RH	*Check	158.00 FL	*- FL
20	1		*A/C CONDENSER TOP AIR GUIDE	*Check	123.00 FL	*- FL
21	1		*A/C FAN BLADE	*Check	73.00 FL	*- FL
22	1		*A/C FAN MOTOR	*Check	479.00 FL	*- FL
23	1		*BONNET	Bent / Buckled	942.00 FL	*942.00 FL
24	2		*BONNET HINGE LH/RH	Repair	176.00 FL	*- FL
25	1		*BONNET LOCK	Twisted	116.00 FL	*116.00 FL
26	2		*BONNET SIDE RUBBER -LH/RH	Not Necessary	56.00 FL	*- FL
27	1		*BONNET INSULATOR	Not Necessary	149.00 FL	*- FL
28	10		*BONNET INSULATOR CLIPS	Not Necessary	49.00 FL	*- FL
29	1		*AIRDUCT	*Check	276.00 FL	*- FL
30	2		*HORN LH/RH	*Check	320.00 FL	*- FL
31	1		*REAR BUMPER	Distorted	878.00 FL	*878.00 FL
32	2		*REAR BUMPER SIDE RETAINER LH/RH	Bent	76.00 FL	*76.00 FL
33	10		*REAR BUMPER CLIPS	Necessary	49.00 FL	*49.00 FL
34	1		*REAR BUMPER TOW COVER	Not Necessary	26.00 FL	*- FL
35	1		*REAR BUMPER CENTER COVER	Not Necessary	55.00 FL	*- FL
36	2		*REAR BUMPER REFLECTOR LH/RH	Not Necessary	76.00 FL	*- FL
37	1		*REAR BUMPER REINFORCEMENT	*Check	348.00 FL	*- FL
38	1		*REAR END PANEL	*Check	363.00 FL	*- FL
39	1		*REAR END PANEL TOP GARNISH	*Check	160.00 FL	*- FL
40	1		*TAILGATE	Dented	1,089.00 FL	*1,089.00 FL
41	2		*TAILGATE HINGE LH/RH	Not Necessary	140.00 FL	*- FL
42	1		*TAILGATE GLASS MOULDING	Necessary	73.00 FL	*73.00 FL
43	1		*TAILGATE ASX WORDINGS	Necessary	65.00 FL	*65.00 FL
44	1		*TAILGATE MIVEC WORDINGS	Necessary	87.00 FL	*87.00 FL
45	1		*TAILGATE MITSUBISHI LOGO	Necessary	58.00 FL	*58.00 FL
46	2		*TAILGATE LAMP LH/RH	Not Necessary	1,276.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*TAILGATE TOP LOCK	*Check	464.00 FL	*- FL
48	1		*TAILGATE LOWER LOCK STRIKER	Not Necessary	28.00 FL	*- FL
49	1		*TAILGATE WEATHERSTRIP	*Check	220.00 FL	*- FL
50	1		*REAR SPARE TYRE TOP BOARD	Not Necessary	261.00 FL	*- FL
51	1		*REAR BUMPER SENSOR	Malfunction	200.00 FS	*200.00 FS
52	2		*SEALANT	Necessary	40.00 FS	*40.00 FS
53	1		*SPONGE TAPE	Necessary	20.00 FS	*20.00 FS
54	1		*FRONT NUMBER PLATE	Bent	35.00 FS	*35.00 FS
55	1		*REAR NUMBER PLATE	Bent	35.00 FS	*30.00 FS
56	1		*A/C FAN COWLING	*Check	275.00 FL	*- FL
57	1		*RADIATOR	*Check	1,189.00 FL	*- FL
58	1		*RADIATOR FAN BLADE	*Check	73.00 FL	*- FL
59	1		*RADIATOR FAN MOTOR	*Check	479.00 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	20,795.00	6,871.00
- List Item Discount on L Items 10.00/10.00% (S\$)	2,046.50	654.60
Total Parts (S\$)	18,748.50	6,216.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCK OUT DENTS ON FENDERS CUT /WELD FRONT SUPPORT PANEL ,REAR END PANEL,REMOVE ,REPLACE ACCIDENT PORTIONS	New	1,800.00	1,200.00
2	TO RESPRAY PAINT ON ACCIDENT PORTIONS	New	1,600.00	1,500.00
3	TO CHECK WIRING	New	50.00	20.00
4	TO REMOVE ,REFIT GARNISH TO FACILITATE REPAIR	New	150.00	60.00
5	TO REMOVE ,REPLACE REAR BUMPER SENSOR	New	80.00	30.00
6	ANTI RUST	New	90.00	60.00
7	TO TRANSFER TAILGATE FITTINGS	New	100.00	50.00
8	TO REMOVE ,REFIT REAR GLASS	New	150.00	120.00
9	TO REMOVE,REPLACE A/C CONDENSER & REFILL GAS (*CHECK)	New	120.00	0.00
Gross Labour Cost (\$\$)			4,140.00	3,040.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >