

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS24110117/EQP3E2
Date: 27/12/2024REFERENCE

Handling Insurer:	ECICS Limited	Policy No:	
Claimant Vehicle No :	SLX4337J	Insured Vehicle No :	SFY9779A
Date of Loss:	24/07/2024	Nature of Claim:	TP
		Claim No:	DMPC2400952H/ST

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLX4337J		
Make & Model:	SUBARU FORESTER, 2.0 I-L CVT AWD SR (A)	Engine No:	FB20YC91693
Reg. Date:	28/03/2018 (Man. Year: 2018)	Chassis No:	JF1SJ5KC5JG105732
Colour:	Grey	Odometer:	103107 km
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/60 R17	Rear Tyre Size:	225/60 R17
Front Left Side:	Yokohama 5 mm	Rear Left Side:	Yokohama 5 mm
Front Right Side:	Yokohama 5 mm	Rear Right Side:	Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,855.44	5,430.88	10,424.56	65.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,980.00	1,260.00	3,720.00	74.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,835.44	6,690.88	14,144.56	67.89
Approved Total (Overridden) (S\$)		5,350.00		
(S\$)	20,835.44	5,350.00	15,485.44	74.32
+ GST 9.00/9.00% (S\$)	1,875.19	481.50	1,393.69	74.32
Nett Amount (S\$)	22,710.63	5,831.50	16,879.13	74.32

INSPECTION

Date of Assignment:	05/11/2024	
Date Inspected:	07/11/2024	Inspected At: MCR Motors Pte Ltd (HQ) 8 Kaki Bukit Ave 4 #01-53, Premier @ Kaki Bukit Singapore 415875
Estimated Period of Repair:	5.0 days	

Adjuster: CHEN TSUE YEE**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Dec 2024)
Parts:	M1-SUV	SUBARU FORESTER 2.0 I-L CVT AWD SR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLX4337J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Broken	610.50 FL	*610.50 FL
2	1		*FRONT BUMPER TOW COVER	Not Necessary	10.20 FL	*- FL
3	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	105.00 FL	*- FL
4	1		*FRONT BUMPER SIDE RETAINER RH	Not Necessary	42.00 FL	*- FL
5	1		*FRONT BUMPER SIDE RETAINER LH	Broken	42.00 FL	*42.00 FL
6	1		*FRONT BUMPER BRACKET RH	Not Necessary	16.00 FL	*- FL
7	1		*FRONT BUMPER BRACKET LH	Not Necessary	16.00 FL	*- FL
8	1		*FRONT BUMPER FOG LAMP GARNISH RH	Not Necessary	48.80 FL	*- FL
9	1		*FRONT BUMPER FOG LAMP GARNISH LH	Not Necessary	48.80 FL	*- FL
10	1		*FRONT BUMPER FOG LAMP SIDE GARNISH RH	Not Necessary	23.00 FL	*- FL
11	1		*FRONT BUMPER FOG LAMP SIDE GARNISH LH	Not Necessary	23.00 FL	*- FL
12	1		*FRONT BUMPER FOG LAMP RH	Not Necessary	282.00 FL	*- FL
13	1		*FRONT BUMPER FOG LAMP LH	Not Necessary	282.00 FL	*- FL
14	1		*FRONT BUMPER NOZZLE COVER RH	Not Necessary	65.50 FL	*- FL
15	1		*FRONT BUMPER NOZZLE COVER LH	Not Necessary	65.50 FL	*- FL
16	1		*FRONT BUMPER NOZZLE WASHER RH	Not Necessary	94.10 FL	*- FL
17	1		*FRONT BUMPER NOZZLE WASHER LH	Not Necessary	94.10 FL	*- FL
18	1		*FRONT BUMPER SPONGE	Not Necessary	142.40 FL	*- FL
19	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	325.60 FL	*- FL
20	1		*FRONT GRILLE ASSEMBLY UPPER	Cut	170.60 FL	*170.60 FL
21	1		*FRONT GRILLE ASSEMBLY LOWER CHROME MOULDING	Not Necessary	185.60 FL	*- FL
22	1		*FRONT GRILLE ASSEMBLY	Broken	357.50 FL	*357.50 FL
23	1		*FRONT GRILLE UPPER BRACKET	Not Necessary	21.60 FL	*- FL
24	1		*FRONT GRILLE LOWER BRACKET	Not Necessary	32.20 FL	*- FL
25	1		*FRONT HEADLAMP ASSEMBLY RH	Not Necessary	2,380.00 FL	*- FL
26	1		*FRONT HEADLAMP ASSEMBLY LH	Broken	2,380.00 FL	*2,380.00 FL
27	1		*FRONT BONNET	Repair	916.50 FL	*- FL
28	1		*FRONT BONNET HINGE RH	Not Necessary	54.40 FL	*- FL
29	1		*FRONT BONNET HINGE LH	Not Necessary	54.40 FL	*- FL
30	1		*FRONT BONNET LOCK ASSEMBLY	Not Necessary	75.50 FL	*- FL
31	1		*FRONT BONNET INSULATOR CENTRE	Not Necessary	169.20 FL	*- FL
32	1		*FRONT BONNET INSULATOR RH	Not Necessary	47.00 FL	*- FL
33	1		*FRONT BONNET INSULATOR LH	Not Necessary	47.00 FL	*- FL
34	1		*FRONT DOOR LH	Not Necessary	884.30 FL	*- FL
35	1		*FRONT FENDER LH	Dented	327.50 FL	*327.50 FL
36	1		*FRONT FENDER INNER UPPER GARNISH LH	Not Necessary	22.50 FL	*- FL
37	1		*FRONT FENDER INNER COWLING LH	Torn	131.00 FL	*131.00 FL
38	1		*FRONT SHOCK ABSORBER LH	Not Necessary	367.60 FL	*- FL
39	1		*FRONT LOWER ARM LH	Not Necessary	527.80 FL	*- FL
40	1		*FRONT KNUCKLE ARM LH	Bent	424.80 FL	*424.80 FL
41	1		*FRONT WHEEL BEARING LH	Jammed	382.20 FL	*382.20 FL
42	1		*FRONT SUPPORT PANEL	Not Necessary	381.60 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*AIRCON CONDENSER	Not Necessary	654.90 FL	*- FL
44	1		*RADIATOR ASSEMBLY	Not Necessary	915.80 FL	*- FL
45	1		*RADIATOR SHROUD	Not Necessary	108.80 FL	*- FL
46	1		*FAN BLADE	Not Necessary	55.50 FL	*- FL
47	1		*FAN MOTOR ASSEMBLY	Not Necessary	282.00 FL	*- FL
48	1		*FRONT NUMBER PLATE	Not Necessary	50.00 FS	*- FS
49	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
50	1		*SET FRONT HEADLAMP CLIPS	Not Necessary	50.00 FS	*- FS
51	1		*SET FRONT GRILLE ASSEMBLY CLIPS	Necessary	50.00 FS	*20.00 FS
52	1		*SET FRONT SUPPORT PANEL TOP GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
53	1		*SET FRONT FENDER INNER COWLING CLIPS	Necessary	50.00 FS	*20.00 FS
54	1		*FRONT BONNET SEALANT	Not Necessary	150.00 FS	*- FS
55	1		*FRONT FENDER LH SEALANT	Not Necessary	150.00 FS	*- FS
56	1		*FRONT SUPPORT PANEL SEALANT	Not Necessary	150.00 FS	*- FS
57	1		*FRONT DOOR LH SEALANT	Not Necessary	150.00 FS	*- FS
58	1		*FRONT WHEEL RIM LH	Cut	1,500.00 FS	*800.00 FS
59	1		*FRONT TYRE LH	Not Necessary	450.00 FS	*- FS
60	1		*FRONT BUMPER LOWER SPOILER - AFTER MARKET	Broken	1,200.00 FS	*700.00 FS
61	1		*RADIATOR COOLANT	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	18,794.30	6,396.10
- List Item Discount on L Items 20.00/20.00% (\$)	2,938.86	965.22
Total Parts (\$)	15,855.44	5,430.88

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT, REMOVE & REFIX PARTS	New	1,600.00	400.00
2	TO SPRAY PAINT AFFECTED AREAS	New	1,400.00	600.00
3	WIRING & BULB CHECK	New	100.00	30.00
4	TO TRANSFER FRONT DOOR LH MECHANISM	New	150.00	0.00
5	TO REMOVE & REFIX AIRCON CONDENSER & TOP UP GAS	New	150.00	0.00
6	TO REMOVE & REFIX RADIATOR & PRESSURE TEST	New	150.00	0.00
7	TO REMOVE & REFIX FRONT UNDERCARRIAGE	New	450.00	100.00
8	TO REMOVE & REFIX FRONT TYRE AND CONDUCT WHEEL BALANCING	New	150.00	20.00
9	TO CONDUCT FOUR WHEEL ALIGNMENT	New	150.00	80.00
10	TO APPLY ANTI RUST ON AFFECTED PARTS	New	100.00	30.00
11	TO CONDUCT WATER LEAK TETS	New	100.00	0.00
12	TO SEND DIAGNOSTIC & RESET CONTROL UNIT. PROGRAMMING & CALIBRATION	New	480.00	0.00
Gross Labour Cost (S\$)			4,980.00	1,260.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >