

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24110118/XMA3Q2  
Date: 17/01/2025

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D22MPC0007747\_02  
Claimant Vehicle No : YQ1581Y Insured Vehicle No : SNB5257S  
Date of Loss: 08/10/2024 Nature of Claim: TP Claim No: MPC2024D0013136

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: YQ1581Y  
Make & Model: MITSUBISHI CANTER, 3.0 D FEB21ER3SDEN (CBU) (M) Engine No: 4P10D92888  
Reg. Date: 25/10/2019 (Man. Year: 2019) Chassis No: FEB21EA30339  
Colour: White Odometer: 309271 km  
Engine Capacity: 2998 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15 Rear Tyre Size: 195 R15 (D)  
Front Left Side: Austone 6 mm Rear Left Side: Austone 6/6 mm  
Front Right Side: Austone 6 mm Rear Right Side: Austone 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	742.00	219.00	523.00	70.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	860.00	420.00	440.00	51.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	1,602.00	639.00	963.00	60.11
Approved Total (Overridden) (S\$)		500.00		
(S\$)	1,602.00	500.00	1,102.00	68.79
+ GST 9.00/9.00% (S\$)	144.18	45.00	99.18	68.79
Nett Amount (S\$)	1,746.18	545.00	1,201.18	68.79
+ Loss of Use (2.0 x S\$100.00/day) (S\$)		200.00		
+ Doc/Search Fee (S\$)		2.18		
Nett Liability (S\$)		747.18		
Global Sum Settlement (S\$)		740.00		

INSPECTION

Date of Assignment: 07/11/2024  
Date Inspected: 07/11/2024 Inspected At: Liu's Brother Auto Engineering Workshop (HQ)  
KAKI BUKIT  
Singapore 417883  
Estimated Period of Repair: 2.0 days

Adjuster: MARCUS CHUA Manager: Daphne Lee Mooi Ngiuk

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 16 Dec 2024)	
Parts:	N/A	mitsubishi canter 3.0 d feb21er3sden (cbu) (m) (model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YQ1581Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR RH TAIL LAMP	Cracked	292.00 F	*292.00 FL
2	1		*REAR RH TAIL LAMP PANEL	Repair	450.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					742.00	292.00
- List Item Discount on L Items 0.00/25.00% (S\$)					0.00	73.00
Total Parts (S\$)					742.00	219.00

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION	New	30.00	20.00
2	LABOR FOR PANEL BEATING ,CUT ,WELD ,STRAIGHTEN & REPLACING PARTS ETCS	New	400.00	200.00
3	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED AREAS	New	400.00	200.00
4	TO APPLY RUST PROOFING ,RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA	New	30.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>860.00</b>	<b>420.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >