



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO JED 8141

| REPLACEMENT OF PARTS |   |                      |                        |                   |
|----------------------|---|----------------------|------------------------|-------------------|
| Qty                  | Description of Parts                          | Condition            | Workshop Estimate (\$) | Our Adjusted (\$) |
| 1                    | BUMPER CLIPS (DISC 20%)                       | NECESSARY            | \$5.20                 | \$4.16            |
| 1                    | BUMPER FRONT COVER (DISC 20%)                 | TORN                 | \$463.50               | \$370.80          |
| 1                    | BUMPER REINFORCEMENT FRONT (DISC 20%)         | BENT                 | \$949.00               | \$759.20          |
| 1                    | FRONT PANEL ASSEMBLY (NPA)                    | TO REPAIR SEE LABOUR | \$0.00                 | \$0.00            |
| 1                    | GRILLE PANEL / HEADLAMP MASK [RH] (DISC 20%)  | BROKEN               | \$138.00               | \$110.40          |
| 1                    | HEADLAMP ASSY RH (DISC 20%)                   | BROKEN               | \$987.00               | \$789.60          |
| 1                    | HEADLAMP MOUNTING PANEL [RH] (DISC 20%)       | BROKEN               | \$382.00               | \$305.60          |
| 1                    | HEADLAMP PANEL MASK RH                        | TO REPAIR SEE LABOUR | \$423.00               | \$0.00            |
| 1                    | KANGAROO BAR (NPA)                            | TO REPAIR SEE LABOUR | \$0.00                 | \$0.00            |
| 1                    | DOOR FRONT HINGE LOWER RH                     | NOT NECESSARY        | \$286.00               | \$0.00            |
| 1                    | DOOR FRONT HINGE UPPER RH                     | NOT NECESSARY        | \$384.00               | \$0.00            |
| 1                    | DOOR FRONT RH (DISC 20%)                      | EDGE CRUMPLED        | \$850.00               | \$680.00          |
| 1                    | BUMPER SIGNAL LAMP FRONT RH                   | NOT NECESSARY        | \$84.00                | \$0.00            |
| 1                    | CHASSIS MEMBER FRONT ASSEMBLY RH (NPA)        | TO REPAIR SEE LABOUR | \$0.00                 | \$0.00            |
| 1                    | INDICATOR LAMP FRONT RH (DISC 20%)            | BROKEN               | \$197.00               | \$157.60          |
|                      | <b>LESS 0.00 / 40.00% BETTERMENT DISCOUNT</b> |                      | \$0.00                 | (\$1,270.94)      |
|                      |   |                      | \$5,148.70             | \$1,906.42        |

| Special Nett |                                |           |                        |                   |
|--------------|--------------------------------|-----------|------------------------|-------------------|
| Qty          | Description of Parts           | Condition | Workshop Estimate (\$) | Our Adjusted (\$) |
| 1            | WINDSCREEN SEALANT, FRONT (SN) | NECESSARY | \$85.00                | \$40.00           |
|              |                                |           | \$85.00                | \$40.00           |

| Labour |  |               |                        |                   |
|--------|--|---------------|------------------------|-------------------|
|        | Description of Parts   | Condition     | Workshop Estimate (\$) | Our Adjusted (\$) |
|        | PAINTWORK MATERIALS (PAINT)  |               | \$900.00               | \$200.00          |
|        | ELECTRICAL (CHECK & DIAGNOSE)  |               | \$100.00               | \$30.00           |
|        | MOUNTING / DISMOUNTING ONTO CAR-O-LINER FRAME ALIGNER BENCH; KNOCK, PUTTY & RESPRAY TO MAKE GOOD CLAMP MARKS ON RH & LH ROCKER PANEL                                 | NOT NECESSARY | \$800.00               | \$0.00            |
|        | LABOUR COST (RATE HRS). OTHERS: 40.30HRS. INCLUSIVE OF THE REPAIR OF FRONT PANEL ASSEMBLY, HEADLAMP PANEL MASK RH, KANGAROO BAR AND CHASSIS MEMBER FRONT ASSEMBLY RH |               | \$1,410.50             | \$200.00          |



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

| Labour  |           |                        |                   |
|---|-----------|------------------------|-------------------|
| Description of Parts                                  | Condition | Workshop Estimate (\$) | Our Adjusted (\$) |
| LABOUR COST (RATE HRS). MET: 14.30HRS                 |           | \$500.50               | \$400.00          |
| LABOUR COST (RATE HRS). PANEL: 8.50HRS                |           | \$297.50               | \$240.00          |
| LABOUR COST (RATE HRS). PAINT: 38.00HRS               |           | \$1,330.00             | \$400.00          |
| TOWING  |           | \$150.00               | \$150.00          |
|   |           | \$5,488.50             | \$1,620.00        |
| <b>GRAND TOTAL</b>                                    |           | <b>\$10,722.20</b>     | <b>\$3,566.42</b> |
| <b>RECOMMENDED COST OF REPAIRS (RINGGIT MALAYSIA)</b> |           |                        | <b>\$3,566.42</b> |
| Report Ref No: CS1/CTI24110121/Enh3e2                 |           |                        |                   |

**CTY**

STEVE CHEN TSUE YEE

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of repositibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.