



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO JED 8141

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	BUMPER CLIPS (DISC 20%)	NECESSARY	\$5.20	\$4.16
1	BUMPER FRONT COVER (DISC 20%)	TORN	\$463.50	\$370.80
1	BUMPER REINFORCEMENT FRONT (DISC 20%)	BENT	\$949.00	\$759.20
1	FRONT PANEL ASSEMBLY (NPA)	TO REPAIR SEE LABOUR	\$0.00	\$0.00
1	GRILLE PANEL / HEADLAMP MASK [RH] (DISC 20%)	BROKEN	\$138.00	\$110.40
1	HEADLAMP ASSY RH (DISC 20%)	BROKEN	\$987.00	\$789.60
1	HEADLAMP MOUNTING PANEL [RH] (DISC 20%)	BROKEN	\$382.00	\$305.60
1	HEADLAMP PANEL MASK RH	TO REPAIR SEE LABOUR	\$423.00	\$0.00
1	KANGAROO BAR (NPA)	TO REPAIR SEE LABOUR	\$0.00	\$0.00
1	DOOR FRONT HINGE LOWER RH	NOT NECESSARY	\$286.00	\$0.00
1	DOOR FRONT HINGE UPPER RH	NOT NECESSARY	\$384.00	\$0.00
1	DOOR FRONT RH (DISC 20%)	EDGE CRUMPLED	\$850.00	\$680.00
1	BUMPER SIGNAL LAMP FRONT RH	NOT NECESSARY	\$84.00	\$0.00
1	CHASSIS MEMBER FRONT ASSEMBLY RH (NPA)	TO REPAIR SEE LABOUR	\$0.00	\$0.00
1	INDICATOR LAMP FRONT RH (DISC 20%)	BROKEN	\$197.00	\$157.60
	LESS 0.00 / 40.00% BETTERMENT DISCOUNT		\$0.00	(\$1,270.94)
			\$5,148.70	\$1,906.42
Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	WINDSCREEN SEALANT, FRONT (SN)	NECESSARY	\$85.00	\$40.00
			\$85.00	\$40.00
Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	PAINTWORK MATERIALS (PAINT)		\$900.00	\$200.00
	ELECTRICAL (CHECK & DIAGNOSE)		\$100.00	\$30.00
	MOUNTING / DISMOUNTING ONTO CAR-O-LINER FRAME ALIGNER BENCH; KNOCK, PUTTY & RESPRAY TO MAKE GOOD CLAMP MARKS ON RH & LH ROCKER PANEL	NOT NECESSARY	\$800.00	\$0.00
	LABOUR COST (RATE HRS). OTHERS: 40.30HRS. INCLUSIVE OF THE REPAIR OF FRONT PANEL ASSEMBLY, HEADLAMP PANEL MASK RH, KANGAROO BAR AND CHASSIS MEMBER FRONT ASSEMBLY RH		\$1,410.50	\$200.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Labour			
Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
LABOUR COST (RATE HRS). MET: 14.30HRS		\$500.50	\$400.00
LABOUR COST (RATE HRS). PANEL: 8.50HRS		\$297.50	\$240.00
LABOUR COST (RATE HRS). PAINT: 38.00HRS		\$1,330.00	\$400.00
TOWING		\$150.00	\$150.00
		\$5,488.50	\$1,620.00
GRAND TOTAL		\$10,722.20	\$3,566.42
RECOMMENDED COST OF REPAIRS			\$3,566.42
Report Ref No: CS1/CTI24110121/Enh3e2			

CTY

STEVE CHEN TSUE YEE

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of repositibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.