



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CS/FCI24110122/Uvp3m4
16 RAFFLES QUAY	Date:	15/11/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHB 4462T	Veh. Inspected	GBF 968C
Policy No.	D-24101861MFCT	Coverage	0
Claim No.	D24009732MFCT	Excess	\$0.00
Assign From	JOANNE	Assign Date	06/11/2024

### 2. Vehicle Details

Make & Model	TOYOTA HIACE	C.C	2982
Engine No.	1KD2626759	Year of Reg.	23/06/2016
Chassis No.	JTFHT02P500199719	Colour	WHITE
Odometer	385363 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: NIL		

### 3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	195R15	MAXMILER	6
L/H Front Tyre	195R15	MAXMILER	6
R/H Rear Tyre	195R15	MAXMILER	6
L/H Rear Tyre	195R15	MAXMILER	6

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	04/11/2024	Inspection Date	07/11/2024
Survey held at	CARSMITH PTE LTD - 8 KAKI BUKIT AVE 4 #04-35 SINGAPORE 415875		

### 5a. Remarks

A)DAMAGES CONSISTENT TO ACCIDENT REPORT.  
B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days