



PRIORITY SERVICES

Insurance Loss Adjusters and Motor Appraisers

Blk 779 Yishun Avenue 2

#01-1545 Singapore 760779

Tel: 6293 4822 Fax: 6296 3283

E-mail: admin@priorityservices.sg

Messrs. Sompoo Insurance Pte Ltd
50 Singapore Land Tower
#03-03 Raffles Place
Singapore 048623

Bill No : DN/00957/21

Date : 8/7/2021

Dr.

To

Survey Fee (S\$) : 150.00
Photographs (S\$) :
Transport (S\$) :
Resurvey (S\$) :
Miscellaneous (S\$) :

Services rendered including photographs and transport charges

(S\$) : 150.00

Our Reference : TP-0020/07/21
Insured : GBG 2749 A
Date Of Accident : 29/03/2021
Policy / Cert. No. : Paper Survey
Your Claim No : CMTD2100970/RUC
Vehicle : Toyota Hiace Van (M) - GBC 8781 L

Dollars : One Hundred Fifty ONLY

For PRIORITY SERVICES

E & O.E.



PRIORITY SERVICES

Insurance Loss Adjusters and Motor Appraisers
Blk 779 #01-1545 Yishun Ave 2 Singapore 760779
Tel: 62934822 Fax: 62963283
E-mail: admin@priorityservices.sg

Date: 8 July 2021

Your Ref: CMTD2100970/RUC

Our Ref: TP-0020/07/21

Motor Claims Department
M/s. Sompo Insurance Pte. Ltd.
50 Raffles Place #05-01/06
Singapore Land Tower
Singapore 048623

Attention: Ms. Ruth Chua

Madam,

Inspection of 2014 Toyota Hiace Van (M)
Registration No.: GBC 8781 L
Odometer Reading: 173917 km
Chassis No.: JTFHT02P700132703

We refer to your instructions to us to conduct a paper survey of the above vehicle. A pre-repair survey was conducted on 30-03-2021, followed by inspection of dismantled parts on 31-03-2021 and resurvey after repairs on 07-04-2021.

The following documents were received: -

- 1) Copy of survey report by M/s. Impact Analysis Consultant
- 2) 91 copies of photos depicting damages sustained by GBC 8781 L
- 3) Accident reports by drivers of GBC 8781 L and GBG 2749 A

The vehicle sustained rear damages during an accident on 29-03-2021.

Repair cost submitted was \$6,700.00 lump-sum.

We append below our findings: -

<u>Replacement of Parts</u>		<u>Revised Amount</u>	<u>Our Recommendation</u>
1pc.	Tail gate – not consistent	\$ 1,758.90	\$ -
1pc.	Tail gate outer garnish (black) – not consistent	195.50	-
1pc.	Tail gate top lock – not consistent	224.50	-
1pc.	Tail gate weatherstrip – not consistent	265.80	-
1pc.	Tail gate logo – not consistent	60.10	-
2pcs.	Tail gate damper – not consistent	370.00	-
1pc.	Tail gate wiper motor – not consistent	311.00	-

1set	Tail gate side stopper – not consistent	\$ 55.00	\$ -
1pc.	Tail gate windscreen glass	1,214.00	1,214.00
1pc.	Tail gate inner board – not consistent	230.10	-
1pc.	Rear bumper – not consistent	452.00	-
2pcs.	Rear bumper side retainer – not consistent	90.00	-
1pc.	Rear fender air vent LH – not consistent	95.20	-
2pcs.	Rear tail lamp – not consistent	590.40	-
1pc.	Rear end panel – not consistent	402.20	-
		=====	=====
		\$ 6,314.70	\$ 1,214.00
	Less 25%	1,578.67	303.50
		=====	=====
		\$ 4,736.03	\$ 910.50

Special Nett Items:-

1pc.	Tail gate 70km/h sticker – not consistent	\$ 20.00	\$ -
1pc.	Tail gate windscreen sealant	60.00	60.00
8pcs.	Rear bumper clips – not consistent	36.00	-
1pc.	Rear reverse sensor – not consistent	250.00	-
1pc.	Tail gate company advertisement – not consistent	550.00	-
1pc.	Tail gate inner aluminium plate – not consistent	321.00	-
1pc.	Rear end panel sealant – not consistent	40.00	-
		=====	=====
	Total For Parts:-	\$ 6,013.03	\$ 970.50
		=====	=====

Labour Charges:-

To dismantle, replace, cut, weld, knock out dents to straighten accident parts as-mentioned on the 'Parts Repair' column inclusive of replacement parts. – not consistent	\$ 1,080.00	\$ -
Putty and spray painting to adjacent panels. Job allowance. Paint/material. – not consistent	800.00	-
Apply rust proofing on the adjacent panels. – not consistent	40.00	-
Remove and replace rear bumper reverse sensor and conduct distance safety setting. – not consistent	76.50	-
Remove and replace tail gate rear windscreen glass.	157.50	157.50
Conduct water leak test for rear portion associated repair works. – not necessary	45.00	-
Transfer of existing tail gate mechanism to new tail gate. – not consistent	90.00	-

Remove and refix upholstery to facilitate the repair works. – not necessary	\$ 67.50	\$ -
Wiring and bulb checking. – not necessary	45.00	-
	=====	=====
Total:-	\$ 8,414.53	\$ 1,128.00
	=====	=====
Lump-sum repairs:	\$ 6,700.00	-
Part-By-Part repairs:	-	\$ 1,128.00

Estimated period of repairs: 1 working days

- 1) According to the driver of GBG 2749 A, the LH wing mirror of his lorry had knocked and broke the rear windscreen of GBC 8781 L.
- 2) The photos taken by reporting centre did not reveal any damages on vehicle GBG 2749 A.
- 3) The rear tail gate, rear bumper and the end panel of GBC 8781 L were badly dented.

These did not appear consistent to damages that could be caused by vehicle GBG 2749 A.

Pre-accident Market Value : About \$ 37,000.00
COE rebate : \$ 6,904.00


Vehicle within economical limit to repair.

We leave the decision of settlement to you.

Assuring you of our best services always


Yours faithfully

PRIORITY SERVICES



JIMMY S. T. LEE AMSOE, AMIRTE, MSAAA
Motor Appraiser

Surveyed by:



LAWRENCE NG, MSAAA
Motor Appraiser