



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO GBG 2519Y

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	TAILGATE	DENTED	\$2,155.30	\$2,155.30
1	TAILGATE LOGO	NECESSARY	\$80.00	\$80.00
1	TAILGATE TOYOTA HIACE STICKER	NECESSARY	\$70.00	\$70.00
1	TAILGATE LOCK	DAMAGED	\$350.00	\$350.00
1	TAILGATE WEATHERSTRIP	NOT NECESSARY	\$410.00	\$0.00
1	REAR BUMPER	DEFORMED	\$520.00	\$520.00
1	REAR BUMPER SIDE RETAINER	NOT NECESSARY	\$85.00	\$0.00
1	END PANEL	NOT NECESSARY	\$755.30	\$0.00
1	END PANEL TOP GARNISH	NOT NECESSARY	\$250.00	\$0.00
	<b>LESS 25.00% DISCOUNT</b>		(\$1,168.90)	(\$793.83)
			<b>\$3,506.70</b>	<b>\$2,381.47</b>

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR NUMBER PLATE (SN)	NOT NECESSARY	\$50.00	\$0.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	\$100.00	\$60.00
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	\$20.00	\$20.00
1	REVERSE SENSOR (SN)	DAMAGED	\$220.00	\$200.00
1	70KM/H (SN)	NECESSARY	\$50.00	\$15.00
			<b>\$440.00</b>	<b>\$295.00</b>

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	PANEL BEATING, REMOVAL AND REPLACING PARTS	NOT NECESSARY	\$1,400.00	\$400.00
	TO SPRAY PAINT AFFECTED AREA		\$1,400.00	\$400.00
	TUFF COAT		\$200.00	\$0.00
	WIRING CHECK		\$80.00	\$30.00
	REMOVE AND REFIX REAR WINDSCREEN		\$120.00	\$120.00
	REMOVE AND REFIX TAILGATE WINDSCREEN		\$120.00	\$60.00
	REMOVE AND REFIX REVERSE SENSOR AND SETTING		\$120.00	\$50.00
			\$3,440.00	\$1,060.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

<b>GRAND TOTAL</b>		<b>\$7,386.70</b>	<b>\$3,736.47</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)</b>		<b>\$2,950.00</b>
Report Ref No: CS/INC24110134/Avh3e2			

**TOTAL FOR SPARE PARTS: \$ 3,946.70 \$ 2,676.47**  
**TOTAL FOR LABOUR : \$ 3,440.00 \$ 1,060.00**  
**TOTAL REPAIR COST: \$ 7,386.70 \$ 3,736.47**

**LWP**

ADRIAN LING WAI PING

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.