



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO JVH 4615

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
2	FRONT FORK TUBE ASSY	SERVICEABLE	\$960.00	\$0.00
1	FORK UNDER BRACKET	NOT NECESSARY	\$260.00	\$0.00
1	FRONT RIM	NOT NECESSARY	\$480.00	\$0.00
1	FRONT BRAKE DISC	NOT NECESSARY	\$285.00	\$0.00
1	FRONT RIM SHAFT	NOT NECESSARY	\$88.00	\$0.00
1	FRONT RIM BEARING	NOT NECESSARY	\$90.00	\$0.00
1	HANDLE BAR	BENT	\$255.00	\$190.00
1	HANDLE BAR END	CUT	\$88.00	\$48.00
1	SET HAND GRIP	TORN	\$76.00	\$76.00
1	METER ASSY	NOT NECESSARY	\$455.00	\$0.00
1	METER COVER	CUT	\$135.00	\$135.00
1	HEADLAMP ASSY	SERVICEABLE	\$485.00	\$0.00
1	BRAKE LEVER	CUT	\$95.00	\$60.00
1	FRONT SIGNALS	SERVICEABLE	\$185.00	\$0.00
1	SET SIDE MIRROR	BROKEN	\$128.00	\$90.00
1	SET FAIRING ASSY	CUT/CRACKED	\$735.00	\$580.00
1	FRONT FOOTREST BRACKET	BENT	\$225.00	\$155.00
1	FRONT FOOTREST RUBBER	TORN	\$95.00	\$60.00
1	BASKET	CRACKED	\$125.00	\$125.00
1	BRAKE PEDAL	CUT	\$165.00	\$165.00
1	EXHAUST ASSY	TO REPAIR SEE LABOUR	\$680.00	\$0.00
1	EXHAUST PROTECTOR	CUT	\$165.00	\$148.00
1	SET REAR FOOTREST	NOT FITTED	\$125.00	\$0.00
1	SET REAR FOOTREST BRACKET	NOT NECESSARY	\$325.00	\$0.00
	LESS 10.00% DISCOUNT		(\$670.50)	(\$183.20)
			\$6,034.50	\$1,648.80

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	SET NUMBER PLATE (SN)	NECESSARY	\$38.00	\$10.00
2	FORK OILS (SN)	NOT NECESSARY	\$30.00	\$0.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
2	FORK OIL SEALS (SN)	NOT NECESSARY	\$56.00	\$0.00
1	SET STEERING CONE (SN)	NOT NECESSARY	\$96.00	\$0.00
1	REAR BOX (SN)	CUT	\$480.00	\$280.00
1	REAR BOX BRACKET (SN)	BENT	\$180.00	\$110.00
1	STICKER (SN)	NECESSARY	\$120.00	\$60.00
			\$1,000.00	\$460.00

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO CHECK WIRING AND RESET HEADLAMP FOCUSING	NOT NECESSARY	\$80.00	\$0.00
	TO REPAIR BODY FRAME	NOT NECESSARY	\$420.00	\$0.00
	TO PROVIDE LABOUR. INCLUSIVE OF THE REPAIR OF EXHAUST ASSY		\$450.00	\$300.00
			\$950.00	\$300.00

GRAND TOTAL			\$7,984.50	\$2,408.80
--------------------	--	--	-------------------	-------------------

	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			\$1,000.00
--	---	--	--	-------------------

Report Ref No: CS/INC24110135/Uqh3e2				
--------------------------------------	--	--	--	--

TOTAL FOR SPARE PARTS: \$ 7,034.50 \$ 2,108.80
TOTAL FOR LABOUR : \$ 950.00 \$ 300.00
TOTAL REPAIR COST: \$ 7,984.50 \$ 2,408.80

CKS

MARCUS CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.