



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO JNW 7708

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
2	FRONT FORK TUBE ASSY	NOT NECESSARY	\$640.00	\$0.00
1	FORK UNDER BRACKET	NOT NECESSARY	\$225.00	\$0.00
1	FRONT WHEEL RIM	NOT NECESSARY	\$495.00	\$0.00
1	FRONT RIM SHAFT	NOT NECESSARY	\$105.00	\$0.00
1	FRONT RIM BEARING	NOT NECESSARY	\$88.00	\$0.00
1	FRONT BRAKE DISC	NOT NECESSARY	\$185.00	\$0.00
1	HANDLE BAR	SERVICEABLE	\$145.00	\$0.00
1	SET HANDLE-BAR ENDS	CUT	\$125.00	\$0.00
1	SET HAND GRIP	NOT NECESSARY	\$90.00	\$0.00
1	HANDLE BAR INNER BRACKET	NOT NECESSARY	\$135.00	\$0.00
1	REAR EXHAUST PIPE	DAMAGED	\$485.00	\$485.00
1	SET SIDE MIRRORS	CUT	\$110.00	\$60.00
1	SET FRONT SIGNALS	NOT NECESSARY	\$140.00	\$0.00
1	SET FAIRING ASSY	CRACKED	\$650.00	\$520.00
1	FRONT FOOTREST BRACKET	BENT	\$65.00	\$65.00
2	FRONT FOOTREST RUBBERS	NECESSARY/TORN	\$70.00	\$70.00
1	BRAKE PEDAL	CUT	\$165.00	\$110.00
1	REAR FOOTREST O/S	SCRATCHED	\$80.00	\$80.00
1	REAR EXHAUST CHROME	BENT	\$156.00	\$156.00
	LESS 10.00% DISCOUNT		(\$415.40)	(\$154.60)
			\$3,738.60	\$1,391.40

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	SET NUMBER PLATE (SN)	FRONT NECESSARY	\$38.00	\$10.00
2	FORK OILS (SN)	NOT NECESSARY	\$30.00	\$0.00
2	FORK OIL SEALS (SN)	NOT NECESSARY	\$56.00	\$0.00
1	SET STEERING CONE (SN)	NOT NECESSARY	\$185.00	\$0.00
1	REAR BOX (SN)	CUT	\$480.00	\$250.00
1	REAR BOX BRACKET (SN)	TO REPAIR SEE LABOUR	\$180.00	\$0.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	SET STICKER (SN)	NECESSARY	\$120.00	\$60.00
			\$1,089.00	\$320.00

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO CHECK WIRING AND RESET HEADLAMP FOCUSING	NOT NECESSARY	\$80.00	\$0.00
	TO PROVIDE LABOUR. INCLUSIVE OF THE REPAIR OF REAR BOX BRACKET		\$480.00	\$300.00
	TO RE-ALIGN BODY FRAME	NOT NECESSARY	\$420.00	\$0.00
			\$980.00	\$300.00

GRAND TOTAL			\$5,807.60	\$2,011.40
--------------------	--	--	-------------------	-------------------

	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			\$900.00
--	---	--	--	-----------------

Report Ref No: CS/INC24110136/Uvh3e2

TOTAL FOR SPARE PARTS: \$ 4,827.60 \$ 1,711.40
TOTAL FOR LABOUR : \$ 980.00 \$ 300.00
TOTAL REPAIR COST: \$ 5,807.60 \$ 2,011.40

CKS

MARCUS CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.