

ASS. REC. BY: Tajm

REF: CD/LPC24110137 / Tua3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$18K

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKW7247H Yr Regn: 2015, 11

Type: M Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Vezel c.c. 1496

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 115174 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: R411103391

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: NI / S/R / STD A/R / or

Tyre Size: F: 215/55R17

R: ~ ~

BS / DUN / EXNOVA / GY / FS / LIZA / MG / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. _____

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/G / Rooftop or

Rear

R/Bal. 6 mm

L/Bal. 6 mm

D.O.I. 08/11/24

Century Motors

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>Repair limit \$4K</u>

Date/Time, File Pass to?

☐ : Prel. Report

1)

Date/Time, File Return to?

☐ : Final Report

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

\$ + RS. \$ _____

Photos

Others

TOTAL

Report Format: _____

Lump Sum / L.R. (\$ _____)



Century Motors

Century Motors (Singapore) Pte Ltd
6 Marsiling Lane
Singapore 739145



E: claims@autoinsure.com.sg
T: (65) 3157 2626
GST No.: 192800002R
Page No.1

AUTOMOBILE ASSESSMENT REPORT

Our Ref: **SKW7247H**
Your Ref: **XD7564M**

CM/11/24/0053

Date: **06-Nov-24**

BY EMAIL ONLY
(claims@autoinsure.com.sg)

ATTENTION: MOTOR CLAIMS DEPT

LONPAC INSURANCE BERHAD

300 Beach Road
#17-04/07 The Concourse
Singapore 199555

Assessed Vehicle No : **SKW7247H**
Car Make and Model : **HONDA VEZEL 1.5S CVT**
Date of Accident : **04-Nov-24**
Date of Assessment : **06-Nov-24**

We have carried out a physical assessment of **SKW7247H** at our workshop Auto Insure Pte Ltd sustained damages to the LH SIDE portion of the vehicle.


4. DESCRIPTION OF DAMAGE

At the time of the inspection observed that this vehicle had sustained damages to the LH SIDE portion of the vehicle.

Please see attached schedule for details.

Remarks: NIL

Claims Type : **L/S**
Adjusted Amount : **\$ 20,196.61**
Est. Repair Days : **8**



Pursuant to your instruction, we have **NOT AUTHORIZED** repair.
The assessment was conducted on a "**WITHOUT PREJUDICE**" basis.

If we are not notified of anything within 14 Days from the date hereof, this report shall be treated as correct.

Disclaimer

This report is intended for the exclusive use of the addressee solely in relation to the loss of occurrence in which the assessed vehicle is involved.

No liability or responsibility whatsoever shall be held by

CENTURY MOTORS PTE. LTD. For any reliance on this report by any third party.

Our Ref: **SKW7247H**

Your Ref: **XD7564M**

S/NO	QTY	DESCRIPTIONS	ASSESSED CONDITION	EST. BY WORKSHOP
<u>PARTS REPLACEMENT - LIST ITEMS</u>				
1	1	FRT BUMPER		\$ 665.80 <i>Rx</i>
2	1	FRT BUMPER SIDE RETAINER LH		\$ 46.50 <i>X</i>
3	1	FRT HEADLAMP LH		\$ 2,617.30 <i>X</i>
4	1	FRT BUMPER FOG LAMP COVER LH		\$ 96.40 <i>X</i>
5	1	FRT BUMPER LOWER COVER		\$ 365.70 <i>X</i>
6	1	FRT FENDER LH		\$ 617.60 <i>X</i>
7	1	FRT FENDER INNER SHIELD LH		\$ 289.80 <i>X</i>
8	1	FRT FENDER WHEELARCH COVER LH		\$ 153.70 <i>Rx</i>
9	1	SIDE MIRROR ASSY LH		\$ 1,466.80 <i>?</i>
10	1	SIDE MIRROR COVER LH		\$ 193.20 <i>cut-</i>
11	1	FRT DOOR LH		\$ 1,948.30 <i>bt-</i>
12	1	FRT DOOR UPPER HINGE LH		\$ 115.90 <i>X</i>
13	1	FRT DOOR LWR HINGE LH		\$ 115.90 <i>X</i>
14	1	FRT DOOR LOCK LH		\$ 521.10 <i>?</i>
15	1	FRT DOOR OUTER HANDLE LH		\$ 519.70 <i>cut-</i>
16	1	FRT DOOR OUTER HANDLE GARNISH LH		\$ 286.30 <i>cut-</i>
17	1	REAR DOOR LH		\$ 1,732.10 <i>bt-</i>
18	1	REAR DOOR UPPER HINGE LH		\$ 115.90 <i>?</i>
19	1	REAR DOOR LWR HINGE LH		\$ 115.90 <i>?</i>
20	1	REAR DOOR LOCK LH		\$ 558.30 <i>X</i>
21	1	REAR DOOR OUTER HANDLE LH		\$ 211.80 <i>X</i>
22	1	SILL PANEL LH		\$ 521.70 <i>X</i>
23	1	REAR FENDER LH		\$ 1,743.20 <i>X</i>
24	1	REAR FENDER WHEELARCH GARNISH LH		\$ 192.80 <i>X</i>
25	1	REAR BUMPER		\$ 616.70 <i>X</i>
26	1	REAR BUMPER SIDE RETAINER LH		\$ 46.50 <i>X</i>
27	1	REAR BUMPER CORNER COVER LH		\$ 235.10 <i>X</i>
			SUB TOTAL	\$ 16,110.00
			LESS 10%	\$ 1,611.00
			TOTAL AMOUNT	\$ 14,499.00

Our Ref: **SKW7247H**

Your Ref: **XD7564M**

S/NO	QTY	SPECIAL NETT ITEMS	ASSESSED CONDITION	EST. BY WORKSHOP
1	1	FRT BUMPER CLIPS		\$ 50.00 X
2	1	REAR BUMPER CLIPS		\$ 50.00 X
3	1	FRT FENDER WHEELARCH CLIPS		\$ 25.00 ✓
4	1	REAR FENDER WHEELARCH CLIPS		\$ 25.00 ✓
			SUB TOTAL	\$ 150.00
			TOTAL PARTS COST	\$ 14,649.00

Our Ref: **SKW7247H**

Your Ref: **XD7564M**

S/NO	DESCRIPTION	EST. BY WORKSHOP
LABOUR & PAINTWORK		
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACED THE DAMAGED PARTS AND COMPONENTS	\$ 1,200.00 ⁶⁰⁰
2	TO REMOVE & REFIT WIRING SYSTEM AT ACCIDENT AND CHECK FOR PROPER FUNCTIONS	\$ 80.00 40
3	TO REMOVE AND REFIT FRT DOOR LH MECHANISM	\$ 200.00 60
4	TO REMOVE AND REFIT REAR DOOR LH MECHANISM	\$ 200.00 60
5	TO CONDUCT ALIGNMENT AND BALANCING	\$ 150.00 X
6	TO RESPRAY AND SUPPLY EXPANDABLE ITEMS & PUFFY ON PARTS REPLACED	\$ 1,800.00 700
7	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS	\$ 80.00 40
8	SUNDRIES (SAND PAPER, WELDING WIRE ETC.)	\$ 60.00 X
9	TO VACUUM, WAXING & CLEAN	\$ 60.00 X
10	TO PERFORM WATER SEEPAGE TEST ON REPAIRED PORTIONS	\$ 50.00 X
TOTAL BEFORE GST		\$ 18,529.00
GST 9%		\$ 1,667.61
TOTAL (PARTS & LABOUR):		\$ 20,196.61

Adjustments / Recommendations

Our estimator have throughly inspected each and every item on the estimate against physical damage found on the vehicle and have listed the breakdown of our finding and recommendation.

Our Workshop has agreed to undertake the job at a **sum of \$ 20,000.00** for LUMP SUM with the third party insurance.

Yours Faithfully,

Marvyn Chua
Claims Estimator

Tanphn' 92495749
'up' 8/11/24 @ 320pm
Tanphn' @ khamban.
4/5 Resny after repair
25 days

repair limit \$4K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: