



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO FBU 207L

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT FORK ASSY	SERVICEABLE	\$1,080.00	\$0.00
1	FRONT RIM SHAFT	NOT NECESSARY	\$128.00	\$0.00
2	FRONT SIDE COVER (MATT)	CUT	\$220.00	\$220.00
1	HEADLAMP (LED)	CRACKED	\$1,080.00	\$1,080.00
1	SIDE MIRROR	CUT	\$180.00	\$110.00
1	HANDLE BAR	SERVICEABLE	\$265.00	\$0.00
1	SET HANDLE BAR BALANCER	CUT	\$140.00	\$60.00
1	SET HAND GRIP	NOT NECESSARY	\$90.00	\$0.00
1	SET BRAKE LEVER	CUT	\$220.00	\$90.00
1	FAIRING ASSY	CRACKED	\$950.00	\$950.00
2	FOOTSTEP PANEL	O/S CUT	\$380.00	\$160.00
2	FOOTSTEP LOWER COVER	O/S CUT	\$450.00	\$145.00
1	REAR MUDGUARD	GRAZED	\$310.00	\$110.00
1	EXHAUST ASSY	TO REPAIR SEE LABOUR	\$850.00	\$0.00
1	EXHAUST PROTECTOR	CUT	\$165.00	\$165.00
1	EXHAUST END CAP	CUT	\$135.00	\$60.00
	LESS 10.00% DISCOUNT		(\$664.30)	(\$315.00)
			\$5,978.70	\$2,835.00

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	SET REAR NUMBER PLATE (SN)	SCRATCHED	\$38.00	\$20.00
2	FORK OILS (SN)	NOT NECESSARY	\$30.00	\$0.00
2	FORK OIL SEAL (SN)	NOT NECESSARY	\$56.00	\$0.00
1	SET STEERING CONE (SN)	NOT NECESSARY	\$120.00	\$0.00
1	REAR BOX (SN)	CUT	\$480.00	\$300.00
1	REAR BOX BRACKET (SN)	BENT	\$180.00	\$100.00
			\$904.00	\$420.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO CHECK WIRING AND RESET HEADLAMP FOCUSING	NOT NECESSARY	\$80.00	\$0.00
	TO REPAIR BODY FRAME	NOT NECESSARY	\$450.00	\$0.00
	TO PROVIDE LABOUR. INCLUSIVE OF THE REPAIR OF EXHAUST ASSY		\$480.00	\$300.00
			\$1,010.00	\$300.00
GRAND TOTAL			\$7,892.70	\$3,555.00
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			\$2,800.00
Report Ref No: CS/INC24110138/Uqh3e2				

TOTAL FOR SPARE PARTS: \$ 6,882.70 \$ 3,255.00
TOTAL FOR LABOUR : \$ 1,010.00 \$ 300.00
TOTAL REPAIR COST: \$ 7,892.70 \$ 3,555.00

CKS

MARCUS CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.