

ASS. REC. BY: Taught

REF: CS3/0124110141/1943

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: _____
at Workshop m/s _____
of _____
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

N/S	O/S

(Policy Condition)
Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: 968K
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS
Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SMK3154H Yr Regn: 2019, 04
Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or _____
Make: Honda Shuttle c.c. 1496
Colour: Blue A/C: Insured / Std / NI / NA
Sp. Reading: 204995 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: GP72005215
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or _____
Brake: In order / Jammed / Leaked / Burnt or _____
Mod: NI / S/Rim / STD A/Rim or _____
Tyre Size: F: 185/60R15
R: _____
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or _____
Front: _____ Rear: _____
R/Bal. 6 mm R/Bal. C mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.A. _____ D.O.I. 7/11/24 03pm
Survey held at TM Motor
Des. of Damages: Frt / Rear / O/S / N/S / U/G / Rooftop or
Frt o/s
The U/G / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>Repair Range: 82000 - 93000, 3 days</u>

Date/Time, File Pass to? ☐ : Prell. Report
i) ☐ : Final Report

Date/Time, File Return to? _____
2) _____

Rep. Format: _____
Lump Sum / L.B.R. ()

Days Of Repair: _____
Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

Survey Fee:	
Transportation:	
\$ + RS. \$	
Photos	
Others	
TOTAL	