

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24110144/UPA3Q2

Date: 07/04/2025

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D23MFL0002582_01

Claimant Vehicle No : SMK7972L Insured Vehicle No : SLP185Z

Date of Loss: 31/10/2024 Nature of Claim: TP Claim No: MFL2024D0012992

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMK7972L

Make & Model: HYUNDAI AD AVANTE, 1.6 GLS S (A) Engine No: G4FGKU109175

Reg. Date: 25/04/2019 (Man. Year: 2019) Chassis No: KMHD841CMKU878976

Colour: Red Odometer: 136580 km

Engine Capacity: 1591 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16

Front Left Side: Continental 6 mm Rear Left Side: Kumho 6 mm

Front Right Side: Continental 6 mm Rear Right Side: Kumho 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,415.98	5,622.00	12,793.98	69.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,500.00	950.00	1,550.00	62.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,915.98	6,572.00	14,343.98	68.58
Approved Total (Overridden) (S\$)		5,200.00		
(S\$)	20,915.98	5,200.00	15,715.98	75.14
+ GST 9.00/9.00% (S\$)	1,882.44	468.00	1,414.44	75.14
Nett Amount (S\$)	22,798.42	5,668.00	17,130.42	75.14
+ Loss of Use (4.0 x S\$60.00/day) (S\$)		240.00		
+ Medical Costs (S\$)		169.72		
+ Doc/Search Fee (S\$)		31.00		
Nett Liability (S\$)		6,108.72		

INSPECTION

Date of Assignment: 11/03/2025

Date Inspected: 11/03/2025 Inspected At: Joo Hak Kee Auto Pte Ltd (HQ)
Blk 3007 Ubi Road 1, #01-406
Singapore 408701

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Mar 2025)
Parts:	143	HYUNDAI AD AVANTE 1.6 GLS S (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMK7972L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Dented	673.50 FL	*573.00 FL
2	2		*FRONT BUMPER SIDE RETAINER LH/RH	Not Necessary	33.60 FL	*- FL
3	2		*FRONT BUMPER FOG LAMP LH/RH	Not Necessary	371.40 FL	*- FL
4	2		*FRONT BUMPER FOG LAMP GARNISH LH/RH	Not Necessary	109.40 FL	*- FL
5	1		*FRONT BUMPER LOWER GARNISH	Deformed	86.40 FL	*76.00 FL
6	1		*FRONT BUMPER REINFORCEMENT	Bent	798.80 FL	*717.00 FL
7	2		*FRONT BUMPER REINFORCEMENT BRACKET LH/RH	Not Necessary	136.80 FL	*- FL
8	1		*FRONT BUMPER SPONGE	Torn	198.20 FL	*111.00 FL
9	1		*FRONT GRILLE }	Cracked	1,458.90 FL	*1,397.00 FL
10	1		*FRONT GRILLE CHROME MOULDING }		195.80 FL	*- FL
11	1		*FRONT GRILLE EMBLEM }		95.60 FL	*- FL
12	1		*FRONT GRILLE UPPER GARNISH	Not Necessary	980.10 FL	*- FL
13	1		*FRONT SUPPORT PANEL	Serviceable	587.40 FL	*- FL
14	1		*FRONT SUPPORT PANEL TOP GARNISH	Not Necessary	325.70 FL	*- FL
15	1		*FRONT HEADLAMP LH/RH	N/S Cracked / O/SNot Necessary	7,194.20 FL	*1,812.00 FL
16	2		*FRONT HEADLAMP BRACKET LH/RH	Not Necessary	97.80 FL	*- FL
17	1		*BONNET	Dented	2,544.70 FL	*2,254.00 FL
18	1		*BONNET LOCK UPPER	Not Necessary	185.90 FL	*- FL
19	1		*BONNET LOCK LOWER	Not Necessary	135.90 FL	*- FL
20	1		*A/C CONDENSER	Not Necessary	810.90 FL	*- FL
21	1		*A/C FAN ASSY	Not Necessary	980.60 FL	*- FL
22	1		*A/C SUCTION HOSE	Not Necessary	794.60 FL	*- FL
23	1		*A/C DISCHARGE HOSE	Not Necessary	187.60 FL	*- FL
24	1		*RADIATOR	Not Necessary	963.80 FL	*- FL
25	1		*RADIATOR TOP HOSE	Not Necessary	48.70 FL	*- FL
26	1		*RADIATOR BOTTOM HOSE	Not Necessary	65.90 FL	*- FL
27	1		*FRONT NUMBER PLATE WITH CASING	Bent	120.00 FS	*40.00 FS
28	1		*SET FRONT BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
29	1		*SET FRONT GRILLE CLIPS	Not Necessary	80.00 FS	*- FS
30	1		*FRONT SUPPORT PANEL TOP GARNISH CLIPS	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	20,422.20	7,010.00
- List Item Discount on L Items 10.00/20.00% (\$\$)	2,006.22	1,388.00
Total Parts (\$\$)	18,415.98	5,622.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RE-SPRAY PAINTING ON THE CHARGE BODY PARTS ,REPAIR PORTION,AND WHERE CONSISTENT TO THE ACCIDENT	New	1,000.00	400.00
2	TO PROVIDE LABOUR ,WORKMANSHIP TO CHARGE THE ABOVE DAMAGED BODYPARTS ,REPAIR ,RECONSTRUCT AND RESTRUCTURE ,BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,000.00	500.00
3	TO REMOVE ,REINSTALL ELECTRICAL WIRING HARNESS	New	100.00	20.00
4	APPLY RUST COATING CHEMICAL ON AFFECTED AND CONSISTENT AREAS AND PANELS	New	250.00	30.00
5	TO CHECK ,REMOVE AND REINSTALL A/C CON AND RADIATOR ASSY .TO VACUUM AND TOP UP A/C GAS AND REFILL RADIATOR COOLANT	New	150.00	0.00
Gross Labour Cost (\$\$)			2,500.00	950.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >