

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24110148/KPA3Q2
Date: 16/04/2025

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D24MCV0001477
Claimant Vehicle No :	SJM132R	Insured Vehicle No :	PC7897C
Date of Loss:	29/10/2024	Nature of Claim:	TP
		Claim No:	MCV2024D0013086

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJM132R	Engine No:	1NZD233930
Make & Model:	TOYOTA ALLION, 1.5 (A)	Chassis No:	NZT2603034520
Reg. Date:	18/12/2008 (Man. Year: 2008)	Odometer:	0 km
Colour:	Metallic Silver		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Firenza 9 mm	Rear Left Side:	Nexen 4 mm
Front Right Side:	Firenza 9 mm	Rear Right Side:	Nexen 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	47,152.60	26,310.50	20,842.10	44.20
Miscellaneous Items	492.00	492.00	0.00	0.00
Labour	6,900.00	5,540.00	1,360.00	19.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	54,544.60	32,342.50	22,202.10	40.70
Approved Total (Overridden) (S\$)		25,800.00		
(S\$)	54,544.60	25,800.00	28,744.60	52.70
+ GST 9.00/9.00% (S\$)	4,909.01	2,322.00	2,587.01	52.70
Nett Amount (S\$)	59,453.61	28,122.00	31,331.61	52.70
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	11/11/2024	Present Location:	Ding Auto Pte Ltd (HQ)
Date Inspected:	11/11/2024	Inspected At:	Ding Auto Pte Ltd (HQ) 176 Sin Ming Drive #04-06, Sin Ming Autocare Singapore 575721
Estimated Period of Repair:	14.0 days		

Adjuster: KENNETH KONG Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 16 Apr 2025)
Parts:	143	TOYOTA ALLION 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJM132R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER (WCP)	Missing	600.00 F	*600.00 F
2	1		*FRONT BUMPER RETAINER LHS (WCP)	Cracked	45.00 F	*45.00 F
3	1		*FRONT BUMPER RETAINER RHS (WCP)	Cracked	45.00 F	*45.00 F
4	1		*FRONT BUMPER LOWER GARNISH (WCP)	Missing	120.00 F	*120.00 F
5	1		*FRONT BUMPER LOWER COVER (WCP)	Missing	125.00 F	*125.00 F
6	1		*FRONT BUMPER LOWER GRILLE (WCP)	Missing	115.00 F	*115.00 F
7	1		*FRONT FOGLAMP LHS (WCP)	Missing	120.00 F	*120.00 F
8	1		*FRONT FOGLAMP RHS (WCP)	Missing	120.00 F	*120.00 F
9	1		*FRONT FOGLAMP COVER LHS (WCP)	Missing	45.00 F	*45.00 F
10	1		*FRONT FOGLAMP COVER RHS (WCP)	Missing	45.00 F	*45.00 F
11	1		*FRONT UPPER RAD GRILLE (WCP)	Missing	220.00 F	*220.00 F
12	1		*FRONT RAD GRILLE EMBLEM (WCP)	Missing	55.00 F	*55.00 F
13	1		*FRONT RADIATOR TOP GARNISH (WCP)	Cracked	45.00 F	*45.00 F
14	1		*FRONT HEADLAMP LHS (WCP)	Broken	350.00 F	*350.00 F
15	1		*FRONT HEADLAMP RHS (WCP)	Mtg Cracked	350.00 F	*350.00 F
16	1		*FRONT BONNET (WCP)	Bent	550.00 F	*550.00 F
17	1		*FRONT BONNET HINGE LHS (WCP)	Bent	40.00 F	*40.00 F
18	1		*FRONT BONNET HINGE RHS (WCP)	Distorted	40.00 F	*40.00 F
19	1		*FRONT BONNET INSULATOR (WCP)	*Check	150.00 F	*- F
20	1		*FRONT BONNET STAY (WCP)	*Check	40.00 F	*- F
21	1		*FRONT BONNET LOCK (WCP)	Bent	55.00 F	*55.00 F
22	1		*FRONT BONNET CABLE (WCP)	*Check	45.00 F	*45.00 F
23	1		*FRONT BONNET WEATHERSTRIP (WCP)	Torn	35.00 F	*35.00 F
24	1		*FRONT BUMPER SPONGE (WCP)	Missing	65.00 F	*65.00 F
25	1		*FRONT BUMPER REINFORCEMENT PANEL (WCP)	Bent	145.00 F	*145.00 F
26	1		*FRONT HORN LHS (WCP)	Serviceable	55.00 F	*- F
27	1		*FRONT HORN RHS (WCP)	Serviceable	55.00 F	*- F
Report was unsubmitted during this print-out.						

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	1		*FRONT SUPPORT PANEL COMPLETE (WCP)	Bent	450.00 F	*450.00 F
29	1		*FRONT CROSSMEMEBER PANEL LHS (WCP)	Bent	180.00 F	*180.00 F
30	1		*FRONT CROSSMEMEBER PANEL RHS (WCP)	Bent	180.00 F	*180.00 F
31	1		*RADIATOR ASSY (WCP)	*Check	550.00 F	*- F
32	1		*RADIATOR RESERVE TANK (WCP)	Dented	100.00 F	*100.00 F
33	1		*RADIATOR RESERVE TANK COVER (WCP)	*Check	40.00 F	*- F
34	1		*RADIATOR RESERVE TANK HOSE (WCP)	*Check	25.00 F	*- F
35	1		*RADIATOR FAN COWLING (WCP)	*Check	110.00 F	*- F
36	1		*RADIATOR FAN BLADE (WCP)	*Check	85.00 F	*- F
37	1		*RADIATOR FAN MOTOR (WCP)	*Check	190.00 F	*- F
38	1		*RADIATOR FAN COWLING TOP COVER (WCP)	*Check	75.00 F	*- F
39	1		*CONDENSER (WCP)	*Check	600.00 F	*- F
40	1		*A/C COMPRESSOR (WCP)	*Check	1,500.00 F	*- F
41	1		*A/C DISCHARGE PIPE IN (WCP)	*Check	240.00 F	*- F
42	1		*A/C DISCHARGE PIPE OUT (WCP)	*Check	320.00 F	*- F
43	1		*AIR INTAKE DUCT (WCP)	*Check	65.00 F	*- F
44	1		*AIR INTAKE HOSE (WCP)	*Check	65.00 F	*- F
45	1		*AIR CLEANER BOX (WCP)	*Check	480.00 F	*- F
46	1		*AIR FILTER (WCP)	*Check	25.00 F	*- F
47	1		*FRONT BRACE PANEL (WCP)	Bent	65.00 F	*65.00 F
48	1		*WASHER RESERVOIR (WCP)	*Check	90.00 F	*- F
49	1		*WASHER RESERVOIR FILLER NECK (WCP)	*Check	80.00 F	*- F
50	1		*WASHER RESERVOIR CAP (WCP)	*Check	30.00 F	*- F
51	1		*AIR INTAKE MANIFOLD (WCP)	*Check	450.00 F	*- F
52	1		*MAF SENSOR (WCP)	*Check	250.00 F	*- F
53	1		*AIR INTAKE MANIFOLD GASKET (WCP)	*Check	58.00 F	*- F
54	1		*FRONT CHASSIS PANEL LHS (WCP)	Repair	650.00 F	*- F
55	1		*FRONT CHASSIS PANEL RHS (WCP)	Repair	650.00 F	*- F
56	1		*FUSE BOX (WCP)	*Check	150.00 F	*- F
57	1		*FRONT FENDER LHS (WCP)	Missing	250.00 F	*250.00 F
58	1		*FRONT FENDER RHS (WCP)	Bent	250.00 F	*250.00 F
59	1		*FRONT FENDER INNERSHIELD LHS (WCP)	Torn	95.00 F	*95.00 F
60	1		*FRONT FENDER INNERSHIELD RHS (WCP)	Torn	95.00 F	*95.00 F
61	1		*FRONT FENDER INNER PANEL LHS (WCP)	Bent	500.00 F	*500.00 F
62	1		*FRONT FENDER INNER PANEL RHS (WCP)	Repair	500.00 F	*- F
63	1		*FRONT LOWER CROSSMEMBER ASSY (WCP)	*Check	480.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
64	1		*FRONT CENTER MEMBER ENGINE MOUNTING (WCP)	*Check	85.00 F	*- F
65	1		*FRONT DISC ROTOR LHS (WCP)	*Check	155.00 F	*- F
66	1		*FRONT WHEEL HUB AXLE LHS (WCP)	Bent	120.00 F	*120.00 F
67	1		*FRONT STEERING KNUCKLE LHS (WCP)	Bent	165.00 F	*165.00 F
68	1		*FRONT WHEEL BEARING LHS (WCP)	Necessary	55.00 F	*55.00 F
69	1		*FRONT DRIVE SHAFT LHS (WCP)	Bent	580.00 F	*580.00 F
70	1		*FRONT STABILIZER LINK LHS (WCP)	Bent	65.00 F	*65.00 F
71	1		*TIE ROD LHS (WCP)	*Check	100.00 F	*- F
72	1		*TIE ROD END LHS (WCP)	*Check	75.00 F	*- F
73	1		*FRONT ABSORBER LHS (WCP)	Bent	250.00 F	*250.00 F
74	1		*FRONT ABSORBER SPRING LHS (WCP)	Distorted	190.00 F	*190.00 F
75	1		*FRONT ABSORBER MOUNTING LHS (WCP)	Bent	75.00 F	*75.00 F
76	1		*FRONT LOWER ARM LHS (WCP)	Bent	160.00 F	*160.00 F
77	1		*FRONT BRAKE CALIPER LHS (WCP)	Serviceable	550.00 F	*- F
78	1		*FRONT DISC ROTOR RHS (WCP)	*Check	155.00 F	*- F
79	1		*FRONT WHEEL HUB AXLE RHS (WCP)	Bent	120.00 F	*120.00 F
80	1		*FRONT STEERING KNUCKLE RHS (WCP)	Bent	165.00 F	*165.00 F
81	1		*FRONT WHEEL BEARING RHS (WCP)	Necessary	55.00 F	*55.00 F
82	1		*FRONT DRIVE SHAFT RHS (WCP)	*Check	580.00 F	*- F
83	1		*FRONT STABILIZER LINK RHS (WCP)	Distorted	65.00 F	*65.00 F
84	1		*TIE ROD RHS (WCP)	*Check	100.00 F	*- F
85	1		*TIE ROD END RHS (WCP)	*Check	75.00 F	*- F
86	1		*FRONT ABSORBER RHS (WCP)	Bent	250.00 F	*250.00 F
87	1		*FRONT ABSORBER SPRING RHS (WCP)	*Check	190.00 F	*- F
88	1		*FRONT ABSORBER MOUNTING RHS (WCP)	Bent	75.00 F	*75.00 F
89	1		*FRONT LOWER ARM RHS (WCP)	Bent	160.00 F	*160.00 F
90	1		*FRONT BRAKE CALIPER RHS (WCP)	Serviceable	550.00 F	*- F
91	1		*FRONT RIM LHS (WCP)	Dented	450.00 F	*450.00 F
92	1		*FRONT RIM RHS (WCP)	Dented	450.00 F	*450.00 F
93	1		*FRONT TYRE LHS (80%)	Punctured	250.00 F	*200.00 FS
94	1		*FRONT TYRE RHS (80%)	Punctured	250.00 F	*200.00 FS
95	1		*FRONT WINDSCREEN (WCP)	Cracked	1,200.00 F	*1,200.00 F
96	1		*FRONT WINDSCREEN MOULDING (WCP)	Necessary	75.00 F	*75.00 F
97	1		*FRONT WINDSCREEN GARNISH CENTER (WCP)	Distorted	250.00 F	*250.00 F
98	1		*FRONT WINDSCREEN GARNISH LHS (WCP)	Distorted	75.00 F	*75.00 F
99	1		*FRONT WINDSCREEN GARNISH RHS (WCP)	*Check	75.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
100	1		*ROOF PANEL (WCP)	Repair	1,200.00 F	*- F
101	1		*FRONT A-PILLAR LHS (WCP)	Bent	320.00 F	*320.00 F
102	1		*FRONT A-PILLAR RHS (WCP)	Repair	320.00 F	*- F
103	1		*FRONT A-PILLAR TRIM LHS (WCP)	Serviceable	320.00 F	*- F
104	1		*FRONT A-PILLAR TRIM RHS (WCP)	Serviceable	320.00 F	*- F
105	1		*FRONT DOOR LHS (WCP)	Bent	650.00 F	*650.00 F
106	1		*FRONT DOOR UPPER HINGE LHS (WCP)	Bent	45.00 F	*45.00 F
107	1		*FRONT DOOR LOWER HINGE LHS (WCP)	Bent	45.00 F	*45.00 F
108	1		*FRONT DOOR INNER TRIM LHS (WCP)	Cracked	550.00 F	*550.00 F
109	1		*FRONT DOOR HANDLE LHS (WCP)	Dented	150.00 F	*150.00 F
110	1		*FRONT DOOR LOCK LHS (WCP)	Dented	200.00 F	*200.00 F
111	1		*FRONT DOOR CATCH (WCP)	Repair	25.00 F	*- F
112	1		*FRONT DOOR WEATHERSTRIP LHS (WCP)	Cut	120.00 F	*120.00 F
113	1		*FRONT WINDOW GLASS LHS (WCP)	Broken	250.00 F	*250.00 F
114	1		*FRONT WINDOW FRAME GARNISH UPPER LHS (WCP)	Dented	45.00 F	*45.00 F
115	1		*FRONT DOOR PILLAR GARNISH LHS (WCP)	Dented	145.00 F	*145.00 F
116	1		*FRONT DOOR RHS (WCP)	Bent	650.00 F	*650.00 F
117	1		*FRONT DOOR UPPER HINGE RHS (WCP)	Bent	45.00 F	*45.00 F
118	1		*FRONT DOOR LOWER HINGE RHS (WCP)	Bent	45.00 F	*- F
119	1		*FRONT DOOR INNER TRIM RHS (WCP)	*Check	550.00 F	*- F
120	1		*FRONT DOOR HANDLE RHS (WCP)	Serviceable	155.00 F	*- F
121	1		*FRONT DOOR LOCK RHS (WCP)	Dented	190.00 F	*190.00 F
122	1		*FRONT DOOR CATCH RHS (WCP)	Repair	25.00 F	*- F
123	1		*FRONT DOOR WEATHERSTRIP RHS (WCP)	*Check	120.00 F	*- F
124	1		*FRONT WINDOW GLASS RHS (WCP)	Serviceable	280.00 F	*- F
125	1		*FRONT WINDOW FRAME WEATHERSTRIP GARNISH RHS (WCP)	*Check	55.00 F	*- F
126	1		*FRONT WINDOW FRAME UPPER GARNISH RHS (WCP)	*Check	55.00 F	*- F
127	1		*FRONT DOOR PILLAR GARNISH RHS (WCP)	*Check	155.00 F	*- F
128	1		*B-PILLAR PANEL LHS (WCP)	*Check	420.00 F	*- F
129	1		*C-PILLAR PANEL LHS (WCP)	*Check	350.00 F	*- F
130	1		*B-PILLAR PANEL RHS (WCP)	Repair	420.00 F	*- F
131	1		*C-PILLAR PANEL RHS (WCP)	Repair	350.00 F	*- F
132	1		*REAR DOOR LHS (WCP)	Bent	650.00 F	*650.00 F
133	1		*REAR DOOR UPPER HINGE LHS (WCP)	Bent	45.00 F	*45.00 F
134	1		*REAR DOOR LOWER HINGE LHS (WCP)	Bent	45.00 F	*45.00 F
135	1		*REAR DOOR HANDLE LHS (WCP)	Dented	45.00 F	*45.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
136	1		*REAR DOOR INNER TRIM LHS (WCP)	*Check	480.00 F	*- F
137	1		*REAR DOOR WEATHERSTRIP LHS (WCP)	*Check	120.00 F	*- F
138	1		*REAR DOOR GLASS LHS (WCP)	Serviceable	250.00 F	*- F
139	1		*REAR DOOR LOCK LHS (WCP)	Repair	190.00 F	*- F
140	1		*REAR DOOR CATCH LHS (WCP)	Repair	25.00 F	*- F
141	1		*REAR WINDOW FRAME WEATHERSTRIP GARNISH LHS (WCP)	Serviceable	122.00 F	*- F
142	1		*REAR DOOR PILLAR GARNISH LHS (WCP)	Serviceable	48.00 F	*- F
143	1		*REAR DOOR FRAME UPPER GARNISH (WCP)	Serviceable	48.00 F	*- F
144	1		*FRONT DOOR WINDOW REGULATOR LHS (WCP)	Bent	120.00 F	*120.00 F
145	1		*FRONT DOOR WINDOW REGULATOR RHS (WCP)	Bent	120.00 F	*120.00 F
146	1		*REAR DOOR WINDOW REGULATOR LHS (WCP)	Bent	120.00 F	*120.00 F
147	1		*FRONT DOOR WINDOW REGULATOR MOTOR LHS (WCP)	Jammed	250.00 F	*250.00 F
148	1		*FRONT DOOR WINDOW REGULATOR MOTOR RHS (WCP)	Jammed	250.00 F	*250.00 F
149	1		*REAR DOOR WINDOW REGULATOR MOTOR LHS (WCP)	Jammed	250.00 F	*250.00 F
150	1		*REAR FENDER LHS (WCP)	Bent	650.00 F	*650.00 F
151	1		*REAR FENDER PANEL LHS (WCP)	Bent	330.00 F	*330.00 F
152	1		*REAR FENDER INNERSHIELD LHS (WCP)	Serviceable	45.00 F	*- F
153	1		*PETROL TANK COVER (WCP)	Repair	75.00 F	*- F
154	1		*REAR RIM LHS (WCP)	*Check	450.00 F	*- F
155	1		*REAR RIM RHS (WCP)	*Check	450.00 F	*- F
156	1		*REAR TYRE LHS (WCP)	*Check	250.00 F	*- F
157	1		*REAR TYRE RHS (WCP)	*Check	250.00 F	*- F
158	1		*REAR BUMPER (WCP)	Buckled	350.00 F	*350.00 F
159	1		*REAR TAIL LAMP LHS (WCP)	Cracked	150.00 F	*150.00 F
160	1		*REAR TAIL LAMP RHS (WCP)	Cracked	150.00 F	*150.00 F
161	1		*FRONT SIDE MIRROR LHS (WCP)	Broken	420.00 F	*420.00 F
162	1		*FRONT SIDE MIRROR RHS (WCP)	Buckled	420.00 F	*420.00 F
163	1		*FRONT SIDE MIRROR INDICATOR LAMP LHS (WCP)	Missing	55.00 F	*55.00 F
164	1		*FRONT SIDE MIRROR INDICATOR LAMP RHS (WCP)	Cracked	55.00 F	*55.00 F
165	1		*DASHBOARD ASSY (WCP)	Torn	550.00 F	*550.00 F
166	1		*AIRBAG LHS (WCP)	Burst	1,250.00 F	*1,250.00 F
167	1		*AIRBAG RHS (WCP)	Burst	1,350.00 F	*1,350.00 F
168	1		*AIRBAG ECU (WCP)	Necessary	550.00 F	*550.00 F
169	1		*STEERING SPRING COIL (WCP)	Necessary	330.00 F	*330.00 F
170	1		*SEAT BELT ASSY LHS (WCP)	Jammed	480.00 F	*480.00 F
171	1		*SEAT BELT ASSY RHS (WCP)	Jammed	480.00 F	*480.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
172	1		*AIRCONT VENT TRIM LHS (WCP)	Distorted	95.00 F	*95.00 F
173	1		*AIRCONT VENT TRIM RHS (WCP)	*Check	95.00 F	*- F
F=Franchise part. S=SpcNett.						
					Sub Total (\$\$)	42,866.00
					+ Margin on L,N Items 10.00/10.00% (\$\$)	2,355.50
					Total Parts (\$\$)	26,310.50

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	BUMPER, GRILLE, INNERSHIELD, SEAL AND GARNISH/PANEL - CLIPS (Necessary)	150.00	150.00
2	1	ERP BRACKET STICKER (Necessary)	10.00	10.00
3	1	FRONT NUMBER PLATE AND FRAME (Missing)	50.00	50.00
4	1	GLUE SEALANT (Necessary)	35.00	35.00
5	1	PRIMER (Necessary)	35.00	35.00
6	1	REFILL - AIRCON GAS (Necessary)	60.00	60.00
7	1	REFILL - COOLANT (Necessary)	60.00	60.00
8	1	WHEEL ALIGNMENT (Necessary)	80.00	80.00
9	1	OD/TP Case (Insurer)	12.00	12.00
Sub Total (\$\$)			492.00	492.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	BODY REPAIR, PANEL BEATING & STRAIGHTEN/ALIGN - ACCIDENT AREA	New	2,200.00	2,200.00
2	SPRAY PAINTING - FRONT BUMPER, FRONT BONNET, FRONT FENDER LHS & RHS, FRONT FOOR LHS & RHS, REAR DOOR LHS, REAR FENDER AND REAR BUMPER	New	2,000.00	2,000.00
3	REMOVE AND REFIT - FRONT UNDERCARRIAGE COMPONENTS	New	450.00	400.00
4	REMOVE AND REFIT - FRONT DOOR AND REAR DOOR COMPONENTS (*Check)	New	450.00	0.00
5	REMOVE AND INSTALL - FRONT DOOR WINDOW GLASS	New	200.00	120.00
6	ALIGN HEADLAMP/SIDE MIRROR/DOOR REGULATOR AND CHECK AND TEST WIRING	New	250.00	0.00
7	REMOVE AND REFIT CONDENSER AND RADIATOR COMPONENTS	New	250.00	100.00
8	REMOVE AND REFIT - DASHBOARD COMPONENTS	New	250.00	250.00
9	REMOVE AND REFIT - SEAT BELT (X2) COMPONENTS	New	250.00	150.00
10	REMOVE AND REFIT - FRONT WINDSCREEN GLASS AND MOULDING	New	150.00	120.00
11	AIRBAG ECU AND SENSOR - DIANOSTIC AND RE-PROGRAMMING	New	450.00	200.00
Gross Labour Cost (\$\$)			6,900.00	5,540.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >