

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24110149/EUA3Q2  
Date: 17/01/2025

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D23MFL0002571\_01  
Claimant Vehicle No : GBG9158J Insured Vehicle No : SLG5833B  
Date of Loss: 21/10/2024 Nature of Claim: TP Claim No: MFL2024D0012471

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBG9158J  
Make & Model: TOYOTA HIACE, 3.0 D TURBO 5DR MT (M) Engine No: 1KD2754035  
Reg. Date: 29/11/2017 (Man. Year: 2017) Chassis No: JTFHT02P400234492  
Colour: Silver Odometer: 196740 km  
Engine Capacity: 2982 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15C Rear Tyre Size: 195 R15C  
Front Left Side: Michelin 5 mm Rear Left Side: Michelin 5 mm  
Front Right Side: Michelin 5 mm Rear Right Side: Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,815.57	4,026.15	5,789.42	58.98
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,180.00	1,820.00	2,360.00	56.46
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,995.57	5,846.15	8,149.42	58.23
Approved Total (Overridden) (S\$)		4,700.00		
Nett Amount (S\$)	13,995.57	4,700.00	9,295.57	66.42
+ Car Rental (10.0 x S\$100.00/day) (S\$)		1,000.00		
(S\$)		5,700.00		
Liabe Amount (50.00%) (S\$)		2,850.00		
+ Doc/Search Fee (S\$)		58.25		
Nett Liability (S\$)		2,908.25		

INSPECTION

Date of Assignment: 11/11/2024  
Date Inspected: 11/11/2024 Inspected At: AUTO BULLOX PTE LTD - ubi (HQ)  
53 UBI AVENUE 1 #01-25 PAYA UBI INDUSTRIAL PARK  
Singapore 408934  
Estimated Period of Repair: 8.0 days

Adjuster: CHEN TSUE YEE

Manager: NA MENG YAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 23 Dec 2024)	
Parts:	N/A	TOYOTA HIACE 3.0 D TURBO 5DR MT (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBG9158J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Broken	986.70 FL	*645.00 FL
2	1		*REAR BUMPER SIDE RETAINER N/S	Broken	42.00 FL	*42.00 FL
3	1		*REAR BUMPER BRACKET N/S	Not Necessary	38.00 FL	*- FL
4	1		*SET REAR BUMPER CLIPS	Necessary	48.00 FL	*30.00 FL
5	1		*TAILLAMP N/S	Cut	496.70 FL	*385.00 FL
6	1		*REAR SIDE PANEL N/S	Dented	1,708.50 FL	*1,708.50 FL
7	1		*REAR SIDE PANEL MUD FLAP N/S	Not Necessary	186.50 FL	*- FL
8	1		*REAR RIM N/S	Not Necessary	480.60 FL	*- FL
9	1		*REAR SUSPENSION N/S	Not Necessary	320.50 FL	*- FL
10	1		*REAR WHEEL BEARING N/S	Not Necessary	296.80 FL	*- FL
11	1		*REAR AXLE	Not Necessary	1,796.80 FL	*- FL
12	1		*SLIDING DOOR N/S	Dented	1,468.70 FL	*1,468.70 FL
13	1		*SET SLIDING DOOR RUBBER N/S	Not Necessary	284.60 FL	*- FL
14	1		*SLIDING DOOR BOTTOM LATCH N/S	Not Necessary	296.70 FL	*- FL
15	1		*SLIDING DOOR TOP LATCH N/S	Not Necessary	198.70 FL	*- FL
16	1		*SET SLIDING DOOR CENTER LATCH N/S	Not Necessary	175.60 FL	*- FL
17	1		*SLIDING DOOR INNER LOCK N/S	Not Necessary	495.60 FL	*- FL
18	1		*SLIDING DOOR RAIL N/S	Not Necessary	255.60 FL	*- FL
19	1		*ROCKER PANEL N/S	Not Necessary	1,068.50 FL	*- FL
20	1		*TAILLAMP LOWER COVER LH	Broken	49.00 FL	*49.00 FL
21	1		*REAR SIDE PANEL SEALANT	Necessary	55.00 FS	*30.00 FS
22	1		*REAR SIDE PANEL ADVERTISEMENT STICKER	Necessary	200.00 FS	*200.00 FS
23	1		*ROCKER PANEL SEALANT	Not Necessary	55.00 FS	*- FS
24	1		*SLIDING DOOR PANEL SEALANT	Necessary	55.00 FS	*30.00 FS
25	1		*SLIDING DOOR PANEL ADVERTISEMENT STICKER	Necessary	500.00 FS	*400.00 FS
26	1		*WHEEL CAP (REAR LH)	Cut	480.00 FS	*120.00 FS
27	1		*REAR TYRE N/S	Not Necessary	450.00 FS	*- FS
Sub Total (\$\$)						12,489.10 5,108.20
- List Item Discount on L Items 25.00/25.00% (\$\$)						2,673.53 1,082.05
Total Parts (\$\$)						9,815.57 4,026.15

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR TO REMOVE ,RENEW & ALIGN AFFECTED ACCIDENT DAMAGED AREA	New	1,500.00	800.00
2	LABOUR TO SPRAY PAINTING ON AFFECTED DAMAGE AREA	New	1,500.00	800.00
3	TO CONDUCT RUST PROOFING ON AFFECTED PANELS	New	100.00	30.00
4	TO REMOVE RENEW & INSTALL SLIDING DOOR COMPONENTS TO FACILITATE REPAIRS	New	150.00	50.00
5	TO CONDUCT ALL WHEEL ALIGNMENT	New	150.00	80.00
6	TO REMOVE ,RENEW & INSTALL REAR UNDERCARRIAGE COMPONENTS TO FACILITATE REPAIRS	New	300.00	0.00
7	TO REMOVE & INSTALL REVERSE SENSOR AND TO ALIGN THE SAME TO SPECIFICATION	New	150.00	30.00
8	TO REMOVE & INSTALLED ALL ELECTRICAL WIRING TO FACILITATE REPAIRS	New	80.00	30.00
9	TO CONDUCT WATER SEEPAGE TEST	New	250.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>4,180.00</b>	<b>1,820.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >