



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO VDH 4259

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
2	FRONT FORK TUBE ASSY	BENT/TWISTED	\$640.00	\$520.00
1	FORK UNDER BRACKET	BENT	\$185.00	\$160.00
1	HANDLE-BAR	NOT NECESSARY	\$105.00	\$0.00
1	SET HAND GRIP	NOT NECESSARY	\$55.00	\$0.00
1	HANDLE BAR ENDS	NOT NECESSARY	\$78.00	\$0.00
2	SIDE MIRRORS	NOT NECESSARY	\$110.00	\$0.00
1	FRONT PILOT LIGHT	NOT NECESSARY	\$228.00	\$0.00
2	FRONT SIGNALS	NOT NECESSARY	\$140.00	\$0.00
1	FRONT SIGNAL LOWER GARNISH	CRACKED	\$95.00	\$95.00
1	FRONT FENDER	CRACKED	\$180.00	\$110.00
1	SET FAIRING ASSY	CRACKED	\$625.00	\$528.00
1	FRONT RIM	WARPED	\$528.00	\$380.00
1	EXHAUST PROTECTOR	NOT NECESSARY	\$60.00	\$0.00
1	EXHAUST PROTECTOR END CAP	NOT NECESSARY	\$45.00	\$0.00
1	REAR FENDER - 1	DISTORTED	\$95.00	\$95.00
1	REAR FENDER - 2	DISTORTED	\$68.00	\$68.00
1	REAR FENDER BRACKET	TWISTED	\$106.00	\$106.00
1	REAR SIGNAL	NOT NECESSARY	\$180.00	\$0.00
1	REAR NUMBER PLATE LAMP	BROKEN	\$98.00	\$98.00
1	REAR RIM	BENT	\$350.00	\$350.00
1	REAR RIM SHAFT	SERVICEABLE	\$98.00	\$0.00
1	SWING ARM	BENT/TWISTED	\$380.00	\$380.00
1	SWING ARM BUSH	NECESSARY	\$180.00	\$100.00
1	SWING ARM SHAFT	SERVICEABLE	\$98.00	\$0.00
	<b>LESS 10.00% DISCOUNT</b>		(\$472.70)	(\$299.00)
			<b>\$4,254.30</b>	<b>\$2,691.00</b>

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	SET REAR NUMBER PLATE (SN)	BENT	\$38.00	\$20.00
2	FORK OILS (SN)	NOT NECESSARY	\$30.00	\$0.00



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
2	FORK OIL SEALS (SN)	NOT NECESSARY	\$56.00	\$0.00
1	SET STEERING CONE (SN)	NECESSARY	\$95.00	\$60.00
1	SET STICKER (SN)	NECESSARY	\$95.00	\$80.00
			\$314.00	\$160.00
Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO CHECK WIRING AND RESET HEADLAMP FOCUSING	NOT NECESSARY	\$80.00	\$0.00
	TO REALIGN BODY FRAME	NOT NECESSARY	\$420.00	\$0.00
	TO PROVIDE LABOUR		\$480.00	\$300.00
			\$980.00	\$300.00
<b>GRAND TOTAL</b>			<b>\$5,548.30</b>	<b>\$3,151.00</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)</b>			<b>\$1,800.00</b>
Report Ref No: CS/INC24110152/Uvh3m4				

TOTAL FOR SPARE PARTS: \$ 4,568.30 \$ 2,851.00  
TOTAL FOR LABOUR : \$ 980.00 \$ 300.00  
TOTAL REPAIR COST: \$ 5,548.30 \$ 3,151.00

**CKS**

MARCUS CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of repositibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.