

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG24110154/UDP3E2
Date: 22/11/2024REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1001209627
Claimant Vehicle No :	SMF3950C	Insured Vehicle No :	SKZ1541G
Date of Loss:	29/10/2024	Nature of Claim:	TP
		Claim No:	378541

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMF3950C	Engine No:	G4FGJU277151
Make & Model:	HYUNDAI ELANTRA, 1.6 AD GLS (AMS) (A)	Chassis No:	KMHD841CMJU767468
Reg. Date:	08/11/2018 (Man. Year: 2018)	Odometer:	326339 km
Colour:	White		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Triangle 6 mm	Rear Left Side:	Triangle 6 mm
Front Right Side:	Triangle 6 mm	Rear Right Side:	Triangle 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,549.12	1,172.08	4,377.04	78.88
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,290.00	1,330.00	960.00	41.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	7,839.12	2,502.08	5,337.04	68.08
Approved Total (Overridden) (\$\$)		2,000.00		
Nett Amount (\$\$)	7,839.12	2,000.00	5,839.12	74.49

INSPECTION

Date of Assignment:	07/11/2024	
Date Inspected:	07/11/2024	Inspected At: T K Lee Automotive Pte Ltd (HQ) NO. 1 KAKI BUKIT AVE 6 #02-47 AUTOBAY Singapore 417883
Estimated Period of Repair:	4.0 days	

Adjuster: MARCUS CHUA**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 Nov 2024)
Parts:	143	HYUNDAI ELANTRA 1.6 AD GLS (AMS) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMF3950C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Repair	1,783.00 FL	*- FL
2	1		*REAR BOOT LOGO	Serviceable	58.80 FL	*- FL
3	1		*REAR BOOT EMBLEM ELANTRA	Necessary	68.80 FL	*68.80 FL
4	1		*REAR BOOT EMBLEM S	Necessary	62.40 FL	*62.40 FL
5	1		*REAR BOOT INNER LOCK	Serviceable	230.60 FL	*- FL
6	2		*REAR BOOT LAMPS - R/L	Not Necessary	883.00 FL	*- FL
7	1		*REAR BOOT W/STRIP	Serviceable	241.20 FL	*- FL
8	1		*REAR BUMPER	Dented / Torn	671.60 FL	*494.20 FL
9	1		*REAR BUMPER DIFUSSER	Deformed	361.60 FL	*173.20 FL
10	2		*REAR BUMPER REFLECTOR - R/L	Not Necessary	220.40 FL	*- FL
11	1		*REAR BUMPER REINFORCEMENT	Distorted	481.50 FL	*313.50 FL
12	1		*REAR BUMPER SIDE RETAINERS - R/L	Necessary	65.50 FL	*65.50 FL
13	1		*REAR END PANEL	Repair	520.60 FL	*- FL
14	1		*REAR END PANEL GARNISH	Not Necessary	161.20 FL	*- FL
15	1		*REAR TAILLAMP - LH	Not Necessary	651.20 FL	*- FL
16	1		*SET REAR BOOT INNER TRIM CLIP	Not Necessary	50.00 FS	*- FS
17	1		*SET REAR BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
18	1		*SET REAR REVERSE SENSOR	Malfunction	280.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,841.40	1,407.60
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,292.28	235.52
Total Parts (\$\$)	5,549.12	1,172.08

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK REAR ELECTRICAL WIRING	New	50.00	20.00
2	TO REMOVE & REFIX REAR INTERIOR TRIMS TO ASSIST REPAIR	New	120.00	0.00
3	TO REMOVE AND REPLACE REVERSE SENSORS	New	60.00	30.00
4	TO TUFF KOTE	New	80.00	0.00
5	TO PUTTY, SPRAY PAINT & POLISH AFFECTED PARTS	New	1,080.00	700.00
6	TO PANEL BEAT, CUT, WELD, REMOVE & REPLACE DAMAGED PARTS	New	900.00	580.00
Gross Labour Cost (\$)			2,290.00	1,330.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >