



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBU 40A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	RH CYLINDER HEAD COVER AGATE GREY (SN)	BENT / CUT	378.68	378.68
3	SCREW WITH BUSH (SN)	NECESSARY	83.70	83.70
1	SET OF GASKETS (SN)	NECESSARY	107.12	107.12
1	MODEL LETTERING (SN)	NECESSARY	43.20	43.20
1	RH CASE W/O PAINTED PRIMED (SN)	CRUSHED	583.17	583.17
1	RH TRIM CASE COVER PRIMED (SN)	CUT	269.54	269.54
2	BODY SCREW W/O COLLAR M5X20 (SN)	NECESSARY	16.70	16.70
1	ADDITIONAL HEADLIGHT ADAPTER (SN)	CUT	40.55	40.55
1	LED ADDITIONAL HEADLIGHT NANO (SN)	NECESSARY	205.68	205.68
			1,728.34	1,728.34
	<u>LABOUR</u>			
	DAMAGE ASSESSMENT.	NOT NECESSARY	132.00	-
	ACCIDENT DAMAGE REPAIR.		1,300.00	975.00
	SPRAY PAINTING TRIM CASE LID, RIGHT.		264.00	264.00
			1,696.00	1,239.00
	GRAND TOTAL		3,424.34	2,967.34
	RECOMMENDED COST OF REPAIRS			2,967.34

Report Ref No. CS/FCI24110155/Evp3e2(N)

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.