



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDINGS SINGAPORE 048581 ATTN: HARMINDER		Ref: CS/FCI24110155/Evp3e2(N) Date: 06/02/2025 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHB 4871X	Veh. Inspected	FBU 40A
Policy No.		Coverage (\$)	0.00
Claim No.	D24009727MFCT	Excess (\$)	0.00
Assign From	HARMINDER	Assign Date	07/11/2024
2. Vehicle Particulars & Condition			
Make & Model	B.M.W. R1250 RT	c.c	1254
Engine No.	HIDDEN	Year of Reg.	2022
Chassis No.	WB10L0108N6F75392	Colour	WHITE
Odometer	38652 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	120/70Z R17	MICHELIN	5 mm
L/H Front Tyre			mm
R/H Rear Tyre	180/55Z R17	MICHELIN	5 mm
L/H Rear Tyre			mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	03/11/2024	Inspection Date	07/11/2024
Survey held at	1 UBI ROAD 4 (S) 408607		
Repairer	PERFORMANCE MOTORS LTD		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	