

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/MSG24110156/UQP3E2**Date:** 07/01/2025REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1002378858
<b>Claimant Vehicle No :</b>	SNM5767D	<b>Insured Vehicle No :</b>	SKW7681L
Date of Loss:	31/10/2024	Nature of Claim:	TP
		Claim No:	378760

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SNM5767D</b>		
Make & Model:	TOYOTA COROLLA ALTIS, 1.8 HYBRID ELEGANCE (A)	Engine No:	2ZRZ054531
Reg. Date:	30/09/2023 (Man. Year: 2023)	Chassis No:	MR2BZ3BE000012702
Colour:	Grey	Odometer:	77034 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40 R17	Rear Tyre Size:	225/40 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,691.60	921.67	2,769.93	75.03
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,200.00	1,150.00	2,050.00	64.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>6,891.60</b>	<b>2,071.67</b>	<b>4,819.93</b>	<b>69.94</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>1,650.00</b>		
<b>Nett Amount (\$\$)</b>	<b>6,891.60</b>	<b>1,650.00</b>	<b>5,241.60</b>	<b>76.06</b>

INSPECTION

Date of Assignment:	08/11/2024	
Date Inspected:	08/11/2024	Inspected At: Mirai Auto Performance Pte Ltd (HQ) 53 UBI AVE 1, #01-33 PAYA UBI INDUSTRIAL PARK Singapore 408934
Estimated Period of Repair:	3.0 days	

**Adjuster:** MARCUS CHUA**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Nov 2024)
Parts:	143	TOYOTA COROLLA ALTIS 1.8 HYBRID ELEGANCE (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNM5767D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cut / Torn	821.00 FL	*712.20 FL
2	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	512.00 FL	*- FL
3	1		*FRONT BUMPER SPONGE	Torn	211.00 FL	*165.30 FL
4	1		*FRONT BUMPER UNDER COVER	Not Necessary	322.00 FL	*- FL
5	1		*FRONT BUMPER SIDE RETAINER	O/S Cracked	224.00 FL	*112.00 FL
6	1		*FRONT BUMPER LOWER CORNER GARNISH	Not Necessary	389.00 FL	*- FL
7	2		*FRONT BUMPER FOG LAMP	Not Necessary	714.00 FL	*- FL
8	2		*FRONT BUMPER FOG LAMP COVER	Not Necessary	260.00 FL	*- FL
9	1		*SET FRONT BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
10	8		*FRONT BUMPER LOWER GRILLE CLIP	Not Necessary	52.00 FS	*- FS
11	6		*FRONT BUMPER LOWER COVER GARNISH CLIP RH	Not Necessary	39.00 FS	*- FS
12	6		*FRONT BUMPER LOWER COVER GARNISH CLIP LH	Not Necessary	39.00 FS	*- FS
13	1		*FRONT SUPPORT SEALANT	Not Necessary	80.00 FS	*- FS
14	1		*FRONT FENDER HYBRID EMBLEM	Necessary	60.00 FS	*60.00 FS
15	1		*FRONT BUMPER LOWER GARNISH O/S	Scratched	212.00 FL	*119.40 FL
16	1		*FRONT BUMPER ENFORCEMENT	Not Necessary	512.00 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	4,527.00	1,198.90
- List Item Discount on L Items 20.00/25.00% (S\$)	835.40	277.23
Total Parts (S\$)	3,691.60	921.67

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK FRONT ELECTRICAL WIRING	New	200.00	20.00
2	PANEL BEAT, REMOVING AND REPLACING PARTS	New	1,600.00	450.00
3	SPRAY PAINT ON AFFECTED AREAS	New	1,400.00	680.00
<b>Gross Labour Cost (\$)</b>			<b>3,200.00</b>	<b>1,150.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >